

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20008401/DDS3Q2**Date:** 03/11/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800020116
Claimant
Vehicle No : YM3777H **Insured Vehicle No :** SLW7827Y
Date of Loss: 11/08/2020 Nature of Claim: TP Claim No: 5707734062SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YM3777H**
Make & Model: MITSUBISHI FK617MSJRDEC, 7.5 D (M) Engine No: 6D16986833
Reg. Date: 26/06/2006 (Man. Year: 2006) Chassis No: FK617MB10198
Colour: White Odometer: 239884 km
Engine Capacity: 7545 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 8.25 R16 Rear Tyre Size: 8.25 R16 (D)
Front Left Side: Lionstone 5 mm Rear Left Side: Lionstone 5/5 mm
Front Right Side: Lionstone 5 mm Rear Right Side: Lionstone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,383.85	4,332.85	7,051.00	61.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	1,210.00	2,370.00	66.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,963.85	5,542.85	9,421.00	62.96
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	14,963.85	4,400.00	10,563.85	70.60
+ GST 7.00/7.00% (S\$)	1,047.47	308.00	739.47	70.60
Nett Amount (S\$)	16,011.32	4,708.00	11,303.32	70.60
+ Car Rental (8.0 x S\$250.00/day) (S\$)		2,000.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,744.45		

INSPECTION

Date of Assignment: 14/08/2020
Date Inspected: 14/08/2020 Inspected At: Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934
Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP LH	Mtg Broken	424.18 FL	*424.18 FL
2	1		*REAR TAILLAMP RH	Mtg Broken	424.18 FL	*424.18 FL
3	1		*REAR TAILLAMP PANEL LH	Bent	296.33 FL	*296.33 FL
4	1		*REAR TAILLAMP PANEL RH	Bent	296.33 FL	*296.33 FL
5	1		*REAR NUMBER PLATE LAMP	Serviceable	87.30 FL	*- FL
6	1		*REAR NUMBER PLATE GARNISH	Bent	109.39 FL	*109.39 FL
7	1		*REAR STOPPER LH	Not Necessary	89.29 FL	*- FL
8	1		*REAR STOPPER RH	Not Necessary	89.29 FL	*- FL
9	1		*REAR RH WOODEN CROSS MEMBER	Repair	1,500.00 FS	*- FS
10	1		*REAR LOWER MEMBER	Not Necessary	1,250.00 FS	*- FS
11	1		*REAR MEMBER -UPPER (WOODEN)		550.00 FS	*550.00 FS
12	1		*STEP PANEL	Bent	1,400.00 FS	*1,400.00 FS
13	2		*STEP PANEL BRACKET	Bent	600.00 FS	*600.00 FS
14	1		*U-BRACKET RH	Bent	450.00 FS	*450.00 FS
15	1		*TAILGATE LH	Not Necessary	1,600.00 FS	*- FS
16	1		*TAILGATE RH	Not Necessary	1,600.00 FS	*- FS
17	6		*TAILGATE HINGE	Not Necessary	180.00 FS	*- FS
18	1		*TAILGATE RODE LH	Not Necessary	130.00 FS	*- FS
19	1		*TAILGATE RODE RH	Not Necessary	130.00 FS	*- FS
20	1		*TAILGATE LOCK FLIP LH	Not Necessary	150.00 FS	*- FS
21	1		*TAILGATE LOCK FLIP RH	Not Necessary	150.00 FS	*- FS
22	1		*60KM/H STICKER	Not Necessary	70.00 FS	*- FS
23	1		*REAR NUMBER PLATE	Bent	80.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,656.29	4,565.41
- List Item Discount on L Items 15.00/15.00% (\$\$)	272.44	232.56
Total Parts (\$\$)	11,383.85	4,332.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	TRANSFER PARTS ,ATTACHMENT FROM OLD LH TAILGATE TO NEW	New	200.00	0.00
3	TRANSFER PARTS ,ATTACHMENT FROM OLD RH TAILGATE TO NEW	New	200.00	0.00
4	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	800.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	300.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	80.00
Gross Labour Cost (\$\$)			3,580.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >