

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20008403/QDS3Q2

**Date:** 15/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SHF280G **Insured Vehicle No :** SJE7979K

**Date of Loss:** 11/08/2020 **Nature of Claim:** TP **Claim No:** 6420201107SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHF280G</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2F47212
Reg. Date:	26/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU203089471
Colour:	Maroon	Odometer:	16083 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,516.10	400.88	1,115.22	73.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,176.00	400.00	776.00	65.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>2,692.10</b>	<b>800.88</b>	<b>1,891.22</b>	<b>70.25</b>
<b>+ Loss of Use (1.8 x S\$50.00/day) (\$\$)</b>		87.50		
<b>+ Car Rental (1.8 x S\$116.63/day) (\$\$)</b>		204.10		
<b>+ Doc/Search Fee (\$\$)</b>		7.00		
<b>Nett Liability (\$\$)</b>		<b>1,099.48</b>		

### INSPECTION

Date of Assignment: 11/08/2020

Date Inspected: 11/08/2020 Inspected At: SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 2.0 days

**Adjuster:** OI SUN PIN

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GUARD ,RR BUMPER LOWER (DISC 25%)	Scratched	374.50 F	*280.88 F
2	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
3	1		*CPVER ,RR BUMPER ASSY	Repair	485.60 F	*- F
4	2		*PAD ,RR BUMPER ,RH & LH,1	Serviceable	4.00 F	*- F
5	2		*PAD ,RR BUMPER ,RH & LH,2	Serviceable	4.00 F	*- F
6	2		*PAD ,RR BUMPER ,RH & LH,3	Serviceable	4.00 F	*- F
7	2		*SEAL ,RR BUMPER ARM ,RH & LH	Serviceable	11.30 F	*- F
8	1		*REAR BUMPER REINFORCEMENT	Serviceable	332.70 F	*- F
9	1		*SET REVERSE SENSOR	Serviceable	180.00 F	*- F

F=Franchise part.

**Total Parts (S\$)**      **1,516.10**      **400.88**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODY WORK	New	338.00	200.00
2	SPRAY PAINT	New	558.00	200.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO WASH AND VACUUM	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,176.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >