

# INVOICE

TO: MUHAMMAD SHAZLIZAN BIN MOHD SALLEH

Invoice No.:

0620/KK570

C/O: KIM KEAT MOTOR CO

Date:

20-Jul-2020

BLK 10, ANG MO KIO IND PK 2A #05-34 AMK AUTOPOINT

SINGAPORE 568047

## **PARTICULARS**

Vehicle Registration No.:

FBC 8945 G

Date of Loss:

19-May-2020

Date of Assessment:

08-Jun-2020

**SERVICES** 

1. Assessment with report Photographs -Including films, developing, storage and Transport.

\$400.00

**FEES** 

**TOTAL** 

\$400.00

# SINGAPORE DOLLARS FOUR HUNDRED ONLY

We would appreciate your cheque crossed and made payable to: "AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

## **AEON AUTO CONSULTANTS LLP**



50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

# **AUTOMOBILE ASSESSMENT REPORT**

TO:

MUHAMMAD SHAZLIZAN BIN MOHD SALLEH

Our Reference:

0620/KK570

C/O: KIM KEAT MOTOR CO

BLK 10, ANG MO KIO IND PK 2A

#05-34 AMK AUTOPOINT SINGAPORE 568047

Date:

20-Jul-2020

ASSESSMENT OF VEHICLE NO. FBC 8945 G

DATE OF LOSS:

19-May-2020

We have carried out a physical assessment at **KIM KEAT MOTOR CO**, Blk 10, Ang Mo Kio Ind PK 2A #05-34 AMK Autopoint, Singapore 568047, according to your instruction

08-Jun-2020

and are pleased to submit our report herewith.

## 1. VEHICLE PARTICULARS

Registration No.:

FBC 8945 G

Make & Model:

HONDA CB4008J M

Year of Registration:

2008

Engine Capacity:

399

Chassis No.:

NC421002213

Engine No.:

NC42E1002218

Colour:

SILVER

#### 2. VEHICLE CONDITION

B ) Paint:

g GOOD

Steering:

SERVICEABLE

Foot Brake:

**SERVICEABLE** 

Parking Brake:

SERVICEABLE

Modification:

NIL

## 3. TYRE PARTICULARS & CONDITION

Front

Make/Size/Thread:

MITAS 120/60 R17 - 70%

Rear

Make/Size/Thread:

MITAS 160/60 R17 - 70%

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

## 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

#### 5. REMARKS

Market Value:

Na

Salvage Value:

Na

Repair Limit:

Na

Estimated Amount:

\$9,755.04

Adjusted Amount:


\$7,977.00

Ly Sum:

\$5,800.00

Esmnated Repair Days:

8 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 days from the date hereof, this report shall be treated as correct.

## Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

# ASSESSMENT REPORT FOR VEHICLE NO. FBC 8945 G

# PARTS (LIST ITEMS)

		a tu	Workshop's	·	
Qty	Description	Condition	Estimate	Assessment	
1	FRONT HEAD LAMP ASSY SVC	Reuse	380.00	5	
1	FRONT HEAD LAMP STAY	Repair	120,00	*	
1	FRONT HANDLÉ BAR 🗸	Bent	260.00	120 260.00	
1 <del>-2</del>	FRONT HANDLE BAR GRIP L/R LH 🗸 CUT / RH X SVC	Cut	110.00	15 110.00	
2	FRONT HANDLE BALANCER L/R X SVC	Bent	110.00	110.00	
2	FRONT SIDE MIRROR L/R 🗸	Bent	220.00	160 220.00	
1	FRONT HAND CLUTCH LEVER 🗸	Bent	71.00	<b>35</b> 71.00	
1	FRONT HAND BRAKE LEVER X SVC	Repair	71.00	2	
1	FRONT METER 🗸	Cracked	450.00	<b>√</b> 450.00	
)	STEERING STEM - SET X SVC	Bent	280.00	280.00	
1	STEERING STEM RACE BEARING - SET X SVC	Jammed	110.00	110.00	
1	FRONT FORK ASSY X SVC	Bent	860.00	860.00	
2	FRONT SIGNAL LAMP L/R	Repair	148.60	:E2	
1	FRONT FENDER	Repair	320.00	34.0	
1	FRONT SPORT WHEEL SHAFT	Repair	86.00	(国)	
1	FRONT SPORT WHEEL	Repair	550.00	: <del>*</del> 6	
1	FRONT SPORT WHEEL BEARING X SVC	Jammed	85.00	85.00	
1	FUEL TANK ASSY X Repair	Bent	480.00	480.00	
1	FRONT FOOT REST LH 🗸	Bent	78.00	<b>42</b> 78.00	
1	FRONT FOOT REST BRACKET LH X SVC	Bent	218.00	218.00	
1	REAR FOOT REST LH X SVC	Bent	78.00	78.00	
1	REAR SEAT COWLING ✓	Cracked	420.00	300 420.00	
1 2	REAR SIGNAL LAMP L/R LH X SVC	Cracked	180.00	80 180.00	
	RH ✓ CUT	1202	5,685.60	4,010.00	
		Less 10% discount	568.56	401.00	
		Parts Total: 1081.8	5,117.04	3,609.00	

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

# ASSESSMENT REPORT FOR VEHICLE NO. FBC 8945 G

## **SPECIAL NETT ITEMS**

1	ERP UNIT 🗸	Cracked	180.00	<b>1</b> 80.00
1	FRONT FORK OIL X SVC	Necessary	18.00	18.00
1	ENGINE CRANKCASE PROTECTOR L/R - SET 🗸	Cracked	180.00	120 180.00
1	CRASH BAR L/R - SET X SVC	Bent	340.00	340.00
1	CRASH BAR TAPE X SVC	Cut	40.00	40.00
1	REAR "YOSHIMURA" EXHAUST MUFFLER 🗸	Bent	1,680.00 <b>1</b>	400 1,680.00
	T .	Special Nett Total :	2,438.00	2,438.00

1700

L DUR

L SOR					
S/N	Description			Workshop's Estimate	Our Assessment
1	Check wiring system and light			100.00	20 80.00
2	To check, align and balance body main frame			300.00	× 250.00
3	Spray painting.			800.00	<b>250</b> 700.00
4	Labour for repair and replace parts.			1,000.00	300 900.00
	я	570	Labour Total :	2,200.00	1,930.00
	4 4	TOTAL (PAR	TS & LABOUR) \$	9,755.04	7,977.00

3351.8

To workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

(SINGAPORE DOLLARS FIVE THOUSAND EIGHT HUNDRED ONLY)

4 days

-20%: 2650

CONSULTANTIS TO STATE OF THE ST

\$5,800.00

Amas Ong Automobile Assessor