

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20008414/R1EA3Q2

Date: 10/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100289832-08

Claimant Vehicle No : SLW2912S **Insured Vehicle No :** SGN6116D

Date of Loss: 12/08/2020 **Nature of Claim:** TP **Claim No:** 2668573740SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW2912S	Engine No:	CHZ634588
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Chassis No:	WAUZZZGA6JA054993
Reg. Date:	05/02/2018 (Man. Year: 2017)	Odometer:	28510 km
Colour:	Grey		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,103.00	2,535.20	1,567.80	38.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,672.00	1,522.00	1,150.00	43.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,775.00	4,057.20	2,717.80	40.12
+ GST 7.00/7.00% (\$\$)	474.25	284.00	190.25	40.12
Nett Amount (\$\$)	7,249.25	4,341.20	2,908.05	40.12
+ Car Rental (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,643.20		

INSPECTION

Date of Assignment: 13/08/2020

Date Inspected: 19/08/2020 Inspected At:

281 ALEXANDRA RD
Repairer: Premium Automobiles Pte
Ltd (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,164.00 FS	*931.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	76.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	281.00 FS	*224.80 FS
4	1		*REAR BUMPER TOWING EYE COVER	Serviceable	43.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR -RH	Scratched	30.00 FS	*23.36 FS
6	1		*REAR PARKING AIR SENSOR -OUTER (NPA)	Serviceable	0.00 FS	*- FS
7	4		*REAR PARKING AIR SEAL RING	Not Necessary	14.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Serviceable	544.00 FS	*- FS
9	2		*REAR BUMPER HOLDING STRAP -LH/RH	Serviceable	26.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION -RH	Serviceable	53.00 FS	*- FS
11	1		*TAIL LIGHT -RH	Scratched	1,306.00 FS	*1,044.80 FS
12	1		*TAIL LIGHT TRIM -RH	Serviceable	30.00 FS	*- FS
13	2		*REAR WHEEL COVER -LH/RH	Necessary	336.00 FS	*268.80 FS
14	1		*SUNDRIES	Necessary	200.00 FS	*42.24 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,103.00** **2,535.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER AND REAR BUMPER SPOILER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,672.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >