

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008417/R1PA3Q2
Date: 18/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700051030
Claimant Vehicle No :	GBB7075D	Insured Vehicle No :	SDT3738H
Date of Loss:	07/08/2020	Nature of Claim:	TP
		Claim No:	1430169797SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB7075D		
Make & Model:	MITSUBISHI FB70BB1SRDEA, 3.0 D (M)	Engine No:	4M42A74524
Reg. Date:	10/12/2009 (Man. Year: 2009)	Chassis No:	FB70BBA20112
Colour:	Multi-colour	Odometer:	329686 km
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/75 R15	Rear Tyre Size:	185/75 R15 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,224.00	1,531.80	1,692.20	52.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	730.00	950.00	56.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,904.00	2,261.80	2,642.20	53.88
Approved Total (Overridden) (S\$)		1,800.00		

(S\$)	4,904.00	1,800.00	3,104.00	63.30
+ GST 7.00/7.00% (S\$)	343.28	126.00	217.28	63.30
Nett Amount (S\$)	5,247.28	1,926.00	3,321.28	63.30
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/08/2020

Date Inspected: 26/10/2020

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Pandan)
 45 Pandan Road
 Singapore 609286

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH HEADLAMP ASSY	Cracked	619.00 FL	*619.00 FL
2	1		*LH FR SIGNAL LAMP	Broken	206.00 FL	*206.00 FL
3	1		*LH FR SIDE LAMP	Broken	139.00 FL	*139.00 FL
4	1		*FRONT BUMPER	Bent	832.00 FL	*832.00 FL
5	1		*FR BUMPER BRACKET RHS	Serviceable	91.00 FL	*- FL
6	1		*FR BUMPER BRACKET LHS	Serviceable	91.00 FL	*- FL
7	1		*LH FR DOOR	Repair	1,827.00 FL	*- FL
8	1		*STICKER -COMPANY LOGO	Necessary	150.00 FS	*80.00 FS
9	1		*STICKER -COMPANY ADDRESS LETTERING	Necessary	30.00 FS	*15.00 FS
					Sub Total (\$\$)	3,985.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	761.00
					Total Parts (\$\$)	3,224.00

1,531.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE ,REALIGN LHS DOOR FRONT BUMPER AND AFFECTED AREA	New	900.00	300.00
2	TO PUTTY SPRAY PAINT RHS & LHS TAIL GATE AND AFFECTED AREA	New	600.00	400.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO REMOVE REFIT LHS DOOR WINDOW GLASS REGULATOR& MOTOR ,TRIM COVERTO FACILITATE FOR REPAIR	New	150.00	0.00
Gross Labour Cost (\$\$)			1,680.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >