COMFORTDELGRO ENGINEERING 45 Pandan Road S (609286)

ACCIDENT REPAIR ESTIMATES

| Our Ref: | | |
|--|------------------------------|---------------------------|
| Type of Claim Own Damage | Vehicle No. | : GBB7075D |
| X 3rd Party | Make & Model | MITSUBISHI / FB70BB1SRDEA |
| Windscreen | Year of Manufacture | : 2019 |
| _ | Chassis No. | FB70BBA20112 |
| Ins Company : AIG INS | Engine No. | 4M42A74524 |
| Excess : | Policy No. | ž |
| Date of Accident 28/07/2020 | Time of Accident | : 16.15 P.M |
| Suggested Days of Repair : 10 Day | In-house Vehicle Asse | essor |
| Repair Estimates | Name | : C. W WONG |
| | Signature | R |
| Parts (a) Cost Price Items \$3,805.00 | Contact No | : 68676919 Or 97239882 |
| Less 20 % <u>\$(761.00)</u> | | |
| (b) Nett Price Items | | |
| Less % | | |
| (c) Special Nett Items \$180.00 | | |
| Total Parts Cost (Appendix A) \$3,224.00 | | |
| Labour (Appendix B) \$1,680.00 | | |
| Total Repair Cost \$4,904.00 | | |
| The above total will be subjected to 7% G.S.T. | | |
| | | |
| 0 | | |
| Company : Survey conducted on : | at | |
| duvey conducted on | a | |
| Remarks By Surveyor | | |
| (a) The repair of this vehicle is authorized / is not auth | norized until further notice | |
| (b) Recommended Days of Repair : | | |
| (c) Resurvey : Required / No | | |
| (d) Excess :\$ | | |
| (e) Signature of surveyor : | Date: | 3 |

VACCIDENT REPAIR ESTIMATES\F3

COMFORTDELGRO ENGINEERING PTE LTD 45 Pandna Road S (609286) Tel: 68676919 Fax: 62626950

Appendix A

Spare Parts

| Vehicle No. | | GBB7075D | Submit By | š | C. W WONG | |
|---------------|------------|--------------|--------------------|---|------------|--|
| Make & Model: | MITSUBISHI | FB70BB1SRDEA | Year Manufacture : | | 2019 | |
| Chassis No. : | | FB70BBA20112 | Engine No. | : | 4M42A74524 | |
| | | | | | <u>TP</u> | |

S/Order

| | S/Order : | | | | | | | | |
|-------|-------------------------------------|-----|------------------------|---------------|---------------|------------------|---------------------------|--|--|
| S/No. | Part Description | Qty | Original Cost Price | Nett Price | List Price | S- Nett Price | Diposition By Surveyor | | |
| 1 | LH HEADLAMP ASSY | 1 | | | \$619.00 | | *** | | |
| 2 | LH FR SIGNAL LAMP | 1 | | | \$206.00 | | | | |
| 3 | LH FR SIDE LAMP | 1 | | | \$139.00 | | | | |
| 4 | FRONT BUMPER | 1 | | | \$832.00 | | | | |
| 5 | FR BUMPER BRACKET RHS | 1 | | | \$91.00 | | | | |
| 6 | FR BUMPER BRACKET LHS | 1 | | | \$91.00 | | | | |
| 7 | LH FR DOOR | 1 | | | \$1,827.00 | | | | |
| 8 | STICKER - COMPANY LOGO | 1 | | | | \$150.00 | | | |
| 9 | STICKER – COMPANY ADDRESS LETTERING | 1 | | | | \$30.00 | | | |
| 10 | | 1 | | | | | | | |
| _11_ | | 1 | | | | | | | |
| 12 | | 1 | | | | | | | |
| 13 | | 1 | | | | | | | |
| 14 | | 1 | | | | | | | |
| 15 | | 1 | | | | | | | |
| 16 | | 1 | | | | | | | |
| 17 | | 1 | | | | | | | |
| 18 | | 1 | | | | | | | |
| 19 | | 1 | | | | | | | |
| 20 | | 1 | | | | | | | |
| 21 | | 1 | | | | | | | |
| 22 | | 1 | | | | | | | |
| 23 | | 1 | | | | | | | |
| 24 | | 1 | | | | | | | |
| 25 | | 1 | | | | | | | |
| 26 | | 1 | | | | | | | |
| 27 | | 1 | | | | | | | |
| 28 | | 11 | | | | | | | |
| 29 | | 1 | | | | | | | |
| 30 | | 1 | | | | | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

COMFORTDELGRO ENGINEERING PTE LTD

Appendix B

45 Pandan Road S (609386) Tel: 68676919 Fax: 62626950,68676903

| la | hc | | , |
|----|-----|---|---|
| La | DC. | ш | r |

| Vehicle No. | : | GBB7075D | Submit By | 1 | : | C. W WONG | |
|--------------|---|------------|----------------|---------|---|-----------|--|
| Make & Model | ř | MITSUBISHI | Year of Manufa | cture : | | 2019 | |

| S/No Labour Description | Esimated Price | Adjusted Price |
|---|-------------------|-------------------|
| | | |
| TO REMOVE & REPLACE, RE ALIGN :LHS DOOR,FRONT BUM AND AFFECTED AREA | PER \$900.00 | |
| | | |
| 2 TO PUTTY, SPRAY PAINT :RHS & LHS TAIL GATE AND AFFCE AREA | ETED \$600.00 | |
| | | |
| 3 TO CHECK WIRING | \$30.00 | |
| TO REMOVE,RE FIT : LHS DOOR WINDOW GLASS ,REGULATOR&MOTOR ,TRIM COVERTO FACILILATATE FOR 4 REPAIR | \$150.00 | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.