



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER		Ref: CC4/ASM20008418/R1ga3q2 Date: 11/01/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SDH 1114J	Veh. Inspected	GBH 8242A
Policy No.	GA051494	Coverage (\$)	0.00
Claim No.	S0M02RWL	Excess (\$)	0.00
Assign From		Assign Date	13/08/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE VAN TURBO	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTFHT02P500245405	Colour	GREY
Odometer	129165 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	DOUBLESTAR	6 mm
L/H Front Tyre	195 R15C	DOUBLESTAR	6 mm
R/H Rear Tyre	195 R15C	DOUBLESTAR	6 mm
L/H Rear Tyre	195 R15C	DOUBLESTAR	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	07/08/2020	Inspection Date	14/08/2020
Survey held at	SKYLINK AUTO GARAGE PTE LTD BLK 48 TOH GUAN ROAD EAST #02-127 ENTERPRISE HUB SINGAPORE 608586		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days