

PRS send on :

Date of accident : 07/08/2020

Our vehicle : GBH8242A


your vehicle : SDH1114J

Vehicle number : GBH8242A

Vehicle mark / model : TOYOTA HIACE 2.8 MANUAL

Engine number : 1KD2827560

Chassis number : JTFHT02P500245405

 This vehicle GBH8242A in our workshop repair was sustain at the **REAR CENTRE PORTION SIDE** damage .

Estimate on parts

NO	QTY	PARTS DISCRPTION	PART NO	PARTS PRICE
				\$ 2,250.00
1	1	Tailgate assy <i>bt</i>		\$ <del>220.00</del>
2	1	Tailgate inner trim broad <i>? x su</i>		\$ 68.00
3	1	Tailgate HIACE emblem <i>nee</i>		\$ 75.00
4	1	Tailgate toyota logo <i>nee</i>		\$ <del>330.00</del>
5	1	Tailgate damper LH <i>x su</i>		\$ <del>330.00</del>
6	1	Tailgate damper RH <i>x su</i>		\$ 310.00
7	1	Tailgate lock assy <i>? bt</i>		\$ <del>130.00</del>
8	1	Tailgate lock striker <i>? x su</i>		\$ <del>297.00</del>
9	1	Tailgate center granish <i>x su</i>		\$ 280.00
10	1	Tailgate weather strip <i>nee</i>		\$ <del>50.00</del>
11	1	Tailgate side rubber LH <i>? x su</i>		\$ <del>50.00</del>
12	1	Tailgate side rubber RH <i>? x su</i>		\$ 1,220.00
13	1	Rear bumper assy <i>de</i>		\$ <del>98.50</del>
14	1	Rear bumper side retainer LH <i>x su</i>		\$ 98.50
15	1	Rear bumper side retainer RH <i>bcn</i>		\$ <del>450.00</del>
16	1	Taillamp assy LH <i>x su</i>		\$ <del>450.00</del>
17	1	Taillamp assy RH <i>x su</i>		\$ 925.00
18	1	Outer rear end panel assy <i>bt</i>		\$ 930.00
19	1	Inner rear end panel assy <i>bt</i>		
Total parts				\$ 8,562.00
Less 25%				\$ 6,421.50

6156.50  
 25%  
 4617.37

**SPECIAL NETT ITEM**

NO	QTY	PARTS DISCRPTION	PART NO	PARTS PRICE
1	1	Rear windscreen moulding <del>XAA</del>	530	\$ <del>180.00</del>
2	1	Rear windscreen sealant <del>nee</del>		\$ 60 <del>100.00</del>
3	1	70km/hr sticker <del>nee</del>		\$ 10 <del>30.00</del>
4	1	8pax sticker <del>nee</del> XAA		\$ <del>20.00</del>
5	1	Rear end panel sealant <del>nee</del>		\$ 60 <del>100.00</del>
6	1	Company logo sticker <del>nee</del>		\$ 200 <del>300.00</del>
7	1	Reverse parking sensor <del>nee</del>		\$ 200 <del>280.00</del>
Total SNett				\$ 1,010.00
parts & SNett				\$ 7,431.50

**LABOUR FOR PANEL BEATING AND SPRAY PAINT**

NO	LABOUR DISCRPTION	LABOUR PRICE
1	Labour for dismantle, panel beating, reshape and replacement tailgate assy, rear end panel, rear bumper and all affected areas	\$ <del>600</del> 750.00 700
2	Labour for spray paint tailgate, end panel and all affected areas	\$ 500.00
3	Labour for replace and distance testing reverse sensor	\$ 60 <del>80.00</del>
4	Labour for remove and replace rear windscreen and conduct water leaking test	\$ 120 <del>180.00</del>
5	Labour for perform anti - rust treatment on affected areas	\$ 80 <del>180.00</del>
Total labour		\$ 1,690.00
Parts + labour		\$ 9,121.50
Total amount		\$ 10,811.50

\*We will carry out LUMP SUM repair on GBH8242A 3rd party claim\*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4617.37  
530.00  
1460.00

6607.37  
20%  
5,285.90  
45-5,300

email: rasul@lkkauto.com

RASUL

4p 90010068

6days

4/8

14/08/2020

@1280

Resurvey after repair