

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20008420/EDA3Q2

**Date:** 26/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100057793

**Claimant**  
**Vehicle No :** GBK1871P **Insured Vehicle No :** SJA5645H

Date of Loss: 08/08/2020 Nature of Claim: TP Claim No: 0120521681SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBK1871P</b>		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KDB020531
Reg. Date:	31/01/2020 (Man. Year: 2019)	Chassis No:	JTFHT02P000250043
Colour:	White	Odometer:	9568 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185R15C	Rear Tyre Size:	185R15C
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,544.25	2,139.00	1,405.25	39.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,420.00	1,280.00	47.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,244.25</b>	<b>3,559.00</b>	<b>2,685.25</b>	<b>43.00</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,850.00</b>		
<b>(S\$)</b>	6,244.25	2,850.00	3,394.25	54.36
<b>+ GST 7.00/7.00% (S\$)</b>	437.10	199.50	237.60	54.36
<b>Nett Amount (S\$)</b>	<b>6,681.35</b>	<b>3,049.50</b>	<b>3,631.85</b>	<b>54.36</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>Nett Liability (S\$)</b>		<b>3,409.50</b>		

### INSPECTION

Date of Assignment: 13/08/2020

Date Inspected: 17/08/2020 Inspected At:

Efficient Motor & Engineering Works  
Pte Ltd (HQ)  
56 Loyang Way #06-07, Loyang  
Enterprise Building  
Singapore 508775

Estimated Period of Repair: 6.0 days

---

**Adjuster:** CHEN TSUE YEE**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	380.00 FL	* - FL
2	1		*REAR BUMPER RETAINER LH	Not Necessary	28.00 FL	* - FL
3	1		*LH REAR FENDER PANEL	Dented	1,062.00 FL	*1,062.00 FL
4	1		*LH SLIDE DOOR	Dented	1,600.00 FL	*1,600.00 FL
5	1		*LH SLIDE DOOR WEATHERSTRIP	Not Necessary	359.00 FL	* - FL
6	1		*LH SLIDE DOOR LOCK REAR	Not Necessary	280.00 FL	* - FL
7	1		*LH SLIDE DOOR HINGE CENTER	Not Necessary	150.00 FL	* - FL
8	1		*LH SLIDE DOOR ROLLER LOWER	Not Necessary	320.00 FL	* - FL
9	1		*REAR WHEEL HUB CAP	Cut	180.00 FL	*150.00 FL
10	1		*TAIL LAMP LH	Not Necessary	260.00 FL	* - FL
11	1		*SEALANT	Necessary	80.00 FS	*30.00 FS
					<b>Sub Total (\$\$)</b>	<b>4,699.00 2,842.00</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,154.75 703.00</b>
					<b>Total Parts (\$\$)</b>	<b>3,544.25 2,139.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CUT & WELD -DAMAGED PANELS RH REAR FENDER TO PANEL BEAT & ALING DOOR ,REMOVE & REPLACE DAMAGED PARTS	New	1,200.00	800.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	100.00	30.00
4	TO SPRAY PAINTING FOR LH PORTIONS ,& AFFECTED AREAS	New	1,000.00	450.00
5	TO TRANSFER SLIDE DOOR COMPONENTS	New	150.00	50.00
6	TO DO TYRE BALANCING & WHEEL ALIGNMENT	New	150.00	60.00
<b>Gross Labour Cost (\$)</b>			<b>2,700.00</b>	<b>1,420.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**