

ASS. REC. BY:

Steve

REF:

CC4 / AIG 20008420 / Edg 3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GOK 1871P

Yr Regn:

31/1/20.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

c.c

2982

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

9568

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT 02P000 250743

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185R15C

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

8/8/20

D.O.I.

17/8/20

Survey held at

EFFICIENT motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MK-66K

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Rep. Form:

Lump Sum / L.B. / C.

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBK1871P

MAKE & MODEL : TOYOTA HIACE VAN TURBO 5DR MT

CHASSIS NO : JTFHT02P000250043

DATE : 13 AUG 2020

CLAIM TYPE : TP CLAIM

D.O.A : 08 AUG 2020

TO : AIG ASIA PACIFIC INSURANCE PTE LTD L/S, RY AL 6 days

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR BUMPER X		\$ 380.00	\$ 380.00
2	1	REAR BUMPER RETAINER LH X		\$ 28.00	\$ 28.00
3	1	LH REAR FENDER PANEL / 00		\$ 1,062.00	\$ 1,062.00
4	1	LH SLIDE DOOR / 00		\$ 1,600.00	\$ 1,600.00
5	1	LH SLIDE DOOR WEATHERSTRIP X		\$ 359.00	\$ 359.00
6	1	LH SLIDE DOOR LOCK REAR X		\$ 280.00	\$ 280.00
7	1	LH SLIDE DOOR HINGE CENTER X		\$ 150.00	\$ 150.00
8	1	LH SLIDE DOOR ROLLER LOWER X		\$ 320.00	\$ 320.00
9	1	REAR WHEEL HUB CAP / CUT		\$ 180.00	\$ 180.00
10	1	TAIL LAMP LH X		\$ 260.00	\$ 260.00
				\$ 4,619.00	\$ 4,619.00

TOTAL PRICE	\$ 4,619.00
LESS 25%	\$ 1,154.75
SUB TOTAL PRICE	\$ 3,464.25

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	SEALANT / MC		\$ 80.00	\$ 80.00
TOTAL S/NETT				\$ 80.00	\$ 80.00

Labour Charges

1	To cut & weld -damaged panels RH rear fender/	\$ 1,200.00	800
	To panel beat & align door, remove & replace damaged parts.		
2	To apply anti rust coat and Tuff Kote repaired areas	\$ 100.00	30
3	To check and rectify lighting & wiring.	\$ 100.00	50
4	To Spray painting for LH Portions, & affected areas.	\$ 1,000.00	450
5	To transfer slide door components.	\$ 150.00	50
6	To do tyre balancing & wheel alignment	\$ 150.00	60

TOTAL LABOUR

\$ 2,700.00

Total Cost of Repairs

\$ 6,244.25

Date:

Signature: (Total parts + Total S/Nett + Total Labour Cost)

Acknowledged by Repairer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company