

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20008438/T1ES3Q2

**Date:** 30/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100413837

**Claimant**  
**Vehicle No :** SHA1914G **Insured Vehicle No :** SKT2951G

Date of Loss: 13/08/2020 Nature of Claim: TP Claim No: 9335410768SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA1914G**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4DFDU596457

Reg. Date: 17/03/2016 (Man. Year: 2015) Chassis No: KMHLB41UMGU085594

Colour: Blue Odometer: 611365 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	326.36	326.36	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,560.00	290.00	15.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,176.36</b>	<b>1,886.36</b>	<b>290.00</b>	<b>13.33</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
<b>(S\$)</b>	2,176.36	1,500.00	676.36	31.08
<b>+ GST 7.00/7.00% (S\$)</b>	152.35	105.00	47.35	31.08
<b>Nett Amount (S\$)</b>	<b>2,328.71</b>	<b>1,605.00</b>	<b>723.71</b>	<b>31.08</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 14/08/2020

Date Inspected: 14/08/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRT & REAR WHEEL CAP RH	Distorted	214.20 FL	*214.20 FL
2	1		*FRT DOOR COMFORTDELGRO RH	Cut	75.00 FS	*75.00 FS
3	1		*REAR DOOR APPS RH	Cut	80.00 FS	*80.00 FS
					<b>Sub Total (S\$)</b>	<b>369.20</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>42.84</b>
					<b>Total Parts (S\$)</b>	<b>326.36</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	560.00
2	SPRAYPAINT-FRT BUMPER,FRT FENDER RH,BOTH DOORS RH & RR FENDER RH	New	1,250.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,850.00</b>	<b>1,560.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >