Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20008439/R1TF3E2

Date: 18/11/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle SMF217G Insured Vehicle No: SKL9311A

Date of Loss: 08/08/2020 Nature of Claim: TP Claim No: CDMPG20001067

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMF217G

Make & Model: MAZDA 3, 1.5 SEDAN (A) Engine No: P520550529

Reg. Date: 25/10/2018 (Man. Year: 2018) Chassis No: JM6BN22A8K0251238

Colour: Black Odometer: 19234 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,848.30	434.17	1,414.13	76.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,115.00	660.00	2,455.00	78.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,963.30	1,094.17	3,869.13	77.95
+ GST 7.00/7.00% (S\$)	347.43	76.59	270.84	77.96
Nett Amount (S\$)	5,310.73	1,170.76	4,139.97	77.95

INSPECTION

Date of Assignment: 14/08/2020

Date Inspected: 19/08/2020 Inspected At: Eurokars Services Pte Ltd (HQ)

27A Tanjong Penjuru Singapore 609042

Estimated Period of Repair: 1.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

(REPAIR COST NOT CONCLUDE)

Adjuster Report Page 4 of 5

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Nov 2020)

Parts: 143 MAZDA 3 1.5 SEDAN (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF217G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	1,128.60 F	*-FL
2	4		*GROMMET,REAR BUMPER	Not Necessary	10.80 F	*-FL
3	4		*FASTENER,REAR BUMPER	Not Necessary	12.00 F	*-FL
4	4		*RIVET,REAR BUMPER	Not Necessary	18.00 F	*-FL
5	1		*TAILLAMP LHS	Cracked	534.90 F	*534.90 FL
6	1		*GASKET LHS,TAILLAMP	Necessary	22.00 F	*22.00 FL
7	1		*GASKET RHS,TAILLAMP	Necessary	22.00 F	*22.00 FL
8	1		*SUNDRIES	Not Necessary	100.00 FS	*-FS
F=Fra	nchise	part. S=SpcNe	tt. L=ListItemDisc.	_		
				Sub Total (S\$)	1,848.30	578.90
	- List Item Discount on L Items 0.00/25.00% (S\$) 0.00 144.73					
				Total Parts (S\$)	1,848.30	434.17
			Report was unsubmit	tted during this print-out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO REPLACE REAR BUMPER,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	990.00	330.00				
2	TO RESPRAY REAR BUMPER	New	945.00	0.00				
3	TO TRANSFER REVERSE SENSORS	New	330.00	0.00				
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00				
5	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	0.00				
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00				
	Gross Labour Cost (S\$)		3,115.00	660.00				
	Report was unsubmitted during t	his print-out.						

< END OF ESTIMATES >