

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20008444/AVF3E2

Date: 16/10/2020

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMM5548G

Insured Vehicle No : GBH9064R

Date of Loss: 12/08/2020

Nature of Claim: TP

Claim No: CDMCG20001082

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM5548G

Make &amp; Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)

Engine No: HRA2215896A

Reg. Date: 24/12/2015 (Man. Year: 2015)

Chassis No: SJNFEAJ11U1544930

Colour: Grey

Odometer: 156680 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size:

215/60 R17

Front Left Side: Habilead 6 mm

Rear Left Side:

Habilead 6 mm

Front Right Side: Habilead 6 mm

Rear Right Side:

Habilead 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,967.10	3,956.30	4,010.80	50.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,310.00	2,330.00	64.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,607.10</b>	<b>5,266.30</b>	<b>6,340.80</b>	<b>54.63</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,200.00</b>		
<b>Nett Amount (\$\$)</b>	<b>11,607.10</b>	<b>4,200.00</b>	<b>7,407.10</b>	<b>63.82</b>

### INSPECTION

Date of Assignment: 14/08/2020

Date Inspected: 17/08/2020 Inspected At:

Xin Hua Workshop Pte Ltd (HQ)

23 Kaki Bukit Ave 4 #04-01

Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2020)
<b>Parts:</b>	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM5548G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Not Necessary	1,153.00 FL	*- FL
2	1		*FRT BUMPER	Deformed	697.00 FL	*697.00 FL
3	1		*FRT BUMPER SIDE RETAINER RH	Necessary	82.00 FL	*82.00 FL
4	1		*FRT BUMPER BRACKET RH	Not Necessary	207.00 FL	*- FL
5	1		*FRT FOG LAMP RH	Not Necessary	388.00 FL	*- FL
6	1		*FRT FOG LAMP COVER RH	Not Necessary	156.00 FL	*- FL
7	1		*FRT HEADLAMP RH	Cut	712.00 FL	*712.00 FL
8	1		*FRT FENDER RH	Dented	831.00 FL	*685.00 FL
9	1		*FRT FENDER BRACKET RH	Not Necessary	166.00 FL	*- FL
10	1		*FRT FENDER INNERSHIELD RH	Torn	154.00 FL	*154.00 FL
11	1		*FRT FENDER ENCLOSE RH	Not Necessary	91.00 FL	*- FL
12	1		*FRT RIM RH	Cut	1,330.20 FS	*650.00 FS
13	1		*FRT RIM WHEEL CAP RH	Missing	94.00 FL	*94.00 FL
14	1		*FRT KNUCKLE ARM RH	Not Necessary	701.00 FL	*- FL
15	1		*FRT WHEEL BEARING RH	Damaged	399.00 FL	*215.00 FL
16	1		*FRT LOW ARM RH	Bent	288.00 FL	*288.00 FL
17	1		*FRT SHOCK ABSORBER RH	Bent	689.00 FL	*547.00 FL
18	10		*FRT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
19	5		*FRT GRILLE CLIP	Not Necessary	20.00 FS	*- FS
20	10		*FRT FENDER INNERSHIELD CLIP	Not Necessary	40.00 FS	*- FS
21	10		*FENDER WHEELARCH CLIP	Necessary	40.00 FS	*30.00 FS
22	1		*FRT TYRE RH	Not Necessary	250.00 FS	*- FS
23	1		*FRT FENDER WHEELARCH GARNISH RH	Cut	133.00 FL	*133.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,661.20</b>	<b>4,317.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	694.10	360.70
<b>Total Parts (\$)</b>	<b>7,967.10</b>	<b>3,956.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,000.00	500.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT BONNET, FRT SUPORT PANEL, FRT FENDER RH, FRT DOOR RH, RR DOOR RH	New	1,600.00	400.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
4	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	80.00	50.00
5	TO REMOVE AND REPLACE RHF UNDER CARRIAGE PARTS	New	250.00	200.00
6	TO PERFORM DIAGNOSIS CHECK & RESET FAULTY CODE AFTER REPAIR	New	250.00	0.00
7	TO REFOCUS HEADLAMP	New	80.00	0.00
8	TO REMOVE AND REFIT FRONT SENSOR	New	80.00	50.00
9	TO CONDUCT 4 WHEEL ALIGNMENT	New	180.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>3,640.00</b>	<b>1,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >