

ASSESSMENT REPORT FOR VEHICLE NO. FBG 5689 U

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT WINDSHIELD <i>X SVC</i>	Cracked	180.00	180.00 <i>X</i>
1	HEADLAMP COWLING <i>/ CRA</i>	Cracked	380.00	380.00 <i>200</i>
1	HEADLAMP <i>X SVC</i>	Cracked	320.00	320.00 <i>X</i>
1	SIDE MIRROR L/R <i>- SCR</i>	Cracked	140.00	140.00 <i>90</i>
2	HEADLAMP COWLING INNER GARNISH L/R <i>X SVC</i>	Cracked	120.00	120.00 <i>X</i>
1	METER ASSY <i>/ short.</i>	Faulty	380.00	380.00 <i>220</i>
1	METER STAY BRACKET <i>X SVC</i>	Bent	95.00	95.00 <i>X</i>
1	HANDLE BRAKE LEVER <i>/ BT</i>	Bent	68.00	68.00 <i>40</i>
1	HANDLE CLUTCH LEVER <i>/ SCR</i>	Bent	68.00	68.00 <i>40</i>
1	HANDLE BAR BALANCER L/R <i>/ SCR</i>	Bent	120.00	120.00 <i>50</i>
1	HANDLE BAR <i>/ BT</i>	Bent	180.00	180.00 <i>120</i>
1	HANDLE GRIP L/R <i>- cut</i>	Cut	68.00	68.00 <i>40</i>
1	HANDLE SWITCH RH <i>/ CRA</i>	Cracked	180.00	180.00 <i>86</i>
1	HANDLE SWITCH LH <i>- CRA</i>	Cracked	200.00	200.00 <i>80</i>
1	STEERING STEM - SET <i>X SVC</i>	Bent	185.00	185.00 <i>X</i>
1	STEERING STEM RACE BEARING - SET <i>/ Tahn</i>	Jammed	85.00	85.00 <i>/</i>
2	SIDE FAIRING COWLING L/R <i>/ CRA</i>	Cracked	460.00	460.00 <i>240</i>
2	SIDE LOWER COWLING L/R <i>- CRA</i>	Cracked	280.00	280.00 <i>160</i>
1	FRONT SIGNAL L/R <i>/ CRA</i>	Cracked	110.00	110.00 <i>60</i>
1	FRONT FENDER <i>/ SCR</i>	Cracked	185.00	185.00 <i>130</i>
1	FRONT FORK ASSY <i>/ BT</i>	Bent	420.00	420.00 <i>300</i>
1	FRONT WHEEL SHAFT <i>X SVC</i>	Bent	30.00	30.00 <i>X</i>
1	FRONT WHEEL BEARING <i>X SVC</i>	Jammed	38.00	38.00 <i>X</i>
1	FRONT WHEEL <i>X SVC</i>	Bent	320.00	320.00 <i>X</i>
1	FRONT BRAKE CALIPER <i>X SVC</i>	Repair	210.00	-
1	FRONT BRAKE DISC ROTOR <i>X SVC</i>	Bent	185.00	185.00 <i>X</i>
1	FUEL TANK COWLING L/R <i>/ CRA</i>	Cracked	420.00	420.00 <i>150</i>
1	FUEL TANK ASSY <i>X SVC</i>	Repair	460.00	-
1	FRONT RH FOOTREST <i>/ SCR</i>	Bent	55.00	55.00 <i>/</i>
1	FRONT RH FOOT REST BRACKET <i>X SVC</i>	Bent	160.00	160.00 <i>X</i>
1	FRONT FOOT BRAKE LEVER <i>/ SCR</i>	Bent	140.00	140.00 <i>70</i>
1	KICK STARTER SHAFT <i>X SVC</i>	Bent	128.00	128.00 <i>X</i>
1	REAR RH FOOTREST <i>- BT</i>	Bent	55.00	55.00 <i>/</i>
1	EXHAUST SIDE HEAT SHIELD <i>/ SCR</i>	Cracked	95.00	95.00 <i>/</i>
1	EXHAUST TAIL COVER <i>/ CRA</i>	Cracked	55.00	55.00 <i>/</i>
1	EXHAUST PIPE <i>X R</i>	Repair	538.00	-

Less 10% discount
Parts Total:

7,113.00	5,905.00
711.30	590.50
6,401.70	5,314.50

2,415.00
- 10%
2,173.50

ASSESSMENT REPORT FOR VEHICLE NO. FBG 5689 U

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE <i>X SVC</i>	Necessary	20.00	20.00 <i>X</i>
1	FRONT FORK OIL <i>/ NEC</i>	Necessary	18.00	18.00 <i>/</i>
1	ERP UNIT <i>X SVC</i>	Faulty	180.00	180.00 <i>X</i>
1	BRAKE FLUID - BTL <i>/ NEC</i>	Necessary	30.00	30.00 <i>/</i>
1	COWLING DECAL STICKER L/R - SET <i>/ NEC</i>	Necessary	120.00	120.00 <i>80</i>
1	REAR TOP BOX AND BASE PLATE <i>/ CRA</i>	Cracked	300.00	300.00 <i>200</i>
1	REAR TOP BOX BRACKET/RAIL SET <i>/ BT</i>	Bent	80.00	80.00 <i>/</i>
Special Nett Total :			748.00	748.00

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	Transport.	40.00	40.00 <i>/</i>
2	Check wiring system and light.	120.00	100.00 <i>30</i>
3	To check, align and balance body main frame.	300.00	250.00 <i>X</i>
4	Spray painting.	800.00	700.00 <i>150</i>
5	Labour for repair and replace parts .	1,200.00	1,000.00 <i>300</i>
Labour Total :		2,460.00	2,090.00
TOTAL (PARTS & LABOUR) \$		9,609.70	8,152.50

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$4,200.00

(SINGAPORE DOLLARS FOUR THOUSAND TWO HUNDRED ONLY)



Amas Ong
Automobile Assessor

$$\begin{array}{r}
 P = 2,173.50 \\
 M = 408 \\
 L = 520 \\
 \hline
 3,101.50 \\
 - 20\% \\
 \hline
 2,481.20
 \end{array}$$

415
\$2,000
3 days