



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 5689U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSHIELD	SERVICEABLE	180.00	-
1	HEADLAMP COWLING	CRACKED	380.00	200.00
1	HEADLAMP	SERVICEABLE	320.00	-
2	SIDE MIRROR L/R	SCRATCHED	140.00	90.00
2	HEADLAMP COWLING INNER GARNISH L/R	SERVICEABLE	120.00	-
1	METER ASSY	SHORTED	380.00	220.00
1	METER STAY BRACKET	SERVICEABLE	95.00	-
1	HANDLE BRAKE LEVER	BENT	68.00	40.00
1	HANDLE CLUTCH LEVER	SCRATCHED	68.00	40.00
2	HANDLE BAR BALANCER L/R	SCRATCHED	120.00	50.00
1	HANDLE BAR	BENT	180.00	120.00
2	HANDLE GRIP L/R	CUT	68.00	40.00
1	HANDLE SWITCH RH	CRACKED	180.00	80.00
1	HANDLE SWITCH LH	CRACKED	200.00	80.00
1	SET STEERING STEM	SERVICEABLE	185.00	-
1	SET STEERING STEM RACE BEARING	JAMMED	85.00	85.00
2	SIDE FAIRING COWLING L/R	CRACKED	460.00	240.00
2	SIDE LOWER COWLING L/R	CRACKED	280.00	160.00
2	FRONT SIGNAL L/R	CRACKED	110.00	60.00
1	FRONT FENDER	SCRATCHED	185.00	130.00
1	FRONT FORK ASSY	BENT	420.00	300.00
1	FRONT WHEEL SHAFT	SERVICEABLE	30.00	-
1	FRONT WHEEL BEARING	SERVICEABLE	38.00	-
1	FRONT WHEEL	SERVICEABLE	320.00	-
1	FRONT BRAKE CALIPER	SERVICEABLE	210.00	-
1	FRONT BRAKE DISC ROTOR	SERVICEABLE	185.00	-
2	FUEL TANK COWLING L/R	N/S CRACKED	420.00	150.00
1	FUEL TANK ASSY	SERVICEABLE	460.00	-
1	FRONT RH FOOTREST	SCRATCHED	55.00	55.00
1	FRONT RH FOOTREST BRACKET	SERVICEABLE	160.00	-
1	FRONT FOOT BRAKE LEVER	SCRATCHED	140.00	70.00

Report Ref No. CS3/III20003522/Qvf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	KICK STARTER SHAFT	SERVICEABLE	128.00	-
1	REAR RH FOOTREST	BENT	55.00	55.00
1	EXHAUST SIDE HEAT SHIELD	SCRATCHED	95.00	95.00
1	EXHAUST TAIL COVER	CRACKED	55.00	55.00
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	538.00	-
	LESS 10% DISCOUNT		-711.30	-241.50
			6,401.70	2,173.50
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	20.00	-
1	FRONT FORK OIL (SN)	NECESSARY	18.00	18.00
1	ERP UNIT (SN)	SERVICEABLE	180.00	-
1	BTL BRAKE FLUID (SN)	NECESSARY	30.00	30.00
2	SET COWLING DECAL STICKER L/R (SN)	NECESSARY	120.00	80.00
1	REAR TOP BOX AND BASE PLATE (SN)	CRACKED	300.00	200.00
1	REAR TOP BOX BRACKET/RAIL SET (SN)	BENT	80.00	80.00
			748.00	408.00
	<u>LABOUR</u>			
	TRANSPORT.		40.00	40.00
	CHECK WIRING SYSTEM AND LIGHT.		120.00	30.00
	TO CHECK,ALIGN AND BALANCE BODY MAIN FRAME.	NOT NECESSARY	300.00	-
	SPRAY PAINTING.		800.00	150.00
	LABOUR FOR REPAIR AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF EXHAUST PIPE.		1,200.00	300.00
			2,460.00	520.00
GRAND TOTAL			9,609.70	3,101.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS3/III20003522/Qvf3e2-1

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.