

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20008445/UGS3Q2

**Date:** 26/11/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0001565_01
<b>Claimant Vehicle No :</b>	SMQ8630K	<b>Insured Vehicle No :</b>	SKJ4715L
Date of Loss:	13/08/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0001522

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ8630K	Engine No:	2ZR0E75749
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800417574
Reg. Date:	05/12/2019 (Man. Year: 2019)	Odometer:	44139 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	28,890.50	7,274.22	21,616.28	74.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	2,370.00	3,010.00	55.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>34,270.50</b>	<b>9,644.22</b>	<b>24,626.28</b>	<b>71.86</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>7,700.00</b>		
<b>Nett Amount (\$\$)</b>	<b>34,270.50</b>	<b>7,700.00</b>	<b>26,570.50</b>	<b>77.53</b>
<b>+ Car Rental (5.0 x S\$120.00/day) (\$\$)</b>		600.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>8,302.00</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>8,300.00</b>		

### INSPECTION

Date of Assignment:	14/08/2020	
Date Inspected:	14/08/2020 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

---

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2020)
<b>Parts:</b>	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMQ8630K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN	Not Necessary	1,425.30 F	*- FL
2	1	*REAR WINDSCREEN MOULDING	Not Necessary	188.20 F	*- FL
3	1	*TAILGATE	Badly Dented	2,145.10 F	*1,645.10 FL
4	1	*TAILGATE HYBRID SYNERGY DRIVE EMBLEM	Not Necessary	86.10 F	*- FL
5	1	*TAILGATE NOAH EMBLEM	Not Necessary	66.50 F	*- FL
6	1	*TAILGATE REAR LOGO	Not Necessary	68.20 F	*- FL
7	1	*TAILGATE INNER TRIM BOARD	Deformed / Torn	681.10 F	*645.10 FL
8	1	*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
9	1	*TAILGATE INNER PULL POCKET	Deformed	66.50 F	*52.50 FL
10	1	*TAILGATE OUTER CHROME MOULDING	Not Necessary	688.50 F	*- FL
11	1	*TAILGATE INNER LOCK	Dented / Shorted	399.20 F	*399.20 FL
12	1	*TAILGATE WEATHERSTRIP	Twisted	388.10 F	*299.20 FL
13	1	*REAR BUMPER	Distorted	1,450.00 F	*1,050.10 FL
14	1	*REAR BUMPER REFLECTORS	O/S Cracked	210.00 F	*85.50 FL
15	1	*REAR BUMPER PDC SENSORS	O/S Shorted	626.20 F	*225.00 FL
16	1	*REAR BUMPER BRACKETS	O/S Dented	198.00 F	*99.00 FL
17	1	*REAR BUMPER SIDE RETAINERS	O/S Bent	133.00 F	*66.50 FL
18	1	*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
19	1	*REAR END PANEL OUTER	Badly Dented	945.10 F	*820.10 FL
20	1	*REAR END PANEL INNER	Repair	1,022.30 F	*- FL
21	1	*REAR END PANEL TOP GARNISH	Distorted	362.50 F	*322.10 FL
22	2	*TAILLAMPS	Not Necessary	2,100.00 F	*- FL
23	1	*TAILLAMP LOWER GARNISHS	O/S Dented	1,650.00 F	*425.20 FL
24	2	*TAILLAMP HOUSING PANELS	Repair	970.00 F	*- FL
25	1	*REAR EXHAUST	Not Necessary	911.20 F	*- FL
26	1	*REAR EXHAUST HEAT SHIELD	Not Necessary	188.20 F	*- FL
27	2	*REAR FENDERS	Repair	3,360.00 F	*- FL
28	2	*REAR FENDER INNER BOARDS	Deformed / Torn	1,830.00 F	*1,430.20 FL
29	1	*REAR FLOOR PANEL	Repair	1,266.10 F	*- FL
30	1	*REAR FLOOR PANEL TOP BOARD	Warped / Cracked	825.00 F	*825.00 FL
31	1	*REAR FLOOR PANEL INNER CLOTH	Torn	850.10 F	*622.50 FL
32	1	*REAR AIR CON BLOWER	Not Necessary	2,880.00 F	*- FL
33	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
34	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
35	1	*SET REAR FLOOR PANEL INSULATOR	Not Necessary	280.00 FS	*- FS
36	1	*SET REAR REVERSE CAMERA	Shorted	380.00 FS	*350.00 FS
37	1	*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (S\$)** 28,890.50 **9,552.30**  
**- List Item Discount on L Items 0.00/25.00% (S\$)** 0.00 **2,278.08**

**Total Parts (S\$)** 28,890.50 **7,274.22**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE COMPONENTS	New	120.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
8	TO SPRAY RUST PROOFING	New	150.00	60.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,200.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,180.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,380.00</b>	<b>2,370.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >