

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20008448/USF3E2

Date: 04/09/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713

Claimant Vehicle No : SJC8703T

Insured Vehicle No : SLJ5470Z

Date of Loss: 13/08/2020

Nature of Claim: TP Claim No: 627298

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC8703T**

Make & Model: TOYOTA MARK X, 2.5 (A)

Engine No: 4GR0412067

Reg. Date: 29/02/2008 (Man. Year: 2007)

Chassis No: GRX1203050497

Colour: Black

Odometer: 146606 km

Engine Capacity: 2499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,574.40	7,862.67	14,711.73	65.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,810.00	3,140.00	2,670.00	45.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,384.40	11,002.67	17,381.73	61.24
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	28,384.40	8,800.00	19,584.40	69.00
+ GST 7.00/7.00% (S\$)	1,986.91	616.00	1,370.91	69.00
Nett Amount (S\$)	30,371.31	9,416.00	20,955.31	69.00

INSPECTION

Date of Assignment: 18/08/2020

Date Inspected: 14/08/2020 Inspected At:

 Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Sep 2020)
Parts:	143	TOYOTA MARK X 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC8703T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Badly Dented	1,665.10 F	*1,399.10 FL
2	1		*BOOTLID REAR LOGO	Necessary	78.50 F	*68.80 FL
3	1		*BOOTLID 250 EMBLEM	Necessary	82.20 F	*82.20 FL
4	1		*BOOTLID MARK X EMBLEM	Necessary	89.50 F	*89.50 FL
5	1		*BOOTLID LICENCE PLATE GARNISH	Cut / Cracked	665.10 F	*499.10 FL
6	1		*BOOTLID INNER LOCK	Twisted	495.10 F	*395.50 FL
7	1		*BOOTLID INNER TRIM	Torn	422.50 F	*422.50 FL
8	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	50.00 F	*50.00 FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	316.10 F	*288.20 FL
10	2		*BOOTLID HINGES	Not Necessary	290.00 F	*- FL
11	1		*REAR BUMPER	Distorted	1,450.00 F	*1,250.00 FL
12	1		*REAR BUMPER SIDE RETAINERS	O/S Bent	170.00 F	*85.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*REAR BUMPER BRACKETS	O/S Dented	182.00 F	*91.00 FL
15	1		*REAR BUMPER SPONGE	No such part	222.00 F	*- FL
16	1		*REAR BUMPER REINFORCEMENT	No such part	395.00 F	*- FL
17	1		*REAR BUMPER EXHAUST CHROMES	O/S Bent	500.00 F	*185.00 FL
18	1		*REAR EXHAUST	Not Necessary	1,281.10 F	*- FL
19	2		*TAILLAMPS	Cracked	1,700.00 F	*1,170.20 FL
20	1		*TAILLAMP HOUSING PANELS	O/S Dented	1,040.00 F	*385.50 FL
21	1		*REAR END PANEL	Badly Dented	899.10 F	*725.10 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	455.30 F	*299.40 FL
23	1		*REAR FENDERS	O/S Badly Dented / Buckled	3,800.00 F	*1,145.20 FL
24	1		*REAR FENDER INNER TRIMS	O/S Torn	1,050.00 F	*488.20 FL
25	1		*REAR WINDSCREEN MOULDING	Necessary	188.20 F	*188.20 FL
26	1		*REAR FLOOR PANEL	Repair	1,885.10 F	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Twisted	499.20 F	*499.20 FL
28	2		*REAR AIR VENTS	Not Necessary	330.00 F	*- FL
29	1		*REAR SPLASH SHIELD O/S	Not Necessary	118.20 F	*- FL
30	1		*REAR DOOR O/S	Repair	1,495.10 F	*- FL
31	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
32	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
33	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	280.00 FS	*180.00 FS
34	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
35	1		*REAR LICENCE PLATE W/HOLDER	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 22,574.40 10,326.90
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 2,464.23

Total Parts (\$\$) 22,574.40 7,862.67

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
8	TO TRANSFER BOOTLID MECHANISM	New	120.00	60.00
9	TO SPRAY RUST PROOFING	New	180.00	100.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,500.00	1,500.00
11	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (\$\$)			5,810.00	3,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >