



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 6546C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT HEADLAMP	DAMAGED	845.00	845.00
1	FRONT BUMPER FOG LAMP	SERVICEABLE	400.00	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	687.00	-
1	FRONT BUMPER SIDE RETAINER	DAMAGED	35.00	35.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	670.00	-
1	FRONT FENDER INNER SHIELD	SERVICEABLE	189.00	-
1	FRONT WHEEL HUB WITH BEARING	NECESSARY	285.00	285.00
1	FRONT SHOCK ABSORBER	DAMAGED	485.00	485.00
1	FRONT KNUCKLE ARM	DAMAGED	655.00	655.00
1	FRONT LOWER ARM	DAMAGED	240.00	240.00
1	FRONT LOWER ARM BALL JOINS	DAMAGED	78.00	78.00
1	FRONT O/S SIDE MIRROR	DAMAGED	882.70	882.70
	LESS 10% DISCOUNT		-545.17	-350.57
			4,906.53	3,155.13
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT BUMPER (SN)	DAMAGED	1,800.00	1,500.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	30.00	30.00
1	FRONT TYRE (SN)	SERVICEABLE	380.00	-
1	FRONT SPORT RIM (SN)	DAMAGED	650.00	650.00
			2,860.00	2,180.00
<b><u>LABOUR</u></b>				
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		60.00	30.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		280.00	200.00
	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.		180.00	80.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT FENDER.		700.00	400.00

Report Ref No. CS1/LAW20008450/Aqf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		650.00	440.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		120.00	30.00
			1,990.00	1,180.00
GRAND TOTAL			9,756.53	6,515.13
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00

Report Ref No. CS1/LAW20008450/Aqf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.