#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG20008453/AQF3E2 AIG Building, 78 Shenton Way, #09-16

Date: 06/01/2021 Singapore 079120

REFERENCE

Insured/Claimant: LI YUANFANGLI YUANFANG Policy No: 1800143196-01

Date of Loss: 30/07/2020 Nature of Claim: OD Claim No: 3524342868SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMF9486L

Make & Model: AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A) CHZB22242 Engine No:

Chassis No: Reg. Date: 29/11/2018 (Man. Year: 2018) WAUZZZ8V6KA008776

Colour: White Odometer: 34481 km

**Engine Capacity:** 999 cc Market Value/New Car Price: S\$93,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Footbrake (Serviceable): General Condition: Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

**CONDITION OF TYRES** 

205/55 R16 Front Tyre Size: 205/55 R16 Rear Tyre Size: Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,385.00	2,674.88	3,710.12	58.11
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,422.00	1,242.00	1,180.00	48.72
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,807.00	3,916.88	4,890.12	55.53
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	8,207.00	3,316.88	4,890.12	59.58
	+ GST 7.00/7.00% (S\$)	574.49	232.18	342.31	59.59
	Nett Amount (S\$)	8,781.49	3,549.06	5,232.43	59.58

**INSPECTION** 

Date of Assignment: 14/08/2020

Premium Automobiles Pte Ltd (UBI)

Date Inspected: 13/08/2020 Inspected At: 55 Ubi Road 1 Singapore 408699

3.0 days Estimated Period of Repair:

Adjuster: **ADRIAN LING** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,842.00 FS	*1,473.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	159.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	293.00 FS	*-FS
5	2		*FRONT BUMPER CLOSING ELEMENT - LH/RH	Not Necessary	586.00 FS	*- FS
6	1		*RADIATOR GRILLE	Cut	1,406.00 FS	*1,124.80 FS
7	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	189.00 FS	*-FS
8	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
9	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	372.00 FS	*- FS
11	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	715.00 FS	*-FS
12	1		*FRONT BUMPR FOAM FILLER PIECE	Not Necessary	187.00 FS	*-FS
13	1		*FOAM FILLER PIECE COVER	Not Necessary	121.00 FS	*-FS
14	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	48.00 FS	*- FS
15	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
16	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Fra	nchise	part. S=SpcN	lett.			
				Total Parts (S\$)	6,385.00	2,674.88
			Report was unsubmitted during this p	rint-out.		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND TRANSFER / REINSTALL FRONT BUMPER WIRE HARNESS FOR FRONT PARKING AID SYSTEM	R New	280.00	0.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEM COMPONENTS. REINSTALL ALL PARTS REMOVED	IENT New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross L	abour Cost (S\$)	2,422.00	1,242.00
	Report was unsubmitted during this prin	t-out		

< END OF ESTIMATES >