

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20008454/AQF3E2

**Date:** 20/01/2021

### REFERENCE

Insured/Claimant:	LI YUANFANG	Policy No:	1800143196-01		
Date of Loss:	05/08/2020	Nature of Claim:	OD	Claim No:	5447287134SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF9486L		
Make & Model:	AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZB22242
Reg. Date:	29/11/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V6KA008776
Colour:	White	Odometer:	34481 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$93,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,673.00	2,050.88	4,622.12	69.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,932.00	2,002.00	5,930.00	74.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,605.00</b>	<b>4,052.88</b>	<b>10,552.12</b>	<b>72.25</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>14,005.00</b>	<b>3,452.88</b>	<b>10,552.12</b>	<b>75.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>980.35</b>	<b>241.70</b>	<b>738.65</b>	<b>75.35</b>
<b>Nett Amount (S\$)</b>	<b>14,985.35</b>	<b>3,694.58</b>	<b>11,290.77</b>	<b>75.35</b>

### INSPECTION

Date of Assignment:	14/08/2020		
Date Inspected:	13/08/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

*any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,847.00 FS	*1,477.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*- FS
3	2		*REAR BUMPER LOCKING MECHANISM - LH / RH	Not Necessary	28.00 FS	*- FS
4	2		*WHEEL HOUSING LINER ADAPTER - LH / RH	Not Necessary	37.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Not Necessary	234.00 FS	*- FS
6	1		*REAR LIGHT REFLECTOR - LH	Not Necessary	30.00 FS	*- FS
7	1		*LED TAIL LIGHT - LH	Not Necessary	867.00 FS	*- FS
8	1		*REAR BUMPER SIDE REINFORCEMENT BEAM	Bent	565.00 FS	*451.60 FS
9	1		*REAR BUMPER BRACKET - LH	Not Necessary	27.00 FS	*- FS
10	1		*REAR BUMPER BRACKET - RH	Not Necessary	28.00 FS	*- FS
11	1		*REAR BUMPER GUIDE SECTION - LH	Cracked	66.00 FS	*52.40 FS
12	2		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	-	-
13	1		*CROSS PANEL REINFORCEMENT	Not Necessary	725.00 FS	*- FS
14	1		*REAR CROSS PANEL	Not Necessary	242.00 FS	*- FS
15	1		*REAR SILENCER	Not Necessary	615.00 FS	*- FS
16	1		*REAR SILENCER DUAL CLIP	Not Necessary	57.00 FS	*- FS
17	2		*EXHAUST SYSTEM RETAINER	Not Necessary	79.00 FS	*- FS
18	1		*AUDI EMBLEM	Not Necessary	122.00 FS	*- FS
19	1		*A3 INSCRIPTION	Not Necessary	95.00 FS	*- FS
20	1		*PACKING ADHESIVE	Not Necessary	18.00 FS	*- FS
21	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
22	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
23	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
24	1		*SUNDRIES	Necessary	300.00 FS	*69.28 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,673.00	2,050.88
-------------------	----------	----------

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To remove and transfer rear parking aid. Check function and renew according to damage.	New	280.00	280.00
2	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio components.	New	480.00	480.00
3	To dismantle and renew rear bumper. To cut out and reweld rear end panelling outer and inner. Reorganise crash management components. Reinstall all parts removed.	New	3,500.00	500.00
4	To respray rear bumper, lhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment.	New	3,000.00	550.00
5	To renew lhs rear exhaust silencer. To align to psition.	New	480.00	0.00
6	To carry out diagnostic check.	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,932.00</b>	<b>2,002.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >