

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

CS/CT120008456/ugf3

ASSIGNMENT

From: Date:
Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMS2186C
at Workshop m/s IMPERUM

of
Insured:
Policy No. DMPCSN14290919099

Claims No. SNM20D202865C02

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$82k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted: Dep/KSUO

Date / Time Action / Instruction

2/9/20 have video. N/A 65999
2/9/20 2/s \$4000 confirmed with Shawn (Red \$10159.72, 72%)
03/09/20@12.46pm revised to Pauline Tham via Merimen.

Veh No: SMS2186C Yr Regn: 12-14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: mer Benz E200 c.c 1991

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 55732 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2120342B 089069

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim STD A/Rim or

Tyre Size: F: 245/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 13/8/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)03/09 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format : MER-TP

Lump Sum \$4000 (\$ 4000)

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 Synergy @ KB

Singapore 417800

TEL.NO: 97489940 / FAX NO. 63467213

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Vehicle No: SMS 2186 E

Model: Mercedes Benz E200

Qty List Items

Unit Price Total Price

1	pc Rear Bumper	Ref to 11	1671.00	\$	1,671.00	X
1	pc Rear Bumper Chrome strip	11	174.00	\$	174.00	X
2	pc Rear Bumper Side strip	11	85.00	\$	170.00	X
2	pc Rear Bumper Sensor - Outer	11	193.00	\$	386.00	X
2	pc Rear Bumper Sensor - Inner	11	193.00	\$	386.00	X
4	pc Rear Bumper Sensor Holder	11	48.00	\$	192.00	X
4	pc Rear Bumper Sensor Seal	11	14.00	\$	56.00	X
1	pc Rear Bumper centre support	11	212.00	\$	212.00	X
1	pc Rear Bumper Beam	11	790.00	\$	790.00	X
1	pc Rear Bumper Lower guide	11	147.00	\$	147.00	X
1	pc Rear Bumper Side Support	11	137.40	\$	137.40	X
2	pc Rear Bumper Lower Bracket	11	38.00	\$	76.00	X
1	pc Rear bumper tow cover	11	37.00	\$	37.00	X
1	2 pc Rear bumper lower Diffuser	11	503.00	\$	503.00	X
1	pc Rear bumper lower Diffuser Chrome	11	351.00	\$	351.00	X
1	pc Tail lamp	11	698.00	\$	698.00	X
2	pc Rear Bumper Exhaust End Chrome	11	383.00	\$	766.00	X
2	pc Rear Bumper Exhaust Chrome Bracket	11	87.00	\$	174.00	X
1	pc Bootlid	11	2710.00	\$	2,710.00	X
1	pc Bootlid LOGO	11	54.00	\$	54.00	X
1	pc Bootlid Emblem E200	11	78.00	\$	78.00	X
1	pc Bootlid Emblem 9G-TRONIC	11	85.20	\$	85.20	X
1	pc Bootlid Lamp	11	443.00	\$	443.00	X
1	pc Bootlid Rubber Seal	11	85.20	\$	85.20	X
1	pc Bootlid Lock	11	286.00	\$	286.00	X
1	pc Bootlid Lock Catch	11	47.00	\$	47.00	X
1	pc Rear Lamp Panel	11	1229.00	\$	1,229.00	X
1	pc Exhaust Muffler	11	1267.00	\$	1,267.00	X
				\$	13,210.80	
		Less 10%		\$	1,321.08	
	Special nett item			\$	11,889.72	
1	Sundry	11		\$	60.00	X
				\$	11,949.72	

Labour

1	To remove and replaced damaged parts.	\$	1,000.00	500
2	Spray painting.	\$	750.00	500
3	To carry out anti rust treatment.	\$	100.00	X
4	Check wiring	\$	80.00	20
5	To install reverse sensor	\$	80.00	50
6	To carry out diagnostic test and reset fault.	\$	200.00	50
	Total	\$	2,210.00	

Total Parts and Labour Cost of Repair

\$ 14,159.72

1/5 4000 3dps.

P-4322
102
38898
50098