

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 5670G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	GRAZED / TORN	1,840.85	1,840.85
1	FRONT BUMPER RETAINER LH	SERVICEABLE	37.75	-
1	FRONT BUMPER PARKING SENSOR LH	SERVICEABLE	271.68	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	1,007.77	-
1	HEADLAMP LH	MTG BROKEN	2,105.12	2,105.12
	LESS 10% DISCOUNT		-526.32	-394.60
			4,736.85	3,551.37
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	52.00	52.00
			52.00	52.00
	<u>LABOUR</u>			
	LABOUR TO REPAIR & REPLACE ABOVE ITEMS. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		750.00	400.00
	SPRAY PAINTING ON FRONT PORTION.		600.00	400.00
	CHECK WIRING & REFOCUS HEADLAMP.		50.00	20.00
	TO REMOVE & REFIT FRONT PARKING SENSOR.		80.00	40.00
	TO DIAGNOSE & RESET SYSTEM AFTER REPAIR.	NOT NECESSARY	300.00	-
	SPRAY TUFF KOTE.	NOT NECESSARY	80.00	-
			1,860.00	860.00
	GRAND TOTAL		6,648.85	4,463.37
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,550.00

Report Ref No. CS3/III20000310/Gtf3e2-1

XING GUO QIANG**M.MATAI, AMSAE-A****Automotive Assessor****ADRIAN LING WAI PING****B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.