

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20008468/QEA3Q2**Date:** 28/01/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100458952
Claimant Vehicle No :	SHB5322H	Insured Vehicle No :	GBE7857Z
Date of Loss:	09/08/2020	Nature of Claim:	TP
		Claim No:	0873936816SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5322H		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2G36007
Reg. Date:	26/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU503090761
Colour:	Maroon	Odometer:	15627 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,821.94	160.95	8,660.99	98.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,488.00	800.00	2,688.00	77.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	12,309.94	960.95	11,348.99	92.19
+ Loss of Use (3.0 x S\$50.00/day) (\$\$)		150.00		
+ Car Rental (3.0 x S\$117.17/day) (\$\$)		351.51		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		1,469.46		

INSPECTION

Date of Assignment:	12/08/2020	
Date Inspected:	12/08/2020	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	Necessary	54.60 F	*40.95 F
2	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
3	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
4	1		*COVER ,RR BUMPER	Serviceable	521.00 F	*- F
5	1		*SUPPORT FR BUMPER LH	Serviceable	82.30 F	*- F
6	1		*LINER ,FR FENDER ,LH	Serviceable	210.30 F	*- F
7	1		*WHEEL ,DISC FRONT	Serviceable	1,879.40 F	*- F
8	1		*CAP SUB-ASSY ,WHEEL	Serviceable	211.50 F	*- F
9	1		*TYRE	Serviceable	126.74 F	*- F
10	1		*MOULDING ASSY,BODY ROCKER PANEL ,LH	Serviceable	594.80 F	*- F
11	1		*MIRROR ASSY ,OUTER REAR VIEW ,LH	Serviceable	1,339.30 F	*- F
12	1		*COVER ,OUTER MIRROR, LH	Serviceable	108.60 F	*- F
13	1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Serviceable	1,294.90 F	*- F
14	1		*PANEL SUB-ASSY ,FRONT DOOR LH	Repair	1,300.70 F	*- F
15	1		*FENDER SUB-ASSY,FR LH	Repair	977.80 F	*- F

F=Franchise part.

Total Parts (S\$)**8,821.94****160.95**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	2,232.00	600.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			3,488.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >