

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20008468/QEA3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100458952

Claimant
Vehicle No : SHB5322H **Insured Vehicle No :** GBE7857Z

Date of Loss: 09/08/2020 Nature of Claim: TP Claim No: 0873936816SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-------------------------------------|-------------|-------------------|
| Reg No: | SHB5322H | | |
| Make & Model: | TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) | Engine No: | 2ZR2G36007 |
| Reg. Date: | 26/12/2019 (Man. Year: 2019) | Chassis No: | JTDKB3FU503090761 |
| Colour: | Maroon | Odometer: | 15627 km |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Dunlop 6 mm | Rear Left Side: | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 8,821.94 | 160.95 | 8,660.99 | 98.18 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,488.00 | 800.00 | 2,688.00 | 77.06 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 12,309.94 | 960.95 | 11,348.99 | 92.19 |
| + Loss of Use (3.0 x S\$50.00/day) (S\$) | | 150.00 | | |
| + Car Rental (3.0 x S\$117.17/day) (S\$) | | 351.51 | | |
| + Doc/Search Fee (S\$) | | 7.00 | | |
| Nett Liability (S\$) | | 1,469.46 | | |

INSPECTION

Date of Assignment: 12/08/2020

Date Inspected: 12/08/2020 Inspected At: SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---------------------------|-----|----------|---|-------------|-----------------|---------------|
| 1 | 1 | | *EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%) | Necessary | 54.60 F | *40.95 F |
| 2 | 1 | | *STICKER DECAL SMRT (DOOR) (SN) | Necessary | 60.00 F | *60.00 F |
| 3 | 1 | | *PIXEL STICKER (SN) | Necessary | 60.00 F | *60.00 F |
| 4 | 1 | | *COVER ,RR BUMPER | Serviceable | 521.00 F | *- F |
| 5 | 1 | | *SUPPORT FR BUMPER LH | Serviceable | 82.30 F | *- F |
| 6 | 1 | | *LINER ,FR FENDER ,LH | Serviceable | 210.30 F | *- F |
| 7 | 1 | | *WHEEL ,DISC FRONT | Serviceable | 1,879.40 F | *- F |
| 8 | 1 | | *CAP SUB-ASSY ,WHEEL | Serviceable | 211.50 F | *- F |
| 9 | 1 | | *TYRE | Serviceable | 126.74 F | *- F |
| 10 | 1 | | *MOULDING ASSY,BODY ROCKER PANEL ,LH | Serviceable | 594.80 F | *- F |
| 11 | 1 | | *MIRROR ASSY ,OUTER REAR VIEW ,LH | Serviceable | 1,339.30 F | *- F |
| 12 | 1 | | *COVER ,OUTER MIRROR, LH | Serviceable | 108.60 F | *- F |
| 13 | 1 | | *PANEL SUB-ASSY ,REAR DOOR ,LH | Serviceable | 1,294.90 F | *- F |
| 14 | 1 | | *PANEL SUB-ASSY ,FRONT DOOR LH | Repair | 1,300.70 F | *- F |
| 15 | 1 | | *FENDER SUB-ASSY,FR LH | Repair | 977.80 F | *- F |
| F=Franchise part. | | | | | | |
| Total Parts (\$\$) | | | | | 8,821.94 | 160.95 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | PANEL BEATING & BODY WORK | New | 676.00 | 200.00 |
| 2 | SPRAY PAINT | New | 2,232.00 | 600.00 |
| 3 | TO CHECK WIRING AND SYSTEM FUNCTION | New | 80.00 | 0.00 |
| 4 | TO APPLY RUST-PROOFING ON AFFECTED AREA | New | 100.00 | 0.00 |
| 5 | TO DO WHEEL ALIGNMENT /TYRE BALANCING | New | 120.00 | 0.00 |
| 6 | TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | New | 120.00 | 0.00 |
| 7 | TO REPLACE SUNDRY PARTS | New | 100.00 | 0.00 |
| 8 | TO WASH AND VACUUM | New | 60.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 3,488.00 | 800.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >