



Case Details

Case Reference Number : TAX/08/20/2022
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5322H

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-12289-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 09/08/2020 07:45 AM
 Vehicle Age(In Months) : 8

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	521.00	521.00	25.00	390.75	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	977.80	977.80	25.00	733.35	Replace	1	0	Repair	✓ X R
One Time Key In	Main			LINER, FR FENDER, LH	1	210.30	210.30	25.00	157.73	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	54.60	54.60	25.00	40.95	Replace	1	40.95	Replace	✓ / Nec
One Time Key In	Main			WHEEL, DISC FRONT	1	1,879.40	1,879.40	25.00	1,409.55	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			CAP SUB- ASSY, WHEEL	1	211.50	211.50	25.00	158.63	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , LH	1	594.80	594.80	25.00	446.10	Replace	0	0	Not Give	✓ X Svc

Total Spare Part Cost 6,879.05

Surveyor Total 160.95

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,879.05

Final Sur Total 160.95

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,300.70	1,300.70	25.00	975.53	Replace	1	0	Repair	✓ X R
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ / Nec
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , LH	1	1,339.30	1,339.30	10.00	1,205.37	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	108.60	108.60	25.00	81.45	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , LH	1	1,294.90	1,294.90	25.00	971.18	Replace	1	0	Repair	✓ X Svc
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ X Svc ✓ NEC

Total Spare Part Cost 6,879.05

Surveyor Total 160.95

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,879.05

Final Sur Total 160.95

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	676.00	200	✓
Total:			676.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	0	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	✓
3	Main	RESPRAY WHEEL CAP	180.00	0	
4	Main	TO RESPRAY RIM	180.00	0	
5	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
Total:			2,232.00	800.00	

12/08/2020

<https://vacsweb.smr.com.sg/Estimation.aspx>

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
7	Main	TO RESRAY REAR DOOR LH	378.00	200	
8	Main	TO RESPRAY VIEW MIRROR	180.00	0	
Total:			2,232.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			580.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,879.05	160.95
Total Labour Cost	0.00	200.00
Total Spray Painting	0.00	600.00
Other	0.00	0.00
Overall Total	6,879.05	960.95
Lump Sum Repair Option		☐
Lump Sum Total	0.00	960.95
Surveyor Approved Amount		960.95
No of Repair Days*	5	2
Remarks	-	2 days P/P, before paint photo

12/08/2020

https://vacswbo.smr.com.sg/Estimation.aspx

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

Sun Pin (LKK)

Signature



Save Clear

Survey Date

12/08/2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: