Adjuster Report Page 1 of 5

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20008470/KDA3Q2

M9R8839C002255

**Date:** 06/11/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100502229

Claimant Vehicle No: SHC5631K Insured Vehicle No: SLL4991H

Date of Loss: 12/08/2020 Nature of Claim: TP Claim No: 9889983844SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC5631K

Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR Engine No:

(A)

Reg. Date: 19/11/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC280317

Colour: Metallic White/Red Odometer: 518204 km

Engine Capacity: 1995 cc
Market Value/New Car
N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Sailun 9 mm Rear Left Side: Sailun 9 mm
Front Right Side: Sailun 9 mm
Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,630.67	6,127.72	7,502.95	55.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,230.00	1,620.00	4,610.00	74.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,860.67	7,747.72	12,112.95	60.99
Approved Total (Overridden) (S\$)	6,200.00			
(S\$)	19,860.67	6,200.00	13,660.67	68.78
+ GST 7.00/7.00% (S\$)	1,390.25	434.00	956.25	68.78
Nett Amount (S\$)	21,250.92	6,634.00	14,616.92	68.78
+ Loss of Use (6.0 x S\$	50.00/day) (S\$)	300.00		
+ Car Rental (6.0 x S\$71.13/day) (S\$)		426.78		
+ Doc/S	+ Doc/Search Fee (S\$)			
Ne	tt Liability (S\$)	7,368.27		
Global Sum Settlement (S\$)		7,360.00		

**INSPECTION** 

Date of Assignment: 13/08/2020

Date Inspected: 13/08/2020 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

Adjuster Report Page 2 of 5

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Bent	561.70 FL	*561.70 FL
2	1	*BUMPER LOWER REAR	Distorted / Bent	411.90 FL	*411.90 FL
3	1	*BUMPER BRACKET CTR REAR	Cracked	98.10 FL	*98.10 FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1	*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR	Distorted	80.80 FL	*80.80 FL
8	1	*BUMPER RETAINER LH REAR	Distorted	54.20 FL	*54.20 FL
9	1	*BUMPER REFLECTOR LH	Cracked	16.60 FL	*16.60 FL
10	1	*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Bent	114.50 FL	*114.50 FL
12	1	*BUMPER BEAM BRACKET EH REAR	Distorted	114.50 FL	*114.50 FL
13	•				
	1	*BUMPER BLOCK LH REAR	Serviceable	76.50 FL	*- FL
14	1	*BUMPER BLOCK RH REAR	Serviceable	76.50 FL	*-FL
15	1	*BOOT REAR	Bent	1,677.20 FL	
16	1	*BOOT FINISHER	Serviceable	344.70 FL	*- FL
17	1	*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
18	1	*BOOT REFLECTOR LAMP LH	Cracked	277.70 FL	*277.70 FL
19	1	*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
20	1	*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
21	1	*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
22	1	*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
23	1	*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
24	1	*BOOT HINGE LH	Repair	254.20 FL	*- FL
25	1	*BOOT HINGE RH	Repair	254.20 FL	*-FL
26	1	*BOOT LOCK	Repair	246.60 FL	*- FL
27	2	*BOOT RUBBER PLUG	Serviceable	139.30 FL	*- FL
21 28	1	*BOOT SWITCH	Serviceable	113.00 FL	*- FL
20 29	2				*- FL
		*LICENCE PLATE LAMP	Serviceable	26.30 FL	
30	1	*TAILLAMP RH	Cracked	401.40 FL	*401.40 FL
31	1	*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
32	1	*TAILLAMP LH	Mtg Cracked	401.40 FL	*401.40 FL
33	1	*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
34	1	*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
35	1	*OUTER PANEL REAR (END PANEL)TRIM	Cracked	404.56 FL	*404.56 FL
36	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	1,229.40 FL	*-FL
37	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
38	1	*SPARE TYRE BOARD	Serviceable	680.90 FL	*- FL
39	1	*EXHAUST CAP REAR	Serviceable	125.40 FL	*- FL
40	1	*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
41	1	*SET REAR BUMPER CLIP	Necessary	75.00 FS	*75.00 FS
42	1	*SET BUMPER BRACKET CTR CLIP	Not Necessary	55.00 FS	*-FS
43	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	60.00 FS	*- FS
44	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	65.00 FS	*-FS
45	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	60.00 FS	*-FS
45 46	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	65.00 FS	- FS *- FS
47 40	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	65.00 FS	*- FS
48	1	*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	*75.00 FS
49	2	*SEAM SEALANT	Not Necessary	180.00 FS	*- FS
50	1	*SET BOOT FINISHER CLIP	Not Necessary	55.00 FS	*-FS
51	1	*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
52	1	*BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
53	1	*BOOT TRIM BOARD CLIP	Not Necessary	60.00 FS	*-FS
		Report was unsubmitted during this pri			

Adjuster Report Page 4 of 5

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
54	1	*RENAULT TYRE RIM (ROUE 7J 16H)	Serviceable	385.00 FS	*- FS
55	1	*RENAULT TYRE 215/60/16	Serviceable	330.00 FS	*- FS
56	1	*TAILLAMP CLIP RH	Necessary	40.00 FS	*5.00 FS
57	1	*TAILLAMP CLIP LH	Necessary	40.00 FS	*5.00 FS
58	1	*REAR BUMPER PROTECTOR	Necessary	190.00 FS	*30.00 FS
59	1	*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	140.00 FS	*- FS
60	1	*SET REAR END PANEL TRIM CLIP	Not Necessary	55.00 FS	*-FS
F=Fra	nchise	part. S=SpcNett. L=ListItemDisc.			
			Sub Total (S\$)	14,827.97	6,736.36
- List Item Discount on L Items 10.00/10.00% (S\$)			1,197.30	608.64	
			Total Parts (S\$)	13,630.67	6,127.72

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST }	New	380.00	60.00
2	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST }	New	380.00	0.00
3	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
4	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	E New	1,800.00	700.00
6	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO RUST PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	60.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	660.00
9	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New D	380.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
	Gross Labour Cost (S\$)		6,230.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >