

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20008480/KGA3Q2

Date: 05/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SHD419K **Insured Vehicle No :** SMM4454A

Date of Loss: 08/08/2020 **Nature of Claim:** TP **Claim No:** 1327504685SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD419K
Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) **Engine No:** M9R8839C003333
Reg. Date: 09/12/2016 (Man. Year: 2016) **Chassis No:** VF1ABL15AUC283417
Colour: Metallic White/Red **Odometer:** 571556 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/60R16 **Rear Tyre Size:** 215/60R16
Front Left Side: Sailun 8 mm **Rear Left Side:** Sailun 8 mm
Front Right Side: Sailun 8 mm **Rear Right Side:** Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,407.33	2,139.64	5,267.69	71.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,690.00	910.00	4,780.00	84.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,097.33	3,049.64	10,047.69	76.72
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	13,097.33	2,450.00	10,647.33	81.29
+ GST 7.00/7.00% (S\$)	916.81	171.50	745.31	81.29
Nett Amount (S\$)	14,014.14	2,621.50	11,392.64	81.29
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$99.13/day) (S\$)		247.83		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,001.78		
Global Sum Settlement (S\$)		2,950.00		

INSPECTION

Date of Assignment: 12/08/2020

Date Inspected: 12/08/2020 **Inspected At:**

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented/Cut	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR REAR	Serviceable	16.60 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
10	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
11	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
12	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
14	1		*TAIL-LAMP	Serviceable	401.40 FL	*- FL
15	1		*BOOT REAR	Repair	1,677.20 FL	*- FL
16	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
17	1		*BOOT REFLECTOR LAMP	Serviceable	277.70 FL	*- FL
18	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
19	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
20	1		*BOOT HINGE	Repair	254.20 FL	*- FL
21	1		*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
22	1		*SET REAR BUMPER CLIP	Necessary	75.00 FS	*75.00 FS
23	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	55.00 FS	*- FS
24	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	60.00 FS	*- FS
25	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	65.00 FS	*- FS
26	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	60.00 FS	*- FS
27	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	65.00 FS	*- FS
28	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	69.00 FS	*- FS
29	1		*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	*75.00 FS
30	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
31	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
32	1		*TAILLAMP CLIP	Not Necessary	45.00 FS	*- FS
33	1		*REAR BUMPER PROTECTOR	No such part	170.00 FS	*- FS
34	1		*REAR LICENCE PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
35	1		*REAR END PANEL TRIM CLIP	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,033.26	2,309.60
- List Item Discount on L Items 10.00/10.00% (\$)	625.93	169.96
Total Parts (\$)	7,407.33	2,139.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
4	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	2,000.00	400.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,000.00	440.00
Gross Labour Cost (\$)			5,690.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >