

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20008508/R1CF3Q2**Date:** 08/03/2021**REFERENCE**

Insured/Claimant: ANG YOKE PHENG Policy No: 1800115567
Date of Loss: 14/08/2020 Nature of Claim: OD Claim No: 0198791291SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDS5525Y**
Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Engine No: CHZA90358
Reg. Date: 28/09/2018 (Man. Year: 2018) Chassis No: WAUZZZGA5KA000621
Colour: Grey Odometer: 13198 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$94,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,087.00	4,721.92	15,365.08	76.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,872.00	4,672.00	4,200.00	47.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,959.00	9,393.92	19,565.08	67.56
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	28,559.00	8,993.92	19,565.08	68.51
+ GST 7.00/7.00% (S\$)	1,999.13	629.57	1,369.56	68.51
Nett Amount (S\$)	30,558.13	9,623.49	20,934.64	68.51

INSPECTION

Date of Assignment: 17/08/2020

Date Inspected: 17/08/2020 Inspected At:

281,ALEXANDRA ROAD
Repairer:Premium Automobiles Pte
Ltd (UBI)

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,854.00 FS	*1,482.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	343.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE-CENTRE	Serviceable	195.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	N/s Scratched/O/s Serviceable	334.00 FS	*133.60 FS
5	2		*FRONT BUMPER END CAP-LH/RH	Serviceable	68.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Deformed	296.00 FS	*236.40 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Serviceable	154.00 FS	*- FS
8	2		*FRONT WHEEL SPOILER-LH/RH	Serviceable	68.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,395.00 FS	*1,116.00 FS
10	1		*RADIATOR GRILLE STRIKER PLATE	Serviceable	123.00 FS	*- FS
11	1		*FRONT BUMPER CARRIER	Serviceable	679.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	77.00 FS	*61.20 FS
13	1		*FOAM FILLER PIECE COVER	Serviceable	99.00 FS	*- FS
14	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Serviceable	70.00 FS	*- FS
15	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
17	2		*WHEEL HOUSING LINER-LH/RH	Serviceable	388.00 FS	*- FS
18	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	57.00 FS	*- FS
19	2		*HEADLIGHT MOUNTING-LH/RH	Serviceable	234.00 FS	*- FS
20	2		*LED HEADLIGHT-LH/RH	Serviceable	9,718.00 FS	*- FS
21	2		*LIFT CYLINDER-LH/RH	Serviceable	282.00 FS	*- FS
22	1		*LIFT CYLINDER HOSE	Serviceable	175.00 FS	*- FS
23	1		*LOCK CARRIER	Serviceable	983.00 FS	*- FS
24	1		*AIRCON CONDENSER	Bent	545.00 FS	*436.00 FS
25	1		*EXTERNAL TEMPERATURE SENSOR	Serviceable	56.00 FS	*- FS
26	1		*READY MIX COOLANT	Necessary	177.00 FS	*141.44 FS
27	1		*RADIATOR AIR GUIDE-LH/RH (2 Pcs)	Cracked	60.00 FS	*23.92 FS
28	1		*RADIATOR AIR GUIDE-UPPER CENTRE	Cracked	22.00 FS	*17.04 FS
29	2		*FRONT WHEEL COVER-LH/RH	Necessary	636.00 FS	*508.80 FS
30	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
31	1		*SUNDRIES	Necessary	300.00 FS	*11.92 FS
32	1		*REAR BUMPER LOWER SPOILER	Scratched	281.00 FS	*224.80 FS
33	1		*REAR WHEEL ARCH TRIM LHS	Necessary	168.00 FS	*134.40 FS
34	1		*REAR WHEEL ARCH TRIM RHS	Necessary	168.00 FS	*134.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 20,087.00 4,721.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES	New	800.00	0.00
3	TO REMOVE AND RENEW AIRCON CONDENSER,ADDITIONAL RADIATOR AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,000.00	1,750.00
5	TO RESPRAY FRONT BUMPER	New	1,200.00	550.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE AND REINSTALL REAR BUMPER }	New	1,000.00	500.00
8	TO RENEW REAR BUMPER LOWER SPOILER }	New	-	-
Gross Labour Cost (\$\$)			8,872.00	4,672.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >