LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd

64 Cecil Street #04-00 IOB Building Singapore 049711 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 17 Aug 2020

Preliminary Advice

Vehicle No: GBK1914AAccident Date: 11/08/2020Make: TOYOTA HIACEPolicy No.: D19MFL0005549

Assignment Date : 17/08/2020 Excess : \$\$0.00 Date of Inspection : 14/08/2020 Est. Duration of Repair : 20

Inspection At : EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD (HQ)

56 LOYANG WAY #06-07, LOYANG ENTERPRISE BUILDING

SINGAPORE 508775

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front RH, rear RH portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,362.00
Revised Amount	:S\$	16,192.00
Check Items (Estimated)	:S\$	1,111.50
Total	:S\$	17,303.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 63,000.00 COE / PARF Rebate :S\$ 23.670.00

Salvage Value :S\$

Margin for Repair :S\$ 39,330.00

Remarks

(x)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage
		Kindly let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments: Repair on part by part