

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20008515/AQF3Q2

**Date:** 02/11/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18404419011
<b>Claimant Vehicle No :</b>	SLW7422G	<b>Insured Vehicle No :</b>	GY234C
Date of Loss:	13/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D202878/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW7422G	Engine No:	G4FGJH694990
Make & Model:	KIA CERATO K3, 1.6 SUNROOF (A)	Chassis No:	KNAFZ411MJ5764750
Reg. Date:	28/02/2018 (Man. Year: 2017)	Odometer:	36305 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,340.04	10,239.62	3,100.42	23.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,910.00	2,700.00	3,210.00	54.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>19,250.04</b>	<b>12,939.62</b>	<b>6,310.42</b>	<b>32.78</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>10,300.00</b>		
<b>(\$\$)</b>	19,250.04	10,300.00	8,950.04	46.49
<b>+ GST 7.00/7.00% (\$\$)</b>	1,347.50	721.00	626.50	46.49
<b>Nett Amount (\$\$)</b>	<b>20,597.54</b>	<b>11,021.00</b>	<b>9,576.54</b>	<b>46.49</b>

### INSPECTION

Date of Assignment:	17/08/2020	
Date Inspected:	17/08/2020 Inspected At:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre Singapore 415933
Estimated Period of Repair:	9.0 days	

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2020)
<b>Parts:</b>	143	KIA CERATO K3 1.6 SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW7422G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,297.90 FL	*1,297.90 FL
2	1		*REAR BOOT LID SPOILER (STICKER ON)	Deformed	590.70 FL	*590.70 FL
3	1		*REAR BOOT LID LOGO EMBLEM	Necessary	32.50 FL	*32.50 FL
4	1		*REAR BOOT LID CERATO EMBLEM	Necessary	31.70 FL	*31.70 FL
5	1		*REAR BOOT LID K3 EMBLEM	Necessary	38.40 FL	*38.40 FL
6	2		*REAR BOOT LID REFLECTOR LAMP LH/RH	Cracked	1,421.60 FL	*1,421.60 FL
7	1		*REAR BOOT LID OUTER LOCK HANDLE SWITCH	Damaged	75.20 FL	*75.20 FL
8	2		*REAR BOOT LID NUMBER PLATE LAMP LH/RH	Cracked	66.80 FL	*66.80 FL
9	1		*REAR BOOT LID REVERSE CAMERA ORIGINAL	Damaged	690.90 FL	*690.90 FL
10	2		*REAR BOOT LID HINGE LH/RH	Bent	132.40 FL	*132.40 FL
11	1		*REAR BOOT LID INNER UPHOLSTERY TRIM	Not Necessary	85.10 FL	*- FL
12	1		*REAR BOOT LID INNER HANDLE	Not Necessary	18.20 FL	*- FL
13	1		*REAR BOOT LID MECHANISM LOCK	Damaged	109.70 FL	*109.70 FL
14	4		*REAR BOOT LID RUBBER GUIDE STOPPER	Not Necessary	33.60 FL	*- FL
15	2		*REAR TAILLAMP LH/RH	Cracked	1,709.80 FL	*1,709.80 FL
16	2		*REAR TAILLAMP INNER PANEL LH/RH	Repair	279.20 FL	*- FL
17	1		*REAR BUMPER	Distorted	688.90 FL	*688.90 FL
18	1		*REAR BUMPER LOWER LIP ORIGINAL	Distorted	800.70 FL	*800.70 FL
19	1		*REAR BUMPER LOWER DIFFUSER	Distorted	347.50 FL	*347.50 FL
20	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	709.20 FL	*354.60 FL
21	4		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	48.40 FL	*48.40 FL
22	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	74.80 FL	*74.80 FL
23	1		*SET REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	279.40 FL	*- FL
24	1		*REAR BUMPER REFLECTOR LH /RH	O/S Cracked	66.20 FL	*33.10 FL
25	1		*REAR BUMPER REINFORCEMENT	Cracked	313.90 FL	*313.90 FL
26	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	Bent	139.40 FL	*139.40 FL
27	2		*REAR BUMPER TOP BRACKET LH/RH	Damaged	37.00 FL	*37.00 FL
28	4		*REAR BUMPER LOWER BRACKET	Damaged	74.00 FL	*74.00 FL
29	2		*REAR BUMPER SIDE ETAINER LH/RH	Necessary	57.20 FL	*57.20 FL
30	1		*REAR BUMPER INNER BOOT LID ANTENNA SENSOR	Not Necessary	185.30 FL	*- FL
31	1		*REAR END PANEL	Dented	324.80 FL	*324.80 FL
32	1		*REAR END PANEL INNER TOP GARNISH	Deformed	102.40 FL	*102.40 FL
33	1		*REAR END PANEL INNER BOOT LID ANTENNA SENSOR	Cracked	185.30 FL	*185.30 FL
34	1		*SPARE TYRE PANEL	Repair	607.30 FL	*- FL
35	1		*SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	Deformed	179.40 FL	*179.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR SUB CHASSIS FRAME RH	Repair	893.40 FL	*- FL
37	1		*REAR EXHAUST SILENCER BOX	Bent	757.80 FL	*757.80 FL
38	3		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	114.60 FL	*- FL
39	1		*REAR FENDER INNER TRIM RH	Torn	255.00 FL	*255.00 FL
40	1		*SET REAR BOOT LID NUMBER PLATE WITH CASING	Not Necessary	65.00 FS	*- FS
41	1		*SET REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS	Not Necessary	60.00 FS	*- FS
42	2		*REAR TAILLAMP CLIPS SET LH/RH	Necessary	80.00 FS	*20.00 FS
43	2		*REAR TAILLAMP INNER PANEL SEALANT LH/RH	Not Necessary	100.00 FS	*- FS
44	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
45	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
46	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*10.00 FS
47	1		*SPARE TYRE PANEL INSULATOR MAT	Necessary	220.00 FS	*200.00 FS
48	1		*REAR SUB CHASSIS FRAME SEALANT RH	Not Necessary	80.00 FS	*- FS
49	1		*REAR EXHAUST GASKET	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 14,725.60 11,336.80**  
**- List Item Discount on L Items 10.00/10.00% (\$\$) 1,385.56 1,097.18**

**Total Parts (\$\$) 13,340.04 10,239.62**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,800.00	1,000.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,600.00	1,300.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	100.00	60.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	New	380.00	0.00
6	TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	New	250.00	0.00
7	TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	New	280.00	80.00
8	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	80.00	50.00
9	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	350.00	100.00
10	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH/RH TO PERFORM FACILITATE REPAIRS	New	280.00	0.00
11	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	100.00	0.00
12	TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	New	250.00	0.00
13	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	80.00
14	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,910.00</b>	<b>2,700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >