

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008516/EPS3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMH7056Y	Insured Vehicle No :	SHC2905R
Date of Loss: 02/08/2020	Nature of Claim: TP	Claim No: MCT20080019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH7056Y		
Make & Model:	HONDA FIT, 1.3 (A)	Engine No:	LEB1444661
Reg. Date:	30/01/2019 (Man. Year: 2018)	Chassis No:	GP51336960
Colour:	Black	Odometer:	78165 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Arivo 4 mm	Rear Left Side:	Arivo 4 mm
Front Right Side:	Arivo 4 mm	Rear Right Side:	Arivo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,622.96	1,678.56	944.40	36.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	460.00	3,170.00	87.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,252.96	2,138.56	4,114.40	65.80
Approved Total (Overridden) (\$\$)		1,700.00		
(\$\$)	6,252.96	1,700.00	4,552.96	72.81
+ GST 7.00/7.00% (\$\$)	437.71	119.00	318.71	72.81
Nett Amount (\$\$)	6,690.67	1,819.00	4,871.67	72.81
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	17/08/2020	
Date Inspected:	17/08/2020 Inspected At:	My Car Consultant Pte Ltd - Ubi (HQ)
		53 Ubi Ave 1, #01-33 Paya Ubi
		Industrial Park
		Singapore 408934
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2021)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH7056Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	698.00 FL	*698.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Broken	96.40 FL	*96.40 FL
3	1		*FRONT BUMPER SIDE GRILLE RH	Broken	167.30 FL	*167.30 FL
4	1		*FRONT BUMPER LOWER GRILLE CENTRE	Not Necessary	212.00 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	198.00 FL	*- FL
6	1		*FRONT GRILLE	Not Necessary	485.00 FL	*- FL
7	1		*FRONT GRILLE CHROME	Not Necessary	198.00 FL	*- FL
8	1		*HEADLAMP RH	Broken	987.00 FL	*987.00 FL
9	1		*HEADLAMP LOWER BRACKET RH	Broken	112.00 FL	*112.00 FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
11	1		*SET FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,253.70	2,090.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	630.74	412.14
Total Parts (\$\$)	2,622.96	1,678.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	200.00
2	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	200.00
3	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
4	REALIGN HEADLAMP	New	150.00	30.00
Gross Labour Cost (\$\$)			3,630.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >