

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008517/AES3Q2

Date: 24/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100442657

Claimant
Vehicle No : SLM3984E **Insured Vehicle No :** SBQ3348P

Date of Loss: 14/08/2020 Nature of Claim: TP Claim No: 3299344898SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM3984E		
Make & Model:	PERODUA BEZZA, 1.3 Premium (A)	Engine No:	1NR0A49567
Reg. Date:	29/03/2017 (Man. Year: 2017)	Chassis No:	PM2B301S003048120
Colour:	Bronze	Odometer:	5959 km
Engine Capacity:	1329 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,732.06	5,555.90	7,176.16	56.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,960.00	3,230.00	2,730.00	45.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,692.06	8,785.90	9,906.16	53.00
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	18,692.06	7,000.00	11,692.06	62.55
+ GST 7.00/7.00% (S\$)	1,308.44	490.00	818.44	62.55
Nett Amount (S\$)	20,000.50	7,490.00	12,510.50	62.55
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,192.00		

INSPECTION

Date of Assignment: 17/08/2020

Date Inspected: 17/08/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
[Autobay@Kaki Bukit](mailto:Autobay@KakiBukit)
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	980.00 F	*865.00 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	160.00 F	*- FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	75.00 F	*75.00 FL
4	1		*REAR BOOT LID BENZZA LOGO	Necessary	60.00 F	*60.00 FL
5	1		*REAR BOOT LID DUAL WT-I LOGO	Necessary	40.00 F	*40.00 FL
6	1		*REAR BOOT LID DUAL X LOGO	Necessary	40.00 F	*40.00 FL
7	1		*REAR BOOT LID REVERSE CAMERA	Not Necessary	380.00 F	*- FL
8	1		*REAR BOOT LID CENTER CHROME MOULDING	Not Necessary	220.06 F	*- FL
9	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
10	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	160.00 F	*- FL
11	1		*REAR BOOT LID LOCK	Damaged	240.00 F	*240.00 FL
12	1		*REAR BOOT LID WEATHERSTRIP	Not Necessary	120.00 F	*- FL
13	1		*REAR BOOT LID TRIM BOARD	Not Necessary	280.00 F	*- FL
14	16		*REAR BOOT LID TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
15	1		*REAR TAIL LAMP	O/S Cracked	900.00 F	*381.00 FL
16	4		*REAR TAIL LAMP CLIP	Necessary	26.00 F	*10.00 FL
17	2		*REAR TAIL LAMP LOWER BRACKET	Cracked	110.00 F	*55.00 FL
18	1		*REAR BUMPER	Distorted	650.00 F	*650.00 FL
19	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
20	2		*REAR BUMPER SIDE RETAINER	Necessary	90.00 F	*90.00 FL
21	1		*REAR BUMPER REINFORCEMENT	Not Necessary	400.00 F	*- FL
22	1		*REAR BUMPER LOWER LID SIDE REFLECTOR	O/S Cracked	220.00 F	*110.00 FL
23	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
24	1		*REAR END PANEL	Dented	450.00 F	*450.00 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	120.00 F	*120.00 FL
26	1		*REAR FENDER	O/S Buckled	2,100.00 F	*980.00 FL
27	1		*REAR FENDER COWLING	O/S Torn	170.00 F	*85.00 FL
28	1		*REAR FENDER COWLING CLIP (12 PCS)	Necessary	78.00 F	*10.00 FL
29	1		*REAR FENDER INNER TRIM BOARD	O/S Crumpled	760.00 F	*295.00 FL
30	1		*REAR FENDER INNER TRIM BOARD CLIP (16 PCS)	Necessary	104.00 F	*30.00 FL
31	1		*REAR SPARE TYRE PANEL	Repair	880.00 F	*- FL
32	1		*REAR SPARE TYRE PANEL TOP COVER	Torn	420.00 F	*265.00 FL
33	1		*REAR EXHAUST	Bent	590.00 F	*590.00 FL
34	1		*REAR CENTER EXHAUST	Not Necessary	780.00 F	*- FL
35	2		*REAR EXHAUST MOUNTING	Not Necessary	50.00 F	*- FL
36	1		*REAR SPARE TYRE SIDE PANEL RH	Distorted	285.00 F	*285.00 FL
37	1		*REAR TAILLAMP PANEL RH	Buckled	195.00 F	*195.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 12,732.06 6,151.00
- List Item Discount on L Items 0.00/10.00% (S\$) 0.00 595.10

Total Parts (S\$) 12,732.06 5,555.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	50.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	160.00	120.00
5	GUM	New	60.00	60.00
6	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	120.00
7	TO CHECK WIRING	New	100.00	30.00
8	TUFF KOTE	New	150.00	120.00
9	TOWING FEE	New	150.00	0.00
10	PANEL BEATING	New	2,400.00	1,400.00
11	SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (\$\$)			5,960.00	3,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >