

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008522/UES3Q2

Date: 02/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070016904

Claimant
Vehicle No : SLB7434H **Insured Vehicle No :** SFT7978G

Date of Loss: 13/08/2020 Nature of Claim: TP Claim No: 4614533790SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB7434H	Engine No:	G4FGGH612918
Make & Model:	KIA FORTE K3, 1.6 EX (A)	Chassis No:	KNAFX411MG5601757
Reg. Date:	21/04/2016 (Man. Year: 2016)	Odometer:	105261 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R16	Rear Tyre Size:	215/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,213.13	8,135.31	6,077.82	42.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	2,490.00	1,640.00	39.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,343.13	10,625.31	7,717.82	42.07
Approved Total (Overridden) (\$\$)		8,500.00		
Nett Amount (\$\$)	18,343.13	8,500.00	9,843.13	53.66
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 17/08/2020

Date Inspected: 17/08/2020 Inspected At:

Zoom Autowerks Pte Ltd
832 SIMS AVENUE #12-884
EUNOSVILLE
Singapore 400832

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	745.20 FL	*745.20 FL
2	1		*FRONT BUMPER FOG LAMP RH	Broken	255.20 FL	*255.20 FL
3	1		*FRONT BUMPER SPONGE	Torn	121.60 FL	*121.60 FL
4	1		*FRONT BUMPER FOG LAMP GARNISH RH	Distorted	175.80 FL	*175.80 FL
5	1		*FRONT BUMPER LOWER CENTRE GRILLE	Distorted	214.20 FL	*214.20 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	375.40 FL	*375.40 FL
7	1		*FRONT BUMPER RETAINER RH	Cracked	78.00 FL	*78.00 FL
8	1		*FRONT WIPER WASHER TANK	Distorted	62.00 FL	*62.00 FL
9	1		*FRONT WIPER WASHER TANK MOTOR	Distorted	290.00 FL	*290.00 FL
10	1		*FRONT BUMPER NUMBER PLATE GARNISH	Shorted	112.60 FL	*112.60 FL
11	1		*FRONT BUMPER LOGO	Necessary	104.20 FL	*104.20 FL
12	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
13	1		*FRONT FENDER RH	Distorted	786.50 FL	*786.50 FL
14	1		*FRONT FENDER INNER SHIELD RH	Torn	215.30 FL	*215.30 FL
15	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*60.00 FL
16	1		*FRONT FENDER BRACKET RH	Distorted	145.60 FL	*145.60 FL
17	1		*FRONT WHEEL HOUSE INNER PANEL RH (NPA)	Repair	0.00 FL	*- FL
18	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
19	2		*FRONT DOOR HINGES	Not Necessary	75.00 FL	*- FL
20	1		*FRONT HEADLAMP RH LED/HID	Broken	2,698.00 FL	*1,523.00 FL
21	1		*FRONT RADIATOR GRILLE ASSY	Cracked	295.30 FL	*295.30 FL
22	1		*FRONT RADIATOR GRILLE TOP GARNISH	Not Necessary	175.40 FL	*- FL
23	1		*SET FRONT RADIATOR GRILLE CLIPS	Not Necessary	60.00 FL	*- FL
24	1		*FRONT BONNET	Dented/Bent	970.50 FL	*970.50 FL
25	1		*FRONT BONNET RUBBER	Necessary	62.40 FL	*62.40 FL
26	1		*FRONT BONNET INSULATOR	Not Necessary	275.60 FL	*- FL
27	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	60.00 FL	*- FL
28	1		*FRONT BONNET LOCK	Twisted	214.20 FL	*214.20 FL
29	1		*FRONT SUPPORT PANEL	Distorted	985.40 FL	*985.40 FL
30	1		*AC CONDENSER	Not Necessary	1,246.30 FL	*- FL
31	1		*FRONT SUSPENSION RH	Bent	468.50 FL	*468.50 FL
32	1		*FRONT LOWER ARM RH	Bent	485.50 FL	*485.50 FL
33	1		*FRONT KNUCKLE ARM	Serviceable	596.50 FL	*- FL
34	1		*FRONT HUB BEARING ASSY RH	Damaged	199.50 FL	*199.50 FL
35	1		*FRONT DRIVE SHAFT RH	Not Necessary	1,256.00 FL	*- FL
36	1		*FRONT NUMBER PLATE W/GARNISH	Serviceable	80.00 FS	*- FS
37	1		*FRONT BUMPER ANGLE SENSOR	Not fitted	320.00 FS	*- FS
38	1		*FRONT RIM RH	Not Necessary	750.00 FS	*- FS
39	1		*FRONT TYRE RH	Not Necessary	450.00 FS	*- FS
40	1		*RADIATOR COOLANT	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,605.70	9,035.90
- List Item Discount on L Items 10.00/10.00% (S\$)	1,392.57	900.59
Total Parts (S\$)	14,213.13	8,135.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,400.00	1,000.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,200.00	1,100.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO REMOVE,INSTALL & CONDUCT RADIATOR PRESSURE LEAKAGE TEST }	New	200.00	100.00
5	TO REMOVE,INSTALL AC CONDENSER & TOP UP GAS }	New	200.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	200.00	60.00
7	TO RENEW,BALANCE & REPLACE FRONT RH TYRE	New	80.00	0.00
8	TO DISMANTLE REPLACED FRONT UNDERCARRIAGE	New	450.00	120.00
9	TO RE-POSITION FRONT SENSOR & ANGLE SENSOR	New	200.00	0.00
10	TO RUST PROOF AFFECTED AREAS	New	150.00	80.00
Gross Labour Cost (\$\$)			4,130.00	2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >