

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008530/KGS3Q2

Date: 24/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLU233S	Insured Vehicle No :	SHD4133H
Date of Loss: 13/08/2020	Nature of Claim: TP	Claim No: MCT20080207

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU233S		
Make & Model:	MERCEDES-BENZ CLA180, 1.6 COUPE URBAN (R18 LED) (A)	Engine No:	27091031434132
Reg. Date:	04/12/2017 (Man. Year: 2017)	Chassis No:	WDD1173422N576192
Colour:	Metallic Grey	Odometer:	28827 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,991.94	4,149.35	842.59	16.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,140.00	520.00	620.00	54.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,131.94	4,669.35	1,462.59	23.85
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	6,131.94	3,700.00	2,431.94	39.66
+ GST 7.00/7.00% (S\$)	429.24	259.00	170.24	39.66
Nett Amount (S\$)	6,561.18	3,959.00	2,602.18	39.66
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	17/08/2020	
Date Inspected:	18/08/2020 Inspected At:	Kum Chew Motor Workshop (160 Sin Ming) (HQ)
		160 Sin Ming Drive, #05-08 Sin Ming
		Autocity
		Singapore 575722
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2020)
Parts:	143	MERCEDES-BENZ CLA180 1.6 COUPE URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU233S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Mtg Cracked	1,378.90 FL	*1,378.90 FL
2	1		*FRT BUMPER SIDE RETAINER-LH	Necessary	66.23 FL	*66.23 FL
3	1		*FRT BUMPER REINFORCEMENT	Repair	337.66 FL	*- FL
4	1		*FRT BUMPER GRILLE-CENTER	Serviceable	157.91 FL	*- FL
5	1		*FRT BUMPER SIDE GRILLE-L/H	Serviceable	78.92 FL	*- FL
6	1		*FRT PARKING SENSOR (CENTRE)	Serviceable	180.86 FL	*- FL
7	1		*FRT PARKING SENSOR (SIDE)	Serviceable	180.86 FL	*- FL
8	1		*FRT HEADLAMP-LH	Cut	2,987.53 FL	*2,987.53 FL
9	1		*FRT BUMPER SPONGE	Cracked	177.73 FL	*177.73 FL
					Sub Total (\$\$)	5,546.60
					- List Item Discount on L Items 10.00/10.00% (\$\$)	554.66
					Total Parts (\$\$)	4,991.94
						4,149.35

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PULL,KNOCK ON FRT ACCIDENT PORTION & CHANGE THE ABOVE PART	New	480.00	250.00
2	TO SPRAY & PAINT ON FRT ACCIDENT PORTION	New	580.00	250.00
3	TO ANTI-RUST N/S AFFECTED AREAS	New	30.00	0.00
4	TO CHECK WIRING FUNCTION	New	50.00	20.00
Gross Labour Cost (\$\$)			1,140.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >