

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008531/AES3Q2

Date: 16/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900245415

Claimant
Vehicle No : SKN9244A **Insured Vehicle No :** GBH4247M

Date of Loss: 14/08/2020 Nature of Claim: TP Claim No: 3689251208SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN9244A	Engine No:	1NZR178396
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKD3B3201074830
Reg. Date:	30/07/2014 (Man. Year: 2014)	Odometer:	74141 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,536.75	1,672.50	1,864.25	52.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,290.00	1,030.00	44.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,856.75	2,962.50	2,894.25	49.42
Approved Total (Overridden) (\$\$)		2,350.00		
Nett Amount (\$\$)	5,856.75	2,350.00	3,506.75	59.88
+ Loss of Use (5.0 x S\$60.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,657.45		

INSPECTION

Date of Assignment: 17/08/2020

Date Inspected: 17/08/2020 Inspected At:

Premium Carz Services Pte Ltd (HQ)
1 Kaki Bukit Ave 6 #01-90
Autobay@Kaki
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	682.00 FL	*- FL
2	1		*FRONT FENDER HYBRID EMBLEM LH	Necessary	88.00 FL	*88.00 FL
3	1		*FRONT FENDER QUARTER GARNISH LH	Not Necessary	98.00 FL	*- FL
4	1		*FRONT DOOR LH	Dented	1,100.00 FL	*1,100.00 FL
5	1		*FRONT DOOR OUTER HANDLE LH	Repair	375.00 FL	*- FL
6	1		*FRONT DOOR OUTER MOULDING LH	Not Necessary	105.00 FL	*- FL
7	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	199.00 FL	*- FL
8	2		*FRONT DOOR HINGE LH	Not Necessary	190.00 FL	*- FL
9	1		*FRONT DOOR STRIKER LH	Not Necessary	118.00 FL	*- FL
10	1		*FRONT DOOR SASH PILLAR BLACK STICKER LH	Necessary	99.00 FL	*99.00 FL
11	1		*SIDE MIRROR LH	Distorted	1,145.00 FL	*868.00 FL
12	1		*SIDE MIRROR COVER LH	Distorted	75.00 FL	*75.00 FL
13	1		*REAR DOOR LH (NPA)	Repair	0.00 FL	*- FL
14	1		*REAR DOOR OUTER HANDLE LH	Not Necessary	375.00 FL	*- FL
15	1		*REAR FENDER LH (NPA)	Not Necessary	0.00 FL	*- FL
16	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
17	10		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,699.00	2,230.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,162.25	557.50
Total Parts (\$\$)	3,536.75	1,672.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	800.00	400.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,200.00	700.00
4	TO REMOVE AND REFIT FRONT DOOR GLASS LH	New	100.00	80.00
5	TO REMOVE AND REFIT FRONT FENDER QUARTER GLASS LH	New	80.00	40.00
6	TO SPRAY ANTI-RUST UNDERCOAT	New	60.00	40.00
Gross Labour Cost (\$\$)			2,320.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >