

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20008541/EES3Q2

**Date:** 19/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100405492

**Claimant**  
**Vehicle No :** SKQ633D **Insured Vehicle No :** SKR8846Z

Date of Loss: 13/08/2020 Nature of Claim: TP Claim No: 9849433241SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKQ633D</b>		Engine No:	HIDDEN
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN (A)		Chassis No:	JM6GJ1071F0141187
Reg. Date:	30/10/2014 (Man. Year: 2014)		Odometer:	76266 km
Colour:	White			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,752.88	1,351.12	401.76	22.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	760.00	1,030.00	57.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,542.88</b>	<b>2,111.12</b>	<b>1,431.76</b>	<b>40.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,700.00</b>		
<b>(S\$)</b>	3,542.88	1,700.00	1,842.88	52.02
<b>+ GST 7.00/7.00% (S\$)</b>	248.00	119.00	129.00	52.02
<b>Nett Amount (S\$)</b>	<b>3,790.88</b>	<b>1,819.00</b>	<b>1,971.88</b>	<b>52.02</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		17.00		
<b>Nett Liability (S\$)</b>		<b>2,236.00</b>		

### INSPECTION

Date of Assignment: 17/08/2020

Date Inspected: 18/08/2020 Inspected At:

Ryder Auto Workshop LLP (HQ)  
1 Kaki Bukit Ave 6, #01-56, Autobay  
@ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 3.0 days

---

**Adjuster:** CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	881.40 FL	*881.40 FL
2	2		*REAR BUMPER TOW COVER	Missing	120.00 FL	*45.00 FL
3	1		*REAR REINFORCEMENT	Dented	652.20 FL	*475.00 FL
4	10		*REAR BUMPER CLIPS	Necessary	80.00 F	*30.00 F
5	4		*REAR REVERSE SENSOR	Shorted (2 PCS ONLY)	350.00 F	*200.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,083.60</b>	<b>1,631.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	330.72	280.28
<b>Total Parts (S\$)</b>	<b>1,752.88</b>	<b>1,351.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE REAR DAMAGE PARTS	New	800.00	300.00
2	TO SPRAY PAINTING	New	800.00	400.00
3	TO REMOVE & REPLACE REAR TAILGATE	New	100.00	0.00
4	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	40.00	30.00
5	TO CHECK WIRING	New	50.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,790.00</b>	<b>760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >