



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2006000
INV Date 02/09/2020
Reference CS/AGI20008548/Atf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SJL 5611Y

Insured Veh. SLP 8091H

Claim No. C10007021

Policy No.

Accident Date 14/08/2020

Inspection Date 18/08/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20008548/Atf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 02-09-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 8091H	Veh. Inspected	SJL 5611Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10007021	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	17/08/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305083352	Colour	SILVER
Odometer	132677	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	MAXXIS	6 mm
L/H Front Tyre	195/55 R15	MAXXIS	6 mm
R/H Rear Tyre	195/55 R15	MAXXIS	6 mm
L/H Rear Tyre	195/55 R15	MAXXIS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/08/2020	Inspection Date	18/08/2020
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 5611Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	BUCKLED	645.00	645.00
1	BOOT LID LOGO	NECESSARY	69.00	69.00
1	BOOT LID EMBLEM "VIOS"	NECESSARY	60.00	60.00
1	BOOT LID EMBLEM "E"	NECESSARY	46.50	46.50
1	BOOT LID EMBLEM "SPORT"	NECESSARY	60.00	60.00
1	BOOT LID TOP LOCK	NOT NECESSARY	135.00	-
1	BOOT LID WEATHER STRIP	CUT	213.00	213.00
1	REAR BUMPER	DEFORMED	536.00	536.00
2	REAR BUMPER SIDE RETAINER (FRONT) @\$115.00	N/S DAMAGED	230.00	115.00
2	REAR BUMPER SIDE RETAINER (REAR) @\$65.00	N/S CRACKED	130.00	65.00
2	TAIL LAMP @\$534.00	N/S CRACKED	1,068.00	299.50
2	TAIL LAMP INNER SEAL @\$55.30	N/S NECESSARY	110.60	20.00
2	TAIL LAMP PANEL @\$268.00	TO REPAIR SEE LABOUR	536.00	-
1	REAR END PANEL	DENTED	712.00	539.10
1	REAR END PANEL TOP GARNISH	DEFORMED	135.00	135.00
1	REAR BUMPER REFLECTOR LH	CUT	98.00	98.00
	LESS 25% DISCOUNT		-1,196.03	-725.28
			3,588.07	2,175.82
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	BOOT LID SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR BUMPER LOWER LID (SN)	CRACKED	850.00	550.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	100.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			1,340.00	840.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO PANEL BEAT,WELD,CUT,KNOCK,GRAZE ,ADJUST,REPLACE NEW PARTS.INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL.		1,600.00	800.00
	TO PUTTY,SPRAY PAINT,POLISH,WAX ADJACENT PANELS.		1,600.00	800.00
	TO SPRAY TUFF COAT AND RUST PROOF ADJACENT PANELS.		250.00	60.00
	WIRING/BULB CHECKING.		120.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	50.00
	REMOVE AND REFIX REAR EXHAUST.	NOT NECESSARY	350.00	-
	TRANSFER BOOT LID MECHANISM.	NOT NECESSARY	150.00	-
			4,190.00	1,740.00
	GRAND TOTAL		9,118.07	4,755.82
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CS/AGI20008548/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJL 5611Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJL 5611Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

