

[illegible]

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLX1063T**
 MODEL : **HYUNDAI I30**
 DATE OF ACCIDENT : 14.08.20
 TIME OF ACCIDENT : 19:45HRS

30	REAR LOWER ARM RH <i>Best</i>	1	\$ 625.96	\$ 625.96	<i>✓</i>
31	REAR UPPER ARM RH <i>Best</i>	1	\$ 409.71	\$ 409.71	<i>✓</i>
32	REAR SWING ARM RH <i>Best</i>	1	\$ 496.47	\$ 496.47	<i>✓</i>
33	REAR SHOCK ABSORBER RH <i>new</i>	1	\$ 496.92	\$ 496.92	<i>+</i>
34	REAR LINKAGE RH <i>new</i>	1	\$ 92.10	\$ 92.10	<i>+</i>
35	REAR WHEEL HUP WITH BEARING RH <i>Ref</i>	1	\$ 454.00	\$ 454.00	<i>✓</i>
36	REAR ABS SENSOR RH <i>new</i>	1	\$ 287.40	\$ 287.40	<i>+</i>
37	REAR BUMPER <i>form</i>	1	\$ 801.59	\$ 801.59	<i>✓</i>
38	REAR BUMPER REFLECTOR RH <i>new</i>	1	\$ 248.40	\$ 248.40	<i>+</i>
39	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 213.09	\$ 426.18	<i>+</i>

TOTAL PRICE \$ 22,893.34
 LESS 20% - \$ 4,578.67
SUB TOTAL PRICE \$ 18,314.67

833370
666676

S.N: 600

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT DOOR INNER TRIM CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
2	CENTER PILLAR INNER TRIM CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
3	ROCKER PANEL SEALANT RH (OUTER) <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
4	REAR DOOR INNER TRIM CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
5	REAR FENDER SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
6	REAR FENDER COWLING CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
7	REAR MUDFLAP CLIP RH (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	<i>+</i>
8	REAR FENDER QUARTER GLASS SEALANT RH <i>new</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
9	REAR FENDER QUARTER GLASS INNER SHIELD RH <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
10	REAR FENDER QUARTER GLASS SOLAR FIM RH <i>new</i>	1	\$ 250.00	\$ 250.00	<i>+</i>
11	REAR WHEEL TYRE RH <i>new</i>	1	\$ 380.00	\$ 380.00	<i>+</i>
12	WHEEL CAP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00	<i>+</i>
13	ROOF MOULDING CLIP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00	<i>+</i>
14	REAR NUMBER PLATE (OFF PEAK) <i>new</i>	1	\$ 180.00	\$ 180.00	<i>50</i>
15	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
16	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
17	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>

TOTAL \$ 2,010.00

180

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLX1063T**
 MODEL : **HYUNDAI I30**
 DATE OF ACCIDENT : 14.08.20
 TIME OF ACCIDENT : 19:45HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/ N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,400.00	900.
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,400.00	800.
3	TUFF COAT	\$ 250.00	80
4	WIRING CHECK	\$ 250.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 550.00	80
6	TRANFER FRONT DOOR MECHANISM	\$ 80.00	X
7	REMOVE & REINSTALL FRONT DOOR WINDOW GLASS	\$ 80.00	X.
8	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	X.
9	RESET RADIO SYSTEM	\$ 200.00	X
10	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 350.00	220
11	TO PRESS REAR WHEEL BEARING	\$ 80.00	X
12	FOUR WHEEL ALIGNMNET	\$ 120.00	80
13	TRANFER REAR DOOR MECHANISM	\$ 80.00	40
14	REMOVE & REINSTALL REAR DOOR WINDOW GLASS	\$ 80.00	40
15	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
16	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
17	REMOVE AND REFIX REAR FENDER GLASS RH	\$ 100.00	50
18	REMOVE AND RESEAL OFF PEAK PLATE	\$ 250.00	80.
19	RESET ABS LIGHT	\$ 350.00	X

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLX1063T**
MODEL : **HYUNDAI I30**
DATE OF ACCIDENT : 14.08.20
TIME OF ACCIDENT : 19:45HRS

20	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$8,120.00

2450

TOTAL PARTS COST : \$ 20,324.67
TOTAL LABOUR COST : \$ 8,120.00
TOTAL REPAIR COST : \$ 28,444.67

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

Adrian Ly
L/S 18/08/20
07 Aug

total 9796963

L/S: 7.81c

7.81c

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TEO HIN TYRES

11 KAKI BUKIT ROAD 1
#01-01 EUNOS TECHNOLINK
SINGAPORE 415939
TEL:67455711

Work Order: R004464

License: SLX 1063 T
Date: 14.8.20 15:08

Hyundai : i30/Elantra Neos : 2017- (PD) : without Independent Rear Suspension : Rest of World

Front : Left

Actual	Before	Specified Range
-0°37'		-0°53' 0°07'
4°43'		4°00' 5°00'
0°31'		-0°03' 0°09'
10°39'		13°30' 14°30'
10°03'		12°37' 14°37'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°42'		-0°53' 0°07'
4°25'		4°00' 5°00'
-0°31'		-0°03' 0°09'
12°01'		13°30' 14°30'
11°18'		12°37' 14°37'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°06'		
0°18'		
-1°21'		
-0°01'		-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-0°16'		-1°42' -0°42'
0°05'		-0°02' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°16'		-1°42' -0°42'
0°53'		-0°02' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
2°01'		
0°58'		-0°04' 0°32'
-0°24'		