

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20008557/KQF3E2

Date: 02/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800143435
Claimant Vehicle No : SLT6556B	Insured Vehicle No :	SDY37R
Date of Loss: 13/08/2020	Nature of Claim:	TP
		Claim No: 7881962198SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT6556B	Engine No:	3A92UGK5652
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AJH000489
Reg. Date:	06/11/2017 (Man. Year: 2017)	Odometer:	46687 km
Colour:	Metallic Pearl White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,763.50	3,074.06	5,689.44	64.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	1,660.00	2,050.00	55.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,473.50	4,734.06	7,739.44	62.05
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	12,473.50	3,750.00	8,723.50	69.94
+ GST 7.00/7.00% (S\$)	873.15	262.50	610.65	69.94
Nett Amount (S\$)	13,346.65	4,012.50	9,334.15	69.94

INSPECTION

Date of Assignment:	17/08/2020	
Date Inspected:	18/08/2020 Inspected At:	Yee Auto Pte Ltd (HQ)
		160 SIN MING DRIVE, #02-17 SIN MING
		AUTOCITY
		Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
2	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS
3	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
4	1		*SET REVERSE CAMERA	Serviceable	300.00 FS	*- FS
5	1		*REAR BUMPER	Bent	865.00 F	*708.00 FL
6	1		*REAR BUMPER BRACKET - LH	Repair	65.00 F	*- FL
7	1		*REAR BUMPER BRACKET - RH	Repair	65.00 F	*- FL
8	1		*REAR BUMPER SIDE RETAINER - LH	Distorted	75.00 F	*75.00 FL
9	1		*REAR BUMPER SIDE RETAINER - RH	Serviceable	75.00 F	*- FL
10	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*REAR BUMPER REFLECTOR - LH	Mtg Cracked	98.00 F	*98.00 FL
12	1		*REAR BUMPER REFLECTOR - RH	Serviceable	98.00 F	*- FL
13	1		*REAR BODY PANEL	Bent	498.00 F	*425.50 FL
14	1		*REAR BODY PANEL TOP GARNISH	Mtg Distorted	185.00 F	*99.70 FL
15	1		*SET REAR BODY PANEL TOP GARNISH CLIP	Necessary	40.00 F	*40.00 FL
16	1		*TAIL LAMP RH	Serviceable	365.50 F	*- FL
17	1		*TAIL LAMP LH	Mtg Cracked	365.50 F	*276.00 FL
18	1		*REAR TAILLAMP PANEL - LH	Repair	326.50 F	*- FL
19	1		*REAR TAILLAMP PANEL - RH	Repair	326.50 F	*- FL
20	1		*REAR BOOT LID	Buckled	795.00 F	*728.70 FL
21	1		*REAR BOOT LID WEATHERSTRIP	Distorted	155.10 F	*155.10 FL
22	1		*BOOT HINGE - LH	Repair	95.00 F	*- FL
23	1		*BOOT HINGE - RH	Repair	95.00 F	*- FL
24	1		*BOOT TOP LOCK	Repair	195.10 F	*- FL
25	1		*BOOT EMBLEM LOGO	Necessary	88.00 F	*39.00 FL
26	1		*BOOT EMBLEM ATTRAGE	Necessary	85.10 F	*25.00 FL
27	1		*BOOT EMBLEM C&C	Necessary	62.00 F	*28.00 FL
28	1		*REAR WINDSCREEN MOULDING	Not Necessary	118.00 F	*- FL
29	1		*REAR NUMBER PLATE LAMP - LH	Serviceable	55.00 F	*- FL
30	1		*REAR NUMBER PLATE LAMP - RH	Serviceable	55.00 F	*- FL
31	1		*REAR FENDER - LH	Repair	868.00 F	*- FL
32	1		*REAR FENDER INNER GARNISH - LH	Serviceable	426.00 F	*- FL
33	1		*SPARE WHEEL PANEL	Repair	655.00 F	*- FL
34	1		*SPARE WHEEL CARDBOARD	Dented	268.10 F	*193.00 FL
35	1		*ANTENNA SENSOR	Cracked	225.00 F	*114.40 FL
36	1		*REVERSE SENSOR BUZZER	Cracked	305.10 F	*138.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,763.50	3,393.40
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	319.34
Total Parts (\$\$)	8,763.50	3,074.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY	New	1,500.00	700.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,500.00	800.00
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL	New	150.00	60.00
4	TO REMOVE / REFIT REAR WINDSCREEN GLASS TO FACILITATE REPAIRS	New	200.00	0.00
5	TO REMOVE / REFIT REAR CUSHION SEAT, SPEAKER BOARD, ROOF UPHOLSTERY TO FACILITATE REPAIRS	New	180.00	80.00
6	TO REMOVE / REFIX FUEL TANK TO FACILITATE REPAIRS	New	100.00	0.00
7	TO CHECK WIRING FUNCTIONS	New	80.00	20.00
Gross Labour Cost (\$\$)			3,710.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >