

REF:

ASS. REC. BY: TGL/KL

CC/ASM 2000858/B43

ASSIGNMENT

From: QD/OWS/TP RES/OD RES/IVA/INV/IMV Date: 17/8/2020
Estimated Cost: SMIA 4984
To Inspect Vehicle No: SMIA 4984
at Workshop m/s Dean Adabo
of 160 Sinking Dr, # 01-14
Insured: Dean Adabo
Policy No: 8AR8122-8 34
Claims No: JTEZB34H301002143
Sum Insured: Good
(Client's Record)
Make of Veh: TOYOTA
Excess: Nil
Type Size: F: 235/55/18 R: 235/55/18
Tire Size: F: 235/55/18 R: 235/55/18
Remarks: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: 110,000/-
IDAC Accident Report: Consistent? Yes or No
GIA / PR Seen: Consistent? Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lim Sumt: 5 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS WP
Date: 17/8/2020 Person Contacted: Dean Adabo Vehicle: IN / OUT

The UIC : Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction
Range 3.00p - 4.00p
4's 3.40p Train 19/2020
NV 110,000/-
PV 55,554/3
NV 54,446/-
Days Of Repair: 17/8/2020
Resurvey No. of Trip: 17/8/2020
Add Fee: Site Insp (\$)
Interview (\$)
Tech. Invs (\$)
Welding (\$)
Survey Fee: Transportation (\$)
Site Insp (\$)
Interview (\$)
Tech. Invs (\$)
Welding (\$)
Total: 17/8/2020

S/E: _____ Vehicle Nos: **SMA 4968 Y**
Date of Survey: _____ Make **Toyota**
Date of ReSurvey: _____ After-Paint: _____ Model **Harrier**
Contacts: _____ Chassis No: _____

*** AGREED Cost Of Repair and Repair Day/s with S/E ***

Amount: _____ Working Day: 23/18

Nos.	PARTS	QTY	Unit \$	TOTAL \$	
1	Rear bumper	1	\$ 1,375.30	\$292.44	AR ✓
2	Rear bumper side retainer	2	\$ 20.00	\$395.00	NEC ✓
3	Rear bumper lower	1	\$ 484.50	\$325.00	AR ✓
4	Rear bumper bracket	2	\$ 121.40	\$	NEC ✓
5	Rear bumper inner sponge	1	\$ 281.60	\$140.00	AR ✓
6	Rear bumper reflector	2	\$ 130.00	\$26.80	AR ✓
7	Rear bumper reverse sensor	2	\$ 244.00	\$40.00	SC ✓
8	Tailgate antenna sensor	1	\$ 385.60	\$30.00	AR ✓
9	Rear end panel outer	1	\$ 887.10	\$49.95	DD ✓
10	Rear end panel inner	1	✓ NEC	\$787.20	DD ✓
11	Rear end panel top garnish	1	\$ 377.80	\$	AR ✓
			Parts Sub Total:	\$ 5,683.90	
			Discount:	\$ 1,670.58	
			25%	\$	
			PARTS TOTAL:	\$ 5,012.93	
			3,627.94		
			906.99		
			2320.96		

Nos.	SPECIAL NETT	QTY	Unit \$	TOTAL \$	
1	Sundries	1	\$ 80.00	\$	NNX
2	Rear bumper clips	1	\$ 50.00	\$36.00	NNX
3	Rear bumper lower clips	1	\$ 50.00	\$30.00	NNX
4	Rear bumper reverse sensor seal	1	\$ 58.00	\$116.00	NNX
5	Rear end panel sealant	1	\$ 100.00	\$20.00	NNX
6	Rear end panel top garnish clips	1	\$ 50.00	\$20.00	NNX
			SPECIAL NETT TOTAL:	\$236.00	

Nos.	LABOUR	\$
1	R&R Rear bumper reverse sensor	\$ 62.00
2	Check wiring	\$ 30.00
3	Upholstery	\$
4	Rust proofing	\$60.00
5	Panel beat	\$600.00
6	Spray painting	\$600.00
		LABOUR TOTAL: \$2530.00
		5,012.93
		562.00
		2,530.00
		GRAND TOTAL: \$ 8,104.93

Surveyed by Resurvey
TQM Win
13/30/20
17/18/2020

Lump sum Repair
Repair days 5

453,400.7
TQM Win
17/18/2020
PARTS 2720.96
SN 236.00
LABOUR 1,350.00
4,386.96
811.39
3,445.56