

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008567/GEA3Q2

Date: 08/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100432031

Claimant
Vehicle No : SMK5492T **Insured Vehicle No :** GBE2471K

Date of Loss: 14/08/2020 Nature of Claim: TP Claim No: 5496154733SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK5492T		
Make & Model:	LEXUS IS250, 2.5 STD (A)	Engine No:	4GR0727605
Reg. Date:	15/03/2011 (Man. Year: 2011)	Chassis No:	JTHFK252602517722
Colour:	Black	Odometer:	118412 km
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,359.31	743.46	2,615.85	77.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	510.00	870.00	63.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,739.31	1,253.46	3,485.85	73.55
+ GST 7.00/7.00% (\$\$)	331.75	87.74	244.01	73.55
Nett Amount (\$\$)	5,071.06	1,341.20	3,729.86	73.55
+ Loss of Use (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		1,643.20		

INSPECTION

Date of Assignment: 14/08/2020

Date Inspected: 17/08/2020 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A,
#01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Not Necessary	1,328.50 FL	*- FL
2	1		*HEADLAMP LOWER BEAM LH	Not Necessary	170.10 FL	*- FL
3	1		*FRONT BUMPER	Cracked	571.50 FL	*571.50 FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	74.60 FL	*74.60 FL
5	12		*FRONT BUMPER CLIPS	Necessary	54.00 FL	*54.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	175.70 FL	*- FL
7	1		*FRONT BUMPER TOW COVER	Not Necessary	20.60 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Not Necessary	128.00 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	595.80 FL	*- FL
10	1		*PARKING SENSOR LH	Not Necessary	491.50 FL	*- FL
11	2		*PARKING SENSOR HOLDER	Not Necessary	56.00 FL	*- FL
12	1		*FOGLAMP LH	Not Necessary	409.20 FL	*- FL
13	1		*FOGLAMP CHROME MOULDING LH	Not Necessary	70.80 FL	*- FL
14	1		*FOGLAMP COVER LH	Not Necessary	41.60 FL	*- FL
15	1		*FRONT FENDER COWLING LH	Torn	265.50 FL	*265.50 FL
16	8		*FRONT FENDER COWLING CLIPS	Necessary	25.68 FL	*25.68 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,479.08	991.28
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,119.77	247.82
Total Parts (\$\$)	3,359.31	743.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO CHECK AND READJUST WHEEL ALIGNMENT	New	80.00	0.00
3	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	40.00
4	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD TO KNOCK & REPAIR FRONT FENDER LH ,SPORTS RIM LHF INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	600.00	200.00
5	TO SPRAY FRONT BUMPER ,FRONT FENDER LH SPORTS RIM LHF	New	600.00	250.00
Gross Labour Cost (\$\$)			1,380.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >