

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20008570/AEA3Q2
Date: 22/03/2021

REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 1900151943 |
| Claimant Vehicle No : | EU702M | Insured Vehicle No : | SMN6035H |
| Date of Loss: | 15/08/2020 | Nature of Claim: | TP |
| | | Claim No: | 0966848906SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | EU702M | Engine No: | CJE060974 |
| Make & Model: | AUDI A4, 1.8 TFSI MU (EU6) (A) | Chassis No: | WAUZZZ8K4EA017843 |
| Reg. Date: | 28/08/2013 (Man. Year: 2013) | Odometer: | 115135 km |
| Colour: | White | | |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 225/50 R17 | Rear Tyre Size: | 225/50 R17 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|-----------------|--------------|
| Parts | 7,070.00 | 2,989.36 | 4,080.64 | 57.72 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,022.00 | 2,572.00 | 3,450.00 | 57.29 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 13,092.00 | 5,561.36 | 7,530.64 | 57.52 |
| + GST 7.00/7.00% (S\$) | 916.44 | 389.30 | 527.14 | 57.52 |
| Nett Amount (S\$) | 14,008.44 | 5,950.66 | 8,057.78 | 57.52 |
| + Loss of Use (5.0 x S\$100.00/day) (S\$) | | 500.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 6,452.66 | | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 18/08/2020 | | |
| Date Inspected: | 18/08/2020 | Inspected At: | Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 2,273.00 FS | *1,818.40 FS |
| 2 | 1 | | *REAR BUMPER FIXING PARTS | Not Necessary | 225.00 FS | *- FS |
| 3 | 1 | | *REAR BUMPER SPOILER | Cut | 264.00 FS | *210.80 FS |
| 4 | 1 | | *REAR BUMPER CARRIER | Not Necessary | 636.00 FS | *- FS |
| 5 | 1 | | *REAR BUMPER SECURING STRIP | Not Necessary | 14.00 FS | *- FS |
| 6 | 1 | | *REAR BUMPER BRACKET HOLDER-RH | Not Necessary | 220.00 FS | *- FS |
| 7 | 1 | | *REAR BUMPER GUIDE SECTION -RH UPPER | Necessary | 22.00 FS | *17.52 FS |
| 8 | 1 | | *REAR BUMPER GUIDE SECTION -RH UPPER | Necessary | 45.00 FS | *35.36 FS |
| 9 | 1 | | *REAR PARKING AID SENSOR (NPA) | Not Necessary | 0.00 FS | *- FS |
| 10 | 1 | | *SET REAR BUMPER WIRING | Not Necessary | 510.00 FS | *- FS |
| 11 | 1 | | *LED TAIL LIGHT -RH | Not Necessary | 1,063.00 FS | *- FS |
| 12 | 1 | | *LED TAIL LIGHT -RH | Cracked | 1,096.00 FS | *850.40 FS |
| 13 | 1 | | *VENT TRIM | Deformed | 72.00 FS | *56.88 FS |
| 14 | 1 | | *PACKING ADHESIVE | Not Necessary | 18.00 FS | *- FS |
| 15 | 1 | | *AUDI EMBLEM | Not Necessary | 122.00 FS | *- FS |
| 16 | 1 | | *A.8T INSCRIPTION | Not Necessary | 95.00 FS | *- FS |
| 17 | 1 | | *A4 INSCRIPTION | Not Necessary | 95.00 FS | *- FS |
| 18 | 1 | | *SUNDRIES | Not Necessary | 300.00 FS | *- FS |

F=Franchise part. S=SpcNett.

| | | |
|-------------------------|-----------------|-----------------|
| Total Parts (\$) | 7,070.00 | 2,989.36 |
|-------------------------|-----------------|-----------------|

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND TRANSFER REAR PARKING AID ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE | New | 280.00 | 280.00 |
| 2 | TO DISMANTLE AND RENEW REAR BUMPER AND REAR BUMPER LOWER SPOILER .TO INSPECT RHS TAIL LAMP PANEL .RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED | New | 1,050.00 | 500.00 |
| 3 | TO RESPRAY REAR BUMPER AND REAR LID | New | 2,000.00 | 550.00 |
| 4 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| 5 | TO REPAIR RHS TAIL LAMP PANEL AND RHS REAR INNER CONNECTION PLATE | New | 1,000.00 | 500.00 |
| 6 | TO RESPRAY RHS TAIL LAMP PANEL AND RHS REAR INNER CONNECTION PLATE | New | 1,500.00 | 550.00 |
| Gross Labour Cost (S\$) | | | 6,022.00 | 2,572.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >