

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008572/UDA3Q2

Date: 13/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070071915

Claimant
Vehicle No : SMJ9138X **Insured Vehicle No :** SGP9833L

Date of Loss: 14/08/2020 Nature of Claim: TP Claim No: 1363232486SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ9138X		
Make & Model:	SKODA OCTAVIA, 1.4 AMBITION PLUS TSI (A)	Engine No:	CZD199870
Reg. Date:	25/03/2019 (Man. Year: 2018)	Chassis No:	TMBBC7NE3K0109617
Colour:	White	Odometer:	56673 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,223.38	11,769.44	8,453.94	41.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	3,030.00	2,650.00	46.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,903.38	14,799.44	11,103.94	42.87
Approved Total (Overridden) (\$\$)		11,800.00		
Nett Amount (\$\$)	25,903.38	11,800.00	14,103.38	54.45
+ Car Rental (12.0 x S\$100.00/day) (\$\$)		1,200.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		13,036.45		

INSPECTION

Date of Assignment: 17/08/2020

Date Inspected: 17/08/2020 Inspected At: Zoom Autowerks Pte Ltd (Bedok)
130 Bedok Reservoir Road, #08-1339
Singapore 470130

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	933.70 FL	*933.70 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	264.00 FL	*- FL
3	2		*REAR BUMPER BRACKET	Not Necessary	196.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	350.00 FL	*- FL
5	1		*REAR BUMPER IMPACT BRACKET	Not Necessary	295.60 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	468.50 FL	*468.50 FL
7	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
8	1		*REAR TAILLAMP	O/S Cracked	1,989.60 FL	*755.00 FL
9	1		*REAR BOOTLID PANEL	Dented / Bent	1,215.40 FL	*1,215.40 FL
10	1		*REAR BOOTLID LOGO	Necessary	112.50 FL	*112.50 FL
11	1		*REAR BOOTLID LOCK	Serviceable	482.50 FL	*- FL
12	1		*REAR BOOTLID SENSOR	Not Necessary	358.40 FL	*- FL
13	1		*REAR END PANEL	Badly Dented	785.40 FL	*785.40 FL
14	1		*REAR END PANEL TOP GARNISH	Twisted	368.20 FL	*368.20 FL
15	1		*REAR FENDERS (NPA)	Not Necessary	0.00 FL	*- FL
16	1		*REAR EXHAUST PIPE	Not Necessary	1,182.40 FL	*- FL
17	2		*REAR EXHAUST MOUNTING	Not Necessary	96.00 FL	*- FL
18	1		*REAR EXHAUST MUFFLER	Not Necessary	275.40 FL	*- FL
19	2		*REVERSE SENSOR	Shorted	390.80 FL	*390.80 FL
20	2		*REVERSE SENSOR BRACKET HOLDER	Not Necessary	150.80 FL	*- FL
21	1		*FRONT BUMPER	Deformed / Torn	910.40 FL	*910.40 FL
22	1		*FRONT BUMPER CENTRE AIR-GRILLE	Serviceable	325.40 FL	*- FL
23	2		*FRONT BUMPER GARNISH	Not Necessary	316.80 FL	*- FL
24	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	255.00 FL	*- FL
25	2		*FRONT BUMPER BRACKET	Not Necessary	216.00 FL	*- FL
26	1		*FRONT BUMPER SPONGE	Torn	160.00 FL	*160.00 FL
27	1		*FRONT BUMPER REINFORCEMENT	Dented	318.11 FL	*318.11 FL
28	1		*FRONT BUMPER NUMBER PLATE BOARD GARNISH	No such part	145.60 FL	*- FL
29	2		*FRONT BUMPER ANGLE SENSOR	Not Necessary	382.40 FL	*- FL
30	2		*FRONT BUMPER ANGLE SENSOR BRACKET HOLDER	Not Necessary	144.60 FL	*- FL
31	1		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
32	1		*FRONT CENTRE GRILLE ASSY	Cracked	546.70 FL	*546.70 FL
33	1		*FRONT RADIATOR GRILLE CLIPS	Not Necessary	60.00 FL	*- FL
34	2		*FRONT HEADLAMP	Cracked	3,424.80 FL	*3,424.80 FL
35	1		*FRONT BONNET	Bent / Buckled	1,480.00 FL	*1,480.00 FL
36	1		*FRONT BONNET LOGO	Necessary	98.00 FL	*98.00 FL
37	1		*FRONT BONNET RUBBER	Not Necessary	71.99 FL	*- FL
38	1		*FRONT BONNET LOCK	Serviceable	128.00 FL	*- FL
39	1		*CENTRE BRACE PANEL	Not Necessary	98.25 FL	*- FL
40	1		*FRONT SUPPORT PANEL	Cracked	1,222.32 FL	*845.20 FL
41	1		*AC CONDENSER	Not Necessary	1,375.30 FL	*- FL
42	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
43	1		*REAR BOOTLID PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
44	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	80.00 FS	*- FS
45	1		*REVERSE SENSOR	Repeated	280.00 FS	*- FS
46	1		*FRONT NUMBER PLATE W/GARNISH	Bent	80.00 FS	*40.00 FS
47	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 22,394.87 13,062.71

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					2,171.49	1,293.27
Total Parts (S\$)					20,223.38	11,769.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,200.00	600.00
2	TO PUTTY ,SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS	New	1,200.00	900.00
3	TO CHECK & RECONNECT ALL ELECTRICAL WIRING	New	80.00	30.00
4	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TRIM & GARNISH	New	150.00	60.00
5	TO RE-POSITION ,DRILL & INSTALL REVERSE SENSOR	New	150.00	50.00
6	TO REMOVE,REPAIR & RENEW FRONT AFFECTED ACCIDENT AREAS	New	1,200.00	600.00
7	TO PUTTY ,SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS	New	1,200.00	600.00
8	TO CONDUCT AC LEAKAGE TEST & TOP UP AC GAS	New	150.00	100.00
9	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
10	TO RUST PROOF AFFECTED AREAS	New	200.00	90.00
Gross Labour Cost (\$\$)			5,680.00	3,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >