

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20008585/GQF3E2

Date: 20/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100469212
Claimant Vehicle No : SKW6796X	Insured Vehicle No : SLD141M
Date of Loss: 16/08/2020	Nature of Claim: TP Claim No: 6798605655SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW6796X		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	HIDDEN
Reg. Date:	(Man. Year:)	Chassis No:	RU11104616
Colour:	Silver	Odometer:	100946 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/08/2020	
Date Inspected:	18/08/2020 Inspected At:	Guan Auto Service (Sin Ming) Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82 Singapore 575642
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER LOWER COVER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER SIDE	Deformed	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
8	1		*TAILGATE	Buckled	0.00 F	*- F
9	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
10	1		*TAILGATE LAMP	Cracked	0.00 F	*- F
11	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
12	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
13	1		*TAILGATE LOCK	Bent	0.00 F	*- F
14	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
15	1		*TAILGATE INNER BOARD	Deformed	0.00 F	*- F
16	1		*SPARE TYRE BOARD	Deformed	0.00 F	*- F
17	1		*SPARE TYRE TOOLS SPONGE	Cracked	0.00 F	*- F
18	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >