

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/C7120008587/49f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SMQ23024

at Workshop m/s

CBC 461 10am

of

Insured:

GBJ 4414L

Policy No.

DMCVSNA00029462000

Claims No.

SNM20D202898C02

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$120k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

1.51

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

LTA \$9999

Vehicle: IN / OUT

Date:

Person Contacted:

Det 126.

Veh No:

SMQ23024

Yr Regn:

11/19

Type:

M24 / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA1

Make:

Kia Sorento CRDi.c 2199

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

9122

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAPH 81BMK 551 7259

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

nexen

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

15/8/20

D.O.I.

20/8/20

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/9/20 \$9844.00 confirmed with her (Red \$7359, 43%)

01/09/20@9.37am revised to Jenny Lew via Merimen.

Date/Time, File Pass to?

☐

Preli. Report

01/09 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

Report Format :

MER-TP

Lump Sum

/I.B.I. (\$

9844

)

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept.	Cust No/Name LCV11416/Mr Tan Eyok Ann
Contact No 63896111	Reg No/Reg Date SMQ2302Y*ECB19 / 04/11/2019
	Date In/Mileage / 0
	Chassis No KNAPH81BMK5517259
	Engine No D4HBJH398417
	Make/Model KIA/SORENTO 2.2 A SR D EGD
	Colour/Trim 4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000018	Credit	17/08/2020/ 16:09		218 / MarsLer	50867			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	SUNDRY							50.00
	C & C LOGO	ru						
M	SUNDRY							50.00
	4 X 4 EMBLEM	ru						
S	MIPNT88088							250.00
	DIAGNOSTIC / SCANNING							
S	MIPNT88088							600.00
	TO TRANSFER TAILGATE COMPONENT & MECHANISM PARTS							
	-INCLUDE REAR SPOILER AND REVERSE CAMERA LENS (NETT)							
S	MIPNT88088							300.00
	TO REPLACE TAILGATE GLASS							
M	SUNDRY							100.00
	SEALANT KIT ON TAILGATE GLASS							
S	MIPNT88088							220.00
	TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS							
S	MIPNT88088							100.00
	TO CHECK LIGHTING AND WIRING ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT88088							600.00
	TO REMOVE AND RE-INSTALL REAR CAPERTING AND TRIMMING TO							
	GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT88088							3000.00
	TO REPLACE REAR BUMPER,REINFORCEMENT,TAILGATE PNL,ETC							
	-TO REPAIR REAR END PANEL							
	STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT88088							600.00
	TO REPLACE REAR EXHAUST MUFFLER ASSY							
S	MIPNT88088							200.00
	TO APPLY SEALANT KIT ON NEW PANEL							
S	MIPNT98088							1680.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS							
M	KS 86611 C5 510				1.00	605.00	0.00	605.00
	COVER-RR BUMPER,UPR							
M	KS 86612 C5 500				1.00	565.00	0.00	565.00
	COVER - REAR BUMPER							
P	KS 86665 C5 510				1.00	103.00	0.00	103.00
	SKID PLATE - REAR BU							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	<table> <tr> <td>Cust No/Name</td><td>LCV11416/Mr Tan Eyok Ann</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMQ2302Y*ECB/ 04/11/2019</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAPH81BMK5517259</td></tr> <tr> <td>Engine No</td><td>D4HBHJ398417</td></tr> <tr> <td>Make/Model</td><td>KIA/SORENTO 2.2 A SR D EGD</td></tr> <tr> <td>Colour/Trim</td><td>4SS / WK</td></tr> </table>	Cust No/Name	LCV11416/Mr Tan Eyok Ann	Reg No/Reg Date	SMQ2302Y*ECB/ 04/11/2019	Date In/Mileage	/ 0	Chassis No	KNAPH81BMK5517259	Engine No	D4HBHJ398417	Make/Model	KIA/SORENTO 2.2 A SR D EGD	Colour/Trim	4SS / WK
Cust No/Name	LCV11416/Mr Tan Eyok Ann														
Reg No/Reg Date	SMQ2302Y*ECB/ 04/11/2019														
Date In/Mileage	/ 0														
Chassis No	KNAPH81BMK5517259														
Engine No	D4HBHJ398417														
Make/Model	KIA/SORENTO 2.2 A SR D EGD														
Colour/Trim	4SS / WK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000018	Credit	17/08/2020/ 16:09		218 / MarsLer	50867			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	KS	96890 C5 5004 SS	ULTRASONIC SENSOR -	n/s shld	2.00	187.00	0.00	374.00
M	KS	91885 C5 130	WIRING HARNESS-R.P.A	SVX	1.00	357.00	0.00	357.00
P	KS	86661 C5 000	LH SIDE BRACKET ASSY	11 X	1.00	22.00	0.00	22.00
P	KS	86662 C5 000	RH SIDE BRACKET ASSY	11 X	1.00	22.00	0.00	22.00
M	KS	81297 29 500	TAPE-ANTI ABRASION	neu	2.00	2.00	0.00	4.00
M	KS	06032 50 037A	CLIP - BUMPER	neu	10.00	2.00	0.00	20.00
M	KS	86630 C5 510	RAIL ASSY-REAR BUMPE	neu	1.00	341.00	0.00	341.00
M	KS	95420 C6 500	ANTENNA ASSY-SMARTKE	neu	1.00	33.00	0.00	33.00
M	KS	86653 C5 500	LH COVER-BLANKING RR	neu	1.00	44.00	0.00	44.00
M	KS	92405 C5 510	LH LAMP ASSY-REAR FO	neu	1.00	129.00	0.00	129.00
M	KS	73700 C5 121	TAIL GATE PANEL ASSY	neu	1.00	1445.00	0.00	1445.00
M	KS	86320 C5 100	EMBLEM-KIA	neu	1.00	69.00	0.00	69.00
M	KS	86310 C5 010	EMBLEM-SORENTO	neu	1.00	28.00	0.00	28.00
P	KS	86333 C5 000	EMBLEM-ECO-DYNAMIC	neu	1.00	37.00	0.00	37.00
M	KS	81770 C5 100	LH GATE LIFTER ASSY	neu	1.00	874.00	0.00	874.00
M	KS	81780 C5 100	RH GATE LIFTER ASSY	neu	1.00	760.00	0.00	760.00
P	KS	81230 C5 100	POWER LATCH ASSY - P	SVX	1.00	652.00	0.00	652.00
M	KS	87321 C5 000	WEATHERSTRIP - TAILG	neu	1.00	128.00	0.00	128.00
M	KS	85770 C5 000W K	TRIM ASSY - REAR TRA	neu	1.00	59.00	0.00	59.00
M	KS	87110 C5 000	GLASS ASSY - TAILGAT	neu	1.00	690.00	0.00	690.00
M	KS	86114 2L 000	PAD - WINDSHIELD	neu	4.00	17.00	0.00	68.00
M	KS	86114 3D 000	PAD - WINDSHIELD GLA	neu	6.00	2.00	0.00	12.00
M	KS	87115 C5 000	STOPPER - REAR WINDO	neu	2.00	4.00	0.00	8.00
M	KS	28710 C5 811	MUFFLER ASSY-REAR	neu	1.00	1177.00	0.00	1177.00
Z	NOTES							

Z NOTES

ACCIDENT ON 15/08/2020 ALONG 230D TAMPINES ST. 24 LOADING/UNLOAD BAY

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP # GBJ4414J TP INS : CHINA TAIPING

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company.

Confirm & accepted by

Parts

Labour

Standard Menu

Specialist Job

Others (Lub, etc)

Sundry

Total (w/o GST)

8,626.00

0.00

0.00

7,550.00

0.00

200.00

16,376.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	LCV11416/Mr Tan Eyok Ann
	Reg No/Reg Date	SMQ2302Y*ECB19 / 04/11/2019
	Date In/Mileage	/ 0
	Chassis No	KNAPH81BMK5517259
	Engine No	D4HBH398417
	Make/Model	KIA/SORENTO 2.2 A SR D EGD
	Colour/Trim	4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	20/08/2020/ 10:46		218 / MarsLer	50867

Description of Goods/Services		Qty	Unit Price	Disc%	Amount
M KS 92403 C5 600	LH INSIDE LAMP ASSY- APD	1.00	827.00	0.00	827.00
Z NOTES					
SUPPLEMENTARY ITEM					
<h1 style="text-align: center;">Estimate</h1>					

Confirm & accepted by

Supplementary

Authorized signatory and company stamp

Parts	827.00
Labour	0.00
Standard Menu	0.00
Specialist Job	0.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	827.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info														
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	<table> <tr> <td>Cust No/Name</td><td>LCV11416/Mr Tan Eyok Ann</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMQ2302Y*ECB19 / 04/11/2019</td></tr> <tr> <td>Date In/Mileage</td><td>24/08/2020/ 9193</td></tr> <tr> <td>Chassis No</td><td>KNAPH81BMK5517259</td></tr> <tr> <td>Engine No</td><td>D4HBH398417</td></tr> <tr> <td>Make/Model</td><td>KIA/SORENTO 2.2 A SR D EGD</td></tr> <tr> <td>Colour/Trim</td><td>4SS / WK</td></tr> </table>	Cust No/Name	LCV11416/Mr Tan Eyok Ann	Reg No/Reg Date	SMQ2302Y*ECB19 / 04/11/2019	Date In/Mileage	24/08/2020/ 9193	Chassis No	KNAPH81BMK5517259	Engine No	D4HBH398417	Make/Model	KIA/SORENTO 2.2 A SR D EGD	Colour/Trim	4SS / WK
Cust No/Name	LCV11416/Mr Tan Eyok Ann														
Reg No/Reg Date	SMQ2302Y*ECB19 / 04/11/2019														
Date In/Mileage	24/08/2020/ 9193														
Chassis No	KNAPH81BMK5517259														
Engine No	D4HBH398417														
Make/Model	KIA/SORENTO 2.2 A SR D EGD														
Colour/Trim	4SS / WK														

Account No	Terms	Date/Time Printed	GSE	Operator	WIP No				
F0000018	Credit	29/08/2020/ 11:00	DS	218 / MarsLer	50867				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
M	SUNDRY								50.00
	C & C LOGO								
M	SUNDRY								50.00
	4 X 4 EMBLEM								
S	MIPNT88088								250.00
	DIAGNOSTIC / SCANNING								
S	MIPNT88088								600.00
	TO TRANSFER TAILGATE COMPONENT & MECHANISM PARTS								
	-INCLUDE REAR SPOILER AND REVERSE CAMERA LENS (NETT)								
S	MIPNT88088								300.00
	TO REPLACE TAILGATE GLASS								
M	SUNDRY								100.00
	SEALANT KIT ON TAILGATE GLASS								
S	MIPNT88088								220.00
	TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS								
S	MIPNT88088								80.00
	TO CHECK LIGHTING AND WIRING ON REAR ACCIDENT AFFECTED AREAS								
S	MIPNT88088								300.00
	TO REMOVE AND RE-INSTALL REAR CAPERTING AND TRIMMING TO								
	GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS								
S	MIPNT88088								1500.00
	TO REPLACE REAR BUMPER,REINFORCEMENT,TAILGATE PNL,ETC								
	-TO REPAIR REAR END PANEL								
	STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS								
S	MIPNT88088								100.00
	TO APPLY SEALANT KIT ON NEW PANEL								
S	MIPNT98088								1260.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								
X	KS 86611 C5 510	COVER-RR BUMPER,UPR	1.00	605.00	0.00	605.00			
X	KS 86612 C5 500	COVER - REAR BUMPER	1.00	565.00	0.00	565.00			
X	KS 96890 C5 500B 4U	ULTRASONIC SENSOR-S.	1.00	187.00	0.00	187.00			
M	KS 81297 29 500	TAPE-ANTI ABRASION	2.00	2.00	0.00	4.00			
X	JJMR328954	CLIP,BUMPER	10.00	2.00	0.00	20.00			

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	LCV11416/Mr Tan Eyok Ann
	Reg No/Reg Date	SMQ2302Y*ECB/ 04/11/2019
	Date In/Mileage	24/08/2020/ 9193
	Chassis No	KNAPH81BMK5517259
	Engine No	D4HBJH398417
	Make/Model	KIA/SORENTO 2.2 A SR D EGD
	Colour/Trim	4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	29/08/2020/ 11:00	DS	218 / MarsLer	50867

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X KS 86630 C5 510 RAIL ASSY-REAR BUMPE	1.00	341.00	0.00	341.00
X KS 73700 C5 121 TAIL GATE PANEL ASSY	1.00	1445.00	0.00	1445.00
X KS 86320 C5 100 EMBLEM-KIA	1.00	69.00	0.00	69.00
X KS 86310 C5 010 EMBLEM-SORENTO	1.00	28.00	0.00	28.00
X KS 86333 C5 000 EMBLEM - ECO DYNAMIC	1.00	37.00	0.00	37.00
X KS 87321 C5 000 WEATHERSTRIP - TAILG	1.00	128.00	0.00	128.00
X KS 87110 C5 000 GLASS ASSY - TAILGAT	1.00	690.00	0.00	690.00
M KS 86114 2L 000 PAD - WINDSHIELD	4.00	17.00	0.00	68.00
M KS 86114 3D 000 PAD - WINDSHIELD GLA	6.00	2.00	0.00	12.00
M KS 87115 C5 000 STOPPER - REAR WINDO	2.00	4.00	0.00	8.00
X KS 92403 C5 600 LH INSIDE LAMP ASSY	1.00	827.00	0.00	827.00

Z NOTES

ACCIDENT ON 15/08/2020 ALONG 2300 TAMMINES ST. 24 LOADING/UNLOADING BAY
 OWNER CLAIMING THIRD PARTY
 REQUIRED REPLACEMENT CAR (CHAN'S)
 TP # GBJ4414J TP INS : CHINA TAIPING

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Parts	5,034.00
Labour	0.00
Standard Menu	0.00
Specialist Job	4,610.00
Others (Lub, etc)	0.00
Sundry	200.00
Total (w/o GST)	9,844.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.