

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20008595/KES3Q2

**Date:** 19/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900133344-01

### Claimant

**Vehicle No :** SMM1353C

**Insured Vehicle No :** SMN3443H

**Date of Loss:** 15/08/2020

**Nature of Claim:** TP

**Claim No:** 9138095434SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SMM1353C

**Make & Model:** HONDA VEZEL, 1.5 X CVT (A)

**Engine No:** L15B5569063

**Reg. Date:** 18/06/2019 (Man. Year: 2019)

**Chassis No:** RU11319024

**Colour:** Metallic Dark Blue

**Odometer:** 97758 km

**Engine Capacity:** 1496 cc

**Market Value/New Car Price:** N/A

**Sum Insured (S\$):** Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 215/60R16

**Rear Tyre Size:** 215/60R16

**Front Left Side:** Dunlop 2 mm

**Rear Left Side:** Dunlop 2 mm

**Front Right Side:** Dunlop 2 mm

**Rear Right Side:** Dunlop 2 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,428.00	2,128.48	5,299.52	71.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	455.00	2,595.00	85.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,478.00</b>	<b>2,583.48</b>	<b>7,894.52</b>	<b>75.34</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,050.00</b>		
<b>(S\$)</b>	10,478.00	2,050.00	8,428.00	80.44
<b>+ GST 7.00/7.00% (S\$)</b>	733.46	143.50	589.96	80.44
<b>Nett Amount (S\$)</b>	<b>11,211.46</b>	<b>2,193.50</b>	<b>9,017.96</b>	<b>80.44</b>
<b>+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		321.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,516.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,500.00</b>		

### INSPECTION

**Date of Assignment:** 18/08/2020

**Date Inspected:** 24/08/2020 **Inspected At:**

MBM Wheelpower Pte Ltd (HQ)  
160 Sin Ming Drive #06-02, Sin Ming  
AutoCity  
Singapore 575722

**Estimated Period of Repair:** 2.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,200.00 FL	*- FL
2	1		*BONNET CENTER SEAL	Serviceable	100.00 FL	*- FL
3	1		*FRONT BUMPER	Bent	990.00 FL	*762.00 FL
4	1		*FRONT BUMPER LOWER GRILLE	Serviceable	150.00 FL	*- FL
5	1		*FRONT BUMPER LOWER TRIM	Serviceable	400.00 FL	*- FL
6	1		*FRONT FOG LAMP LH	Serviceable	250.00 FL	*- FL
7	1		*FRONT FOG LAMP RH	Serviceable	250.00 FL	*- FL
8	1		*FRONT BUMPER FOG LIGHT GARNISH RH	Serviceable	105.00 FL	*- FL
9	1		*FRONT BUMPER FOG LIGHT GARNISH LH	Serviceable	105.00 FL	*- FL
10	1		*FRONT BUMPER TOWING COVER	Serviceable	60.00 FL	*- FL
11	1		*FRONT BUMPER LOWER SPOILER (RUBBER)	Serviceable	90.00 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Repair	600.00 FL	*- FL
13	1		*FRONT BUMPER RETAINER LH	Serviceable	75.00 FL	*- FL
14	1		*FRONT BUMPER RETAINER RH	Distorted	75.00 FL	*48.60 FL
15	10		*FRONT BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
16	1		*FRONT GRILLE	Serviceable	500.00 FL	*- FL
17	1		*FRONT GRILLE CHROME MOULDING	Serviceable	400.00 FL	*- FL
18	1		*FRONT GRILLE (H) EMBLEM	Not Necessary	50.00 FL	*- FL
19	1		*FRONT GRILLE INNER COVER	Serviceable	60.00 FL	*- FL
20	10		*FRONT GRILLE CLIP	Not Necessary	50.00 FL	*- FL
21	1		*FRONT HEADLAMP LH	Serviceable	1,800.00 FL	*- FL
22	1		*FRONT HEADLAMP RH	Mtg Cracked	1,800.00 FL	*1,800.00 FL
23	1		*NUMBER PLATE & HOLDER	Serviceable	50.00 FS	*- FS
24	1		*BODY SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,260.00</b>	<b>2,660.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,832.00</b>	<b>532.12</b>
<b>Total Parts (\$\$)</b>	<b>7,428.00</b>	<b>2,128.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS	New	1,600.00	220.00
2	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	200.00	15.00
3	TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	New	250.00	0.00
4	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	220.00
<b>Gross Labour Cost (\$)</b>			<b>3,050.00</b>	<b>455.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**