

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2645R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	I40VC COVER ASSY-RR BUMPE	DEFORMED	1,106.00	1,106.00
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	I40VC COVER-RR BUMPER LWR	TO REPAIR SEE LABOUR	228.00	-
	LESS 20% DISCOUNT		-271.20	-225.60
			1,084.80	902.40
<u>NETT ITEMS</u>				
1	HYUNDAI REVERSE SENSOR AS (N)	NOT WORKING	135.70	135.70
	LESS 10% DISCOUNT		-13.57	-13.57
			122.13	122.13
<u>SPECIAL NETT ITEMS</u>				
1	I40VC PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF I40VC COVER-RR BUMPER LWR.		350.00	280.00
	SPRAYPAINT ON AFFECTED AREA.		250.00	200.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			680.00	510.00
GRAND TOTAL			1,936.93	1,584.53
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,250.00

Report Ref No. NS/INC20008602/T1sf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.