Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20008608/T1SF3E2

Date: 04/09/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MK001053 Claimant Vehicle SHC3023D

Insured Vehicle No: SMG5902Z No:

ΤP Date of Loss: 17/08/2020 Nature of Claim: Claim No: M2004011

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC3023D

Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A) Engine No: G4LEJU167105

Reg. Date: 01/02/2019 (Man. Year: 2018) Chassis No: KMHC851CVKU133906

Colour: Odometer: 172411 km

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition: Good

CONDITION OF TYRES

195/65 R15 Front Tyre Size: 195/65 R15 Rear Tyre Size: Front Left Side: Rear Left Side: Davanti 6 mm Davanti 6 mm Rear Right Side: Front Right Side: Davanti 6 mm Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	175.68	165.68	10.00	5.69
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,450.00	1,110.00	340.00	23.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,636.68	1,286.68	350.00	21.38
+ GST 7.00/7.00% (S\$)	114.57	90.07	24.50	21.38
Nett Amount (S\$)	1,751.25	1,376.75	374.50	21.38

INSPECTION

Date of Assignment: 18/08/2020 Present Location: ComfortDelGro Engineering Pte Ltd

(Loyang)

18/08/2020 Inspected At: ComfortDelGro Engineering Pte Ltd Date Inspected:

> (Loyang) 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Hiew May Fung Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference			
Part Source:		(Last Synchronised: 04 Sep 2020)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	de: (Unsubmitted, no print-code for SHC3023D)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*DOOR REAR COMFORT APP	Necessary	80.00 FS	-	*80.00 FS
2	1		*FENDER REAR PETROL STCKER	Not Necessary	10.00 FS	-	*- FS
3	1		*WHEEL HUB COVER LH	Cut	107.10 FL	-	*107.10 FL
F=Fra	ınchise	part. S=Spcl	Nett. L=ListItemDisc.				
				Sub Total (S\$)	197.10	187.10	
			- List Item Discount on L Items	20.00/20.00% (S\$)	21.42	21.42	
				Total Parts (S\$)	175.68		165.68
			Report was unsubmitted du	ring this print-out.]

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellar	neous Items			
1	1	OD/TP Case (Insurer)		11.00	11.00
			Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	640.00	480.00
2	SPRAY PAINTING	New	600.00	600.00
3	REMOVE /REFIX UPHOLSTERY REAR	New	120.00	0.00
4	TUFF KOTE	New	90.00	30.00
		Gross Labour Cost (S\$)	1,450.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >