## HIN TAT AUGUSTINE & PARTNERS UEN NO. 53130863D

Advocates & Solicitors Commissioners For Oaths Notaries Public

20 LIPPER CIRCULAR ROAD #02-10/12 THE RIVERWALK SINGAPORE 058416 TEL: (65) 6533 0212 FAX: (65) 6533 0313

WEBSITE: www.htapartners.com.sg WRITER: GONG CHIN NAM (chinnam@htapartners.com.sg) SECRETARY: RUBY ONG (ruby@htapartners.com.sg)

In Association with: Strohal Legal Group Pte Ltd International Legal Consultants

(65) 6533 0163 (Direct Fax) Service By Fax Not Accepted

Our Ref:

TCL.GCN.ro.50168.19.ess

Your Ref:

SNM19D201267-GBC1851P

20 April 2020

Nguan Food Trading Pte Ltd

15 Jalan Tepon #01-15 Singapore 619936 By Certificate of Posting (w/o encl)

(for your information only)

**Zhang Xing** 59 Lasia Avenue #07-1553 Lucky Park

Singapore 277866

By Certificate of Posting (w/o encl)

(for your information only)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

By email:

boonsen.chong@sg.cntaiping.com

Attn: Mr Chong Boon Sen / Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING SLG 6953G & GBC 1851P ALONG CORPORATION ROAD TOWARDS JURONG PORT ROAD ON 20 MARCH 2019 @ 0715HRS

We act for AMV Pte Ltd, the owner of motor vehicle no. SLG 6953G, in relation to the abovecaptioned road traffic accident.

We are instructed that you were the owner and driver and/or the insurer of motor vehicle no. GBC 1851P at the material time. We are further instructed that the accident was caused by your authorised driver and/or your insured driver's negligence in the driving, control and/or management of your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

Cost of Repairs 1.

S\$18,000.00 S\$ 2,520.00

Rental Charges (21 days x S\$120.00/ day)



#### HIN TAT AUGUSTINE & PARTNERS

Page No. 2

Our Ref. TCL.GCN.ro.50168.19.ess Your Ref. SNM19D201267-GBC18519

Date: 20 April 2020

3. GIA Search / Docume	nt Fee	S\$ 29.00	
4. Survey Report Fees		S\$ 1,337.00	
5. Costs (inclusive of GS	T)	S\$ 1,070.00	
6. Incidentals	•	S\$ 50.00	
	Total	S\$23,006.00	

The following supporting documents are enclosed herewith: -

- 1. Copy of Singapore Accident Statement and Traffic Police Report by SLG 6953G;
- 2. Copy of Repair Bill from Euro Success Serv Pte Ltd;
- 3. Copy of Rental Invoice from Selection Pre-Owned;
- 4. Copies of GIA Invoices;
- 5. Copy of Survey Invoice & Survey Report from Priority Services;
- 6. **207 pcs of original** photographs of motor vehicle no. <u>SLG 6953G</u>.

Please note that you and / or your authorized driver and/or your insured driver should send to us an acknowledgement of receipt of this letter within **fourteen (14)** days of receipt of this letter, failing which our clients will have no alternative but to commence proceedings against you and / or your authorized driver and/or your insured driver without further notice to you and / or authorized driver and/or your insured driver.

Please note that if you and / or authorized driver and/or insured driver have a counterclaim against our clients arising out of the accident, you and / or authorized driver and/or your insured driver are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Please note that our client's claim is in respect of its property damage claim and is strictly without prejudige to the uninsured losses and/or injury claim (if any).

Yours fathfully,

Enc.

cc: clients

By fax

### SINGAPORE ACCIDENT STATEMENT

### MPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wliful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aioresaid.	
	ACCIDENT STATEMENT
Date Of Report	20/03/2019 15:25
Date Of Accident	20/03/2019 07:15
Exact Location Of Accident	CORPORATION RD BEFORE JURONG PORT ROAD
Country/State of Loss	SINGAPORE
· 经有一种商品支票的企业的	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLG6953G
Insured/Policyholder	

Insured/Polic	yholder
---------------	---------

Name Of Registered Owner AMV PTE\_LTD.

Co Reg No 201505825Z

Email Address INFO@AMV-SINGAPORE.COM

 Mobile Phone No
 (LOCAL) +65-98583956

 Alternative Phone No
 OFFICE-98583956

#### Vehicle Particulars

Manufacturer MAZDA

Model MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

Vehicle Category

Pf

THIRD PARTY
PRIVATE HIRE

### Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy No.

Policy Number 5095368867-01

Cover Note Number

#### Driver

Name of Driver CHEN YUTONG
NRIC No S8515434F
Date Of Birth 14/05/1985
Occupation OUTDOOR
Date Of Driving Pass 03/11/2003

Driving Experience 15 YEARS AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-93264941

Fax Number

Contact Number

EMail Address NOEMAIL

OTHER, - HIRER

Securities at any syen of the inner deal on the v

If No. Relationship of the Driver with the Insured

Vehicle

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD ON COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle).

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

t have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

NAME:

GRAB PASSENGER

GENDER:

MALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station Police Station Name

TRAFFIC POLICE DIVISION HQ

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20190320/2066;

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

**GBC1851P** 

Vehicle Make/Model/Colour

MITSUBISHI FB70BB1SRDEA

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ZHANG XING

NRIC/Passport Number

G3283509R

Contact Number

Address

Page 2 of 16

-THE COLD

Taulibrate Bridge V all as

National Of Page 1989.

No. Of Passenger (Including Driver)

#### Accident Sketch Plan Pg. 1

### IMPORTANT NOTICE

- A supply report convertly to exercise at 17 km and 2.1 km and 2.2 km and 3.1 km.
- The Foreign of the Completed by the Policyholder and/or the Authorised Drivet
- of process processed from the an united and accurate as possible. And or the management of a continuous processes repudiate policy liability
- any false reporting may be referred to the Police for investigation
- THE SERVICE WE SET THE PROPERTY OF THE EAST OF THE EAST OF THE PROPERTY OF THE AND WHILE IT STREET ON THE BOOK OF SOME DISTRICT OF STREET OF STREET OF STREET OF STREET OF STREET
- - - - the supplied with the state of the state of

DEN STRYAL

WHITE BY BUT DE DE CO. C. C. CO. Date & Timus

2 0 1 7 7019

HIAC KAKUBUKU TUTO 21 KAKI BUKILA

Secretal Representations Tel: 67416697

Vame: Face 67492305

Lineal suckharsingnetics

### Accident Sketch Plan Pg. 1

DECLARATION  //Walderless the street of the second of the	The base of the post of the property of the entire to the entire t	2 0 MAR 2019  IDAC KAKI BUKIT (VA 23 KAKI BUKIT AVE 4 Singapore 415933  Expecting fining Fifthdog/4-Experime Fator Fifth figure 1 yackburing ret com	9
	*		
	<i>f</i>		
		1	
		, , , , ,	
		7	
Rela to poles		F.	
DESCRIBE CIRCUMSTANCES	DETHI ADDIDENT		
B GELLERIE			
A SLG COLSE			
	1		
	*		:77 :57
P - 1/26 13 2		1 1 1 1 1 1 - 1	

Page 5 of 16





Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 013

Report No. T/20190320/2066

### REPORT OF A TRAFFIC ACCIDENT

20/03/2019		ade: 	Vide Report No.:	Station Diary No.:	
Informant	s Particul	ars			
Name of Ir CHEN YU			Address: APT BLK 317 JURONG EAST STREET 31 #13-30 SINGAPORE 600317		
ID Type / ID No.; NRIC NO / S8515434F Nationality: SINGAPORE CITIZEN			Contact No.: Home/Office: Email:	Mobile: 93264941	
Sex: Male	Age: 33	Date of Birth: 14/05/1985	Type of Informant: Driver		
Race: Chinese		Transaction of the Control of the Co	Language: English	Institution / School Name:	
Occupation GRAB DRI			Driving Licence Information: Class: 2B,3	Date of Expiry:	

acricial inform	nation of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 20/03/2019 07:15	Type of Location:	
Location: Along Road 1 CORPORATIO	ON ROAD ON ROAD > JURONG PO	ORT BOAD			
Weather:	ATTIONS > CONCINCT	Road Surface:	Ro	pad Speed Limit:	
Traffic Flow: Traffic Control:				Traffic Volume:	
Type of Collision	on:			nyone conveyed by nbulance:	

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
GBC1851P	Lorry					0
SLG6953G	Car					1





3 01 3

Report No. T/20190320/2066

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

### **Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Informant:

**CONTINUATION OF REPORT** 

Signature Of Officer Recording The Report:
TP /
TAN KOK RAY

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sgt 3 MARIAH BINTE ZAKARIA
Contact No.: 65476433

Authentication Stamp

**NP168** 

Date/Time:
20/03/2019 12:43

Classification Of Case:
SINGAPORE
POLICE FORCE



### RECORDS MANAGEMENT CENTRE

# GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Phone +65 6224 0010 Fax +65 6224 0030 Operating Hours, Monday to Friday 9am to 5pm GST Registration No: M400017735

### TAX INVOICE

Our Ref No:

GR-19-047086

Date of Request:

26/03/2019

Your Ref No:

WALK IN GOH

SIONG HAI MOTOR & TRADING

NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

Dear Sir/Madam,

Your Vehicle No:

SLG6953G

Date of Accident:

20/03/2019

Place of Accident:

CORPORATION RD

Flace of Accident.

Involving Vehicle No: GBC1851P

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[] GIRO [X] Cash [] Cheque



### GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Phone +65 6224 0010 Fax +65 6224 0030 Operating Hours, Monday to Friday Sam to Spn. GST Registration No: M400017735

### TAX INVOICE

Our Ref No:

GR-19-047087

Date of Request:

26/03/2019

Your Ref No:

WALK IN GOH

SIONG HAI MOTOR & TRADING NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

Dear Sir/Madam.

Date of Accident:

20/03/2019

Vehicle No:

SLG6953G

Place of Accident:

CORPORATION RD BEFORE JURONG PORT ROAD

Involving Vehicle No: GBC1851P

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GBC1851P	CORPORATION RD BEFORE JURONG PORT ROAD	14.00	1	13.08
GST Amount				0.92
Total Amount Du	le (GST Inclusive)			14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[] GIRO [X] Cash [] Cheque

### **SELECTION PRE-OWNED**

ROC 53308607L

### **INVOICE**

To:

**CHEN YUTONG** 

Address:

**BLK 317 JURONG EAST STREET 31** 

Invoice No: SPOIN 0001

#13-30 SINGAPORE (600317)

Invoice Date : <u>09-04-2020</u>

Vehicle Model:

**SEAT TOLEDO** 

Vehicle No:

**SLL4068Z** 

Rental Rate: SGD 120.00

S/N	Description	Duration / Days	Amount
1	Wednesday to Wednesday 20/03/19 to 10/04/19	21	SGD 2520.00
	Total No. of Days:	21	
		Total Amount:	SGD 2520.00

Remarks:

SLG6953G



### **EURO SUCCESS SERV PTE. LTD.**

No. 1 Kaki Bukit Avenue 6 #02-03 AutoBay, Singapore 417883

Tel: 9336 5311 Fax: 6741 1019

Name : AMV PTE LTD

Date : 09 APRIL 2020

Address : c/o No. 1 Kaki Bukit Avenue 6

Invoice No : SH/SLG6953G

#02-03 AutoBay @ Kaki Bukit

Singapore 417883

FINAL REPAIR BILL FOR MAZDA 3 NO. SLG6953G

Lump Sum Repair Cost

18,000.00

**SINGAPORE DOLLARS: EIGHTEEN THOUSAND ONLY** 

nature & Official Stamp



### PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel: 62934822 Fax: 62963283

Messrs.

AMV Pte Ltd

20, Sin Ming Lane #04-68, Midview City Singapore 573968 Bill No. DN/TP/19/0187/EURO

27/12/2019

				Dr.	<u> </u>
То					
	Survey Fee (S \$):				
	Photographs (S \$):				
	Transport (S \$):				
	Resurvey (S \$):				
	Site-Survey (S \$):				
	Services rendered in	clu	uding photographs and transport charges	(S \$)	1,337.00
	Our reference	:	TP/0046/03/19		
	Insured	**			
	Policy / Cert. No.	•			
	Your Claim No.	:	Third Party Claim		
	Vehicle:	:	Mazda 3 (A) - SLG 6953 G		
	Dollars:	:	One Thousand Three Hundred Thirty Seven Only		
	Checked by		for PRIORITY SERVICES		
ě	lix		E. & O. E	*	

Only our official receipt will be recognised for payment made on this account



### PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers Block 779 Yishun Avenue 2 #01-1545 Singapore 760779

Tel: 62934822 Fax: 62963283

### VEHICLE INSPECTION REPORT

Report No. TP/0046/03/19

To: AMV Pte Ltd

20, Sin Ming Lane #04-68, Midview City Singapore 573968

Date of Report

27 December 19

Date of Request

20 March 19

Report requested by

: AMV Pte Ltd

Date of Accident Date of Inspection : 20 March 19

Claim No.

: 20 March 19

: Third Party Claim

### PARTICULARS OF DAMAGED VEHICLE

Registration Plate No

\* SLG 6953 G

Odometer Reading

: 160,090 km

Make

: Mazda

Carrying Capacity

Model

: 3 (A)

Radio / Cassette / CD

: Yes

Year of Manufacture

: 2016

Air-Conditioner Wing Mirror

: Yes

Colour **Engine Capacity**  : Pearl White : 1,496 cc

Clock

: Yes

Engine No

Seat Belts

: Yes : Yes

Chassis / Frame No

: JM6BM42A8G0343672

Others

: Nil

### TYRE CONDITION

Front Left

⊕ 6mm

Front Right

. 6mm

Make

: Campeon

Make

: Campeon

Rear Left

: 6mm

Rear Right

: 6mm

Make

: Campeon

Make

: Campeon

Spare

Road Wheels Type

: Alloy

### (The above represents the approximate remaining life of tyre treads)

Jack & Tools

: Intact

Spare Tyre

: Intact

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work

Good

Paint Work

Good

Handbrake

Serviceable

Footbrake

Steering

Serviceable

Apparent engine modification

Serviceable

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

		Repairer's Estimate (S \$)	Our Recommendation (S \$)
Spare Parts	慧	40,514.17	27,672.97
Labour Charges	#	4,630.00	3,010.00
Paint Work	3. 0.	1,400.00	1,000.00
Towing Charges	4	100.00	50.00
Others	3	0.00	0.00
Totals	3	46,644.17	31,732.97

Reduction (S \$) :

28,644.17

Recommended Reserve (S \$) :

18,000.00

(Lump Sum)

Estimated Normal Period of Repairs :

15 working days

### **CONTRIBUTIONS BY INSURED**

Excess (S \$)

: N/A

Others

: ---

### The Assignment

The survey was conducted at Euro Success Services Pte Ltd, No 1, Kaki Bukit Avenue 6, #02-03, Autobay @ Kaki Bukit, Singapore 417883.

Follow-up inspection has been conducted.

### Point of Impact

At the front RH portion.

#### Damages

The bonnet, front bumper, front bumper reinforcement, front grille, front fenders, headlamps assembly, support panel, A/C condenser, radiator assembly, front undercarriage parts, altemeter assembly, inlet manifold, air-bag system, front chassis members, etc.

Other parts were also found damaged. (see schedule for details)

### Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$31,732.97

### Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$18,000.00

Pre-accident market value: About \$60,000.00

COE and PARF rebate : About \$41,208.40 (COE expiry on 10-10-2026)

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES

JIMMY S. T. LEE-AMSOE, AMIRTE, AMSAE-AUS, MSAAA

Motor Appraiser

LAWRENCE NG Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : SLG 6953 G Mazda 3 (A) Workshop : Euro Success Services Pte Ltd

To Supply :				_		
To Supply:	Replacement of Parts	Condition	Repairer's	Dist.%	Our	Dist.%
Dented			Estimate		Recommendation	
Dented			(S \$)		(S \$)	
Dented						
Inc. Front bonnet rubber - oiner	To Supply:					
Inc. Front bonnet rubber - oiner						
1pc. Front bonnet rubber - outer	1pc. Front bonnet 🗸	Dented	991.60	20	✓ 991.60	20
1pc. Front bonnet lock	1pc. Front bonnet rubber - inner ✓	Bent / Necessary	58.60	20	✓ 58.60	20
1pc. Front bonnet lock cable   SVC   Refit   89.90   20     20   2pcs. Front bonnet hinges L/R ✓   Bent   111.20   20   82   111.20   20   2pcs. Front bonnet stand   SVC   Bent / Repair   89.60   20     20   1pc. Front bonnet insulator   SVC   Not In Use   126.20   20     20   1pc. Front bonnet insulator   SVC   Not In Use   126.20   20     20   1pc. Front bumper volume   SVC   Not In Use   155.00   20     20   1pc. Front bumper volume   SVC   Not In Use   281.90   20     20   1pc. Front bumper fog lamp - RH SVC   Not In Use   281.90   20     20   1pc. Front bumper fog lamp cover RH ✓   Dented   110.20   20   25   110.20   20   1pc. Front bumper signal lamp RH ✓   Broken   Dislodged / Missing   288.90   20   ✓ 29   20   √ 186.90   20   √ 186.90   20   √ 186.90   20   ✓ 29   20   ✓ 29   20   √ 186.90   20   ✓ 29   20   20   ✓ 29   20   20   ✓ 29   20   20   20   20   20   20   20	1pc. Front bonnet rubber - outer ✓	Bent / Necessary	68.96	20	✓ 68.96	20
1pc. Front bonnet lock cable   SVC   Refit   89.90   20     20   2pcs. Front bonnet hinges L/R ✓   Bent   111.20   20   82   111.20   20   2pcs. Front bonnet stand   SVC   Bent / Repair   89.60   20     20   1pc. Front bonnet insulator   SVC   Not In Use   126.20   20     20   1pc. Front bonnet insulator   SVC   Not In Use   126.20   20     20   1pc. Front bumper volume   SVC   Not In Use   155.00   20     20   1pc. Front bumper volume   SVC   Not In Use   281.90   20     20   1pc. Front bumper fog lamp - RH SVC   Not In Use   281.90   20     20   1pc. Front bumper fog lamp cover RH ✓   Dented   110.20   20   25   110.20   20   1pc. Front bumper signal lamp RH ✓   Broken   Dislodged / Missing   288.90   20   ✓ 29   20   √ 186.90   20   √ 186.90   20   √ 186.90   20   ✓ 29   20   ✓ 29   20   √ 186.90   20   ✓ 29   20   20   ✓ 29   20   20   ✓ 29   20   20   20   20   20   20   20	1pc. Front bonnet lock ✓		186.90	20	✓ 186.90	
2   2   2   2   2   2   3   2   3   3	1pc. Front bonnet lock cable SVC	Refit	89.90	20		
Ipc. Front bonnet stand   SVC   Bent / Repair   89.60   20					82 111.20	
Ipc. Front bonnet insulator SVC   Not In Use   126.20   20     20						
10pcs. Front bumper   ✓   Dented   1,339.50   20   92.51   1,339.50   20     1pc. Front bumper   ✓   Dented   1,339.50   20   92.51   1,339.50   20     1pc. Front bumper fog lamp - RH SVC   Not In Use   281.90   20   25   110.20   20     1pc. Front bumper fog lamp cover RH						
1pc. Front bumper     Dented   1,339.50   20   925.1 1,339.50   20   1pc. Front bumper fog lamp - RH SVC   Not In Use   281.90   20     26   26   1pc. Front bumper fog lamp cover RH   Dented   110.20   20   25   110.20   20   20   1pc. Front bumper signal lamp RH   Broken   155.60   20   141   155.60   20   1pc. Front bumper signal lamp RH   Broken   155.60   20   141   155.60   20   1pc. Front bumper lower grille SVC   Refit   86.20   20     20   20   2pc. Front bumper chrome mouldings   RH Cracked / LH Refit   373.80   20   ✓ 186.90   20   2pc. Front bumper top pad garnish   SVC   Not Necessary   131.60   20     20   20   2pc. Front bumper top beam SVC   Not In Use   145.00   20     20   2pc. Front bumper reinforcement   Dented   523.70   20   478.8   523.70   20   2pc. Front bumper reinforcement   SVC   Not In Use   161.20   20     20   2pc. Front bumper reinforcement   More   SVC   Not In Use   161.20   20     20   2pc. Front bumper reinforcement   SVC   Not In Use   117.00   20     20   2pc. Front bumper reinforcement   More   SVC   Not In Use   117.00   20     20   2pc. Front bumper reinforcement   SVC   Not In Use   117.00   20     20   2pc. Front bumper reinforcement   More   SVC   Not In Use   117.00   20     20   2pc. Front bumper reinforcement   SVC   Not In Use   117.00   20     20   2pc. Front fender there in SVC   RH Dented / LH Refit   259.00   20   333.9   381.90   20   2pc. Front fender shields L/R   RH Dented / LH Refit   259.00   20   √   30.00   20   2pc. Front fender inner shields L/R   RH Dented / LH Refit   259.00   20   √   129.50   20   20   20   20   20   20   20						
1pc. Front bumper fog lamp - RH SVC   Not In Use   281.90   20					025 1 1 339 50	
1pc. Front bumper signal lamp RH					920.1 1,557,50	
Ipc. Front bumper signal lamp RH	The Front bumper log lamp - left 500	Trot in esc	201.50	20		20
1pc. Front bumper top pad garnish	1pc. Front bumper fog lamp cover RH ✓	Dented	110.20	20	25 110.20	20
1pc. Front bumper top pad garnish	1pc. Front bumper signal lamp RH	Broken	155.60	20	141 155.60	20
1pc. Front bumper lower grille SVC   Refit   86.20   20     20		Broken / Dislodged / Missing				
2pes. Front bumper chrome mouldings   RH Cracked / LH Refit   373.80   20						
L/R						
1pc. Front bumper top beam SVC   Not In Use   145.00   20     20     1pc. Front bumper reinforcement	L/R ✓	RH Cracked / LH Refit	373.80	20	✓ 186.90	20
1pc. Front bumper reinforcement	1pc. Front bumper top frame pad SVC	Not Necessary	131.60	20		20
1pc. Front bumper reinforcement pad   SVC   Not In Use   161.20   20     20	1pc. Front bumper top beam SVC	Not In Use	145.00	20	-	20
2pcs. Front bumper brackets         SVC         Not In Use         117.00         20          20           2pcs. Front bumper side retainers L/R         Broken / Necessary         77.20         20         57.4         77.20         20           1set. Front bumper clips         Necessary         45.00         20         √ 30.00         20           2pcs. Front fender L/R         RH Dented / LH Repair         763.80         20         333.9         381.90         20           2pcs. Front fender inner shields L/R         RH Dented / LH Refit         259.00         20         ✓ 129.50         20           30pc. Front fender inner shield clips         SVC         Not Necessary         135.00         20          20           1pc. Front fender inner shield clips         SVC         Refit         86.90         20          20           1pc. Front fender wheel housing RH SVC         Dented / Repair         581.90         20          20           1pc. Front fender inner panel RH         SVC         Dented / Repair         488.60         20          20           1pc. Front grille logo         Cracked         481.60         20         33.7         481.60         20           1pc. Front grille	1pc. Front bumper reinforcement 🗸	Dented	523.70	20	478.8 523.70	20
2pcs. Front bumper side retainers L/R ✓         Broken / Necessary         77.20         20         57.4         77.20         20           1set. Front bumper clips ✓         Necessary         45.00         20         ✓ 30.00         20           2pcs. Front fenders L/R ✓         RH Dented / LH Repair         763.80         20         333.9         381.90         20           2pcs. Front fender inner shields L/R ✓         RH Dented / LH Refit         259.00         20         ✓ 129.50         20           30pcs. Front fender inner shield clips svc         Not Necessary         135.00         20          20           1pc. Front fender extay RH svc         Refit         86.90         20          20           1pc. Front fender wheel housing RH SVC         Dented / Repair         581.90         20          20           1pc. Front fender inner panel RH SVC         Dented / Repair         488.60         20          20           1pc. Front grille logo         Cracked         481.60         20         233.7         481.60         20           1pc. Front grille logo         Not Necessary         58.60         20         ✓ 58.60         20           1pc. Front grille top garnish svc         Not Necessary         181.9	1pc. Front bumper reinforcement pad	SVC Not In Use	161.20	20		20
Necessary   45.00   20	2pcs. Front bumper brackets SVC	Not In Use	117.00	20	(404);	20
2pcs. Front fenders L/R ✓         RH Dented / LH Repair         763.80         20         333.9 381.90         20           2pcs. Front fender inner shields L/R ✓         RH Dented / LH Refit         259.00         20         ✓ 129.50         20           30pcs. Front fender inner shield clips svc         Not Necessary         135.00         20          20           1pc. Front fender stay RH svc         Refit         86.90         20          20           1pc. Front fender wheel housing RH svc         Dented / Repair         581.90         20          20           1pc. Front fender inner panel RH svc         Dented / Repair         488.60         20          20           1pc. Front grille √         Cracked         481.60         20         233.7         481.60         20           1pc. Front grille logo √         Necessary         58.60         20         √         58.60         20           1pc. Front grille top garnish svc         Not Necessary         181.90         20          20           2pcs. Front headlamps L/R √         RH Broken / LH Holder Cracked         3,778.00         20         1746.6 3,778.00         20           1pc. Front sheadlamp top brackets √         Bent         125.00         <	2pcs. Front bumper side retainers L/R 🗸	Broken / Necessary	77.20	20	57.4 77.20	20
2pcs. Front fenders L/R ✓         RH Dented / LH Repair         763.80         20         333.9 381.90         20           2pcs. Front fender inner shields L/R ✓         RH Dented / LH Refit         259.00         20         ✓ 129.50         20           30pcs. Front fender inner shield clips svc         Not Necessary         135.00         20          20           1pc. Front fender stay RH svc         Refit         86.90         20          20           1pc. Front fender wheel housing RH svc         Dented / Repair         581.90         20          20           1pc. Front fender inner panel RH svc         Dented / Repair         488.60         20          20           1pc. Front grille √         Cracked         481.60         20         233.7         481.60         20           1pc. Front grille logo √         Necessary         58.60         20         √         58.60         20           1pc. Front grille top garnish svc         Not Necessary         181.90         20          20           2pcs. Front headlamps L/R √         RH Broken / LH Holder Cracked         3,778.00         20         1746.6 3,778.00         20           1pc. Front sheadlamp top brackets √         Bent         125.00         <	1set. Front bumper clips \square	Necessary	45.00	20	✓ 30.00	20
2pcs. Front fender inner shields L/R ✓         RH Dented / LH Refit         259.00         20         ✓ 129.50         20           30pcs. Front fender inner shield clips svc         Not Necessary         135.00         20         —         20           1pc. Front fender stay RH svc         Refit         86.90         20         —         20           1pc. Front fender wheel housing RH svc         Dented / Repair         581.90         20         —         20           1pc. Front fender inner panel RH svc         Dented / Repair         488.60         20         —         20           1pc. Front grille √         Cracked         481.60         20         233.7         481.60         20           1pc. Front grille logo √         Necessary         58.60         20         ✓         58.60         20           1pc. Front grille top garnish svc         Not Necessary         181.90         20         —         20           2pcs. Front headlamps L/R √         RH Broken / LH Holder Cracked         3,778.00         20         1746.6 3,778.00         20           1pc. Front headlamp side garnish svc         Not In Use         48.60         20         —         20           2pcs. Front headlamp top brackets √         Bent         125.00         20					333.9 381.90	
30 pcs. Front fender inner shield clips   SVC   Not Necessary   135.00   20     20     1pc. Front fender stay RH   SVC   Refit   86.90   20     20     1pc. Front fender wheel housing RH   SVC   Dented / Repair   581.90   20     20     1pc. Front fender inner panel RH   SVC   Dented / Repair   488.60   20     20     1pc. Front grille   ✓   Cracked   481.60   20   233.7   481.60   20     1pc. Front grille logo   ✓   Necessary   58.60   20   ✓   58.60   20     1pc. Front grille top garnish   SVC   Not Necessary   181.90   20     20     2pcs. Front headlamps L/R   ✓   RH Broken / LH Holder Cracked   3,778.00   20   1746.6 3,778.00   20     1pc. Front headlamp side garnish   SVC   Not In Use   48.60   20     20     2pcs. Front headlamp top brackets   ✓   Bent   125.00   20   50.4   125.00   20     1pc. Front support top panel   ✓   Cracked   245.00   20   ✓   245.00   20     1pc. Front support shroud panel   ✓   Cracked   596.00   20   √   245.00   20     1pc. Front shock absorber RH   ✓   Bent   489.60   20   ✓   343.60   20     1pc. Front shock absorber top mounting   SVC   Refit   154.40   20     20     1pc. Front lower arm RH   ✓   Bent   480.60   20   ✓   343.60   20     1pc. Front knuckle arm RH   ✓   Bent   510.90   20   ✓   385.20   20     1pc. Front knuckle arm RH   ✓   Bent   510.90   20   ✓   385.20   20     1pc. Front knuckle arm RH   ✓   Bent   510.90   20   ✓   385.20   20     1pc. Front knuckle arm RH   ✓   Bent   510.90   20   ✓   385.20   20     1pc. Front knuckle arm RH   ✓   Bent   510.90   20   ✓   385.20   20     1pc. Front knuckle arm RH   ✓   Bent   510.90   20   ✓   385.20   20     1pc. Front knuckle arm RH   ✓   Bent   510.90   20   ✓   385.20   20     1pc. Front knuckle arm RH   ✓   Bent   510.90   20   ✓   385.20   20					/ 129.50	
Ipc. Front fender stay RH         SVC         Refit         86.90         20          20           1pc. Front fender wheel housing RH         SVC         Dented / Repair         581.90         20          20           1pc. Front fender inner panel RH         SVC         Dented / Repair         488.60         20          20           1pc. Front grille √         Cracked         481.60         20         233.7         481.60         20           1pc. Front grille logo √         Necessary         58.60         20         ✓ 58.60         20           1pc. Front grille top garnish SVC         Not Necessary         181.90         20          20           2pcs. Front headlamps L/R         ✓         RH Broken / LH Holder Cracked         3,778.00         20         1746.6 3,778.00         20           1pc. Front headlamp side garnish SVC         Not In Use         48.60         20          20           2pcs. Front headlamp top brackets √         Bent         125.00         20         50.4         125.00         20           1pc. Front support top panel √         Cracked         245.00         20         ✓ 245.00         20           1pc. Front shock absorber RH         Bent <td< td=""><td>·</td><td></td><td></td><td></td><td>V 125120</td><td></td></td<>	·				V 125120	
Ipc. Front fender wheel housing RH SVC         Dented / Repair         581.90         20          20           1pc. Front fender inner panel RH         SVC         Dented / Repair         488.60         20          20           1pc. Front grille √         Cracked         481.60         20         233.7         481.60         20           1pc. Front grille logo √         Necessary         58.60         20         √         58.60         20           1pc. Front grille top garnish SVC         Not Necessary         181.90         20          20           2pcs. Front headlamps L/R √         RH Broken / LH Holder Cracked         3,778.00         20         1746.6         3,778.00         20           1pc. Front headlamp side garnish SVC         Not In Use         48.60         20          20           2pcs. Front headlamp top brackets √         Bent         125.00         20         50.4         125.00         20           1pc. Front support top panel √         Cracked         245.00         20         √         245.00         20           1pc. Front shock absorber RH √         Bent         489.60         20         √         343.60         20           1pc. Front lower arm RH         Be						
1pc. Front fender inner panel RH         SVC         Dented / Repair         488.60         20          20           1pc. Front grille ✓         Cracked         481.60         20         233.7         481.60         20           1pc. Front grille logo ✓         Necessary         58.60         20         ✓ 58.60         20           1pc. Front grille top garnish         SVC         Not Necessary         181.90         20          20           2pcs. Front headlamps L/R         RH Broken / LH Holder Cracked         3,778.00         20         1746.6         3,778.00         20           1pc. Front headlamp side garnish         SVC         Not In Use         48.60         20          20           2pcs. Front headlamp top brackets         Bent         125.00         20         50.4         125.00         20           1pc. Front support top panel         Cracked         245.00         20         ✓ 245.00         20           1pc. Front shock absorber RH         Bent         489.60         20         ✓ 343.60         20           1pc. Front lower arm RH         Bent         480.60         20         421.5         480.60         20           1pc. Front knuckle arm RH         Bent         51						
1pc. Front grille ✓         Cracked         481.60         20         233.7         481.60         20           1pc. Front grille logo ✓         Necessary         58.60         20         ✓         58.60         20           1pc. Front grille top garnish SVC         Not Necessary         181.90         20         —         20           2pcs. Front headlamps L/R         ✓         RH Broken / LH Holder Cracked         3,778.00         20         1746.6 3,778.00         20           1pc. Front headlamp side garnish SVC         Not In Use         48.60         20         —         20           2pcs. Front headlamp top brackets ✓         Bent         125.00         20         50.4         125.00         20           1pc. Front support top panel ✓         Cracked         245.00         20         ✓         245.00         20           1pc. Front shock absorber RH         Bent         489.60         20         ✓         343.60         20           1pc. Front shock absorber top mounting         SVC         Refit         154.40         20         —         20           1pc. Front lower arm RH         Bent         480.60         20         421.5         480.60         20           1pc. Front knuckle arm RH         Bent <td></td> <td></td> <td></td> <td></td> <td></td> <td>-</td>						-
1pc. Front grille logo ✓         Necessary         58.60         20         ✓ 58.60         20           1pc. Front grille top garnish SVC         Not Necessary         181.90         20          20           2pcs. Front headlamps L/R ✓         RH Broken / LH Holder Cracked         3,778.00         20         1746.6 3,778.00         20           1pc. Front headlamp side garnish SVC         Not In Use         48.60         20          20           2pcs. Front headlamp top brackets ✓         Bent         125.00         20         50.4         125.00         20           1pc. Front support top panel ✓         Cracked         245.00         20         ✓         245.00         20           1pc. Front shock absorber RH ✓         Bent         489.60         20         ✓         343.60         20           1pc. Front shock absorber top mounting         SVC         Refit         154.40         20          20           1pc. Front lower arm RH         Bent         480.60         20         421.5         480.60         20           1pc. Front knuckle arm RH         Bent         510.90         20         385.20         20					222.7 481.60	-
1pc. Front grille top garnish       SVC       Not Necessary       181.90       20        20         2pcs. Front headlamps L/R       ✓       RH Broken / LH Holder Cracked       3,778.00       20       1746.6 3,778.00       20         1pc. Front headlamp side garnish       SVC       Not In Use       48.60       20        20         2pcs. Front headlamp top brackets       ✓       Bent       125.00       20       50.4       125.00       20         1pc. Front support top panel       ✓       Cracked       245.00       20       ✓       245.00       20         1pc. Front support shroud panel       ✓       Cracked       596.00       20       469.7       596.00       20         1pc. Front shock absorber RH       ✓       Bent       489.60       20       ✓       343.60       20         1pc. Front shock abosrber top mounting       SVC       Refit       154.40       20        20         1pc. Front lower arm RH       ✓       Bent       480.60       20       421.5       480.60       20         1pc. Front knuckle arm RH       ✓       Bent       510.90       20       ✓       385.20       20	1 0			-		
2pcs. Front headlamps L/R         ✓         RH Broken / LH Holder Cracked         3,778.00         20         1746.6 3,778.00         20           1pc. Front headlamp side garnish SVC         Not In Use         48.60         20         —         20           2pcs. Front headlamp top brackets         ✓         Bent         125.00         20         50.4 125.00         20           1pc. Front support top panel         ✓         Cracked         245.00         20         ✓         245.00         20           1pc. Front support shroud panel         ✓         Cracked         596.00         20         469.7 596.00         20           1pc. Front shock absorber RH         ✓         Bent         489.60         20         ✓         343.60         20           1pc. Front shock absorber top mounting         SVC         Refit         154.40         20         —         20           1pc. Front lower arm RH         ✓         Bent         480.60         20         421.5 480.60         20           1pc. Front knuckle arm RH         ✓         Bent         510.90         20         ✓         385.20         20					V 30.00	
1pc. Front headlamp side garnish SVC       Not In Use       48.60       20        20         2pcs. Front headlamp top brackets ✓       Bent       125.00       20       50.4       125.00       20         1pc. Front support top panel ✓       Cracked       245.00       20       ✓ 245.00       20         1pc. Front support shroud panel ✓       Cracked       596.00       20       469.7       596.00       20         1pc. Front shock absorber RH ✓       Bent       489.60       20       ✓ 343.60       20         1pc. Front shock abosrber top mounting       SVC       Refit       154.40       20        20         1pc. Front lower arm RH       ✓       Bent       480.60       20       421.5       480.60       20         1pc. Front knuckle arm RH       Ø       Bent       510.90       20       ✓ 385.20       20					1746 6 2 779 00	
2pcs. Front headlamp top brackets ✓       Bent       125.00       20       50.4       125.00       20         1pc. Front support top panel ✓       Cracked       245.00       20       ✓ 245.00       20         1pc. Front support shroud panel ✓       Cracked       596.00       20       469.7       596.00       20         1pc. Front shock absorber RH ✓       Bent       489.60       20       ✓ 343.60       20         1pc. Front shock abosrber top mounting       SVC       Refit       154.40       20       —       20         1pc. Front lower arm RH       ✓       Bent       480.60       20       421.5       480.60       20         1pc. Front knuckle arm RH       ✓       Bent       510.90       20       ✓ 385.20       20	· · · · · · · · · · · · · · · · · · ·			$\overline{}$	1/40.0 3,//8.00	
1pc. Front support top panel       ✓       Cracked       245.00       20       ✓       245.00       20         1pc. Front support shroud panel       ✓       Cracked       596.00       20       469.7       596.00       20         1pc. Front shock absorber RH       ✓       Bent       489.60       20       ✓       343.60       20         1pc. Front shock abosrber top mounting       SVC       Refit       154.40       20       —       20         1pc. Front lower arm RH       ✓       Bent       480.60       20       421.5       480.60       20         1pc. Front knuckle arm RH       ✓       Bent       510.90       20       ✓       385.20       20					50.4. 135.00	
1pc. Front support shroud panel       ✓       Cracked       596.00       20       469.7       596.00       20         1pc. Front shock absorber RH       ✓       Bent       489.60       20       ✓       343.60       20         1pc. Front shock abosrber top mounting       SVC       Refit       154.40       20       —       20         1pc. Front lower arm RH       ✓       Bent       480.60       20       421.5       480.60       20         1pc. Front knuckle arm RH       ✓       Bent       510.90       20       ✓       385.20       20						
1pc. Front shock absorber RH       ✓       Bent       489.60       20       ✓       343.60       20         1pc. Front shock abosrber top mounting       SVC       Refit       154.40       20       —       20         1pc. Front lower arm RH       ✓       Bent       480.60       20       421.5       480.60       20         1pc. Front knuckle arm RH       ✓       Bent       510.90       20       ✓       385.20       20						
1pc. Front shock abosrber top mounting       SVC       Refit       154.40       20       —       20         1pc. Front lower arm RH       ✓       Bent       480.60       20       421.5       480.60       20         1pc. Front knuckle arm RH       ✓       Bent       510.90       20       ✓       385.20       20						
1pc. Front lower arm RH       ✓       Bent       480.60       20       421.5       480.60       20         1pc. Front knuckle arm RH       ✓       Bent       510.90       20       ✓       385.20       20	1pc. Front snock absorber RH 🗸	Bent	489.60	20	✓ 343.60	20
1pc. Front knuckle arm RH ✓ Bent 510.90 20 ✓ 385.20 20	1pc. Front shock abosrber top mounting	SVC Refit	154.40	20	<del></del>	20
		Bent	480.60	20	421.5 480.60	20
1pc. Front wheel bearing RH ✓ Warped 182.60 20 ✓ 182.60 20	1pc. Front knuckle arm RH 🗸	Bent	510.90	20	✓ 385.20	
	1pc. Front wheel bearing RH ✓	Warped	182.60	20	<b>√</b> 182.60	20

Vehicle No: SLG 6953 G Mazda 3 (A) Workshop: Euro Success Services Pte Ltd

Replacement of Parts	Condition	Repairer's	Dist.%	Our	Dist.%
replacement of Latts	Condition	Estimate	15151. 70	Recommendation	D18t. 70
		(S \$)		(S \$)	
		(5 4)		(5 \$)	
1pc. Front sport wheel RH ✓	Dented / Cut	1,054.60	20	350(SN) 1,054.60	20
1pc. Front drive shaft RH SVC	Refit	1,361.80	20		20
1pc. A/C condenser ✓	Dented / Bent	1,063.00	20	<b>√</b> 1,063.00	20
1pc. A/C discharge pipe SVC	Refit	421.10	20		20
1pc. A/C suction pipe SVC	Refit	381.60	20		20
1pc. A/C liquid pipe ✓	Bent	241.60	20	✓ 241.60	20
1pc. A/C compressor SVC	Not Necessary	1,181.50	20		20
1pc. A/C compressor belt SVC	Refit	190.60	20		20
1pc. Air cleaner intake duct SVC	Refit	98.60	20	-	20
1pc. Air cleaner box SVC	Refit	281.60	20		20
1pc. Radiator $\checkmark$	Holder Broken	1,066.50	20	<b>√</b> 1,066.50	20
1set. Radiator top mounts SVC	Refit	37.20	20		20
1pc. Radiator top hose SVC	Refit	58.60	20	1	20
1pc. Radiator bottom hose SVC	Refit	61.50	20		20
1pc. Radiator auxiliary fan ✓	Cracked	1,356.00	20	√ 1,356.00	20
1pc. Radiator spare tank SVC	Refit	89.50	20		20
1pc. Power steering cooler pipe SVC	Refit	196.50	20		20
1pc. Altenator 🗸	Pulley Dented / Bent	1,381.80	20	√ 1,381.80	20
1pc. Engine mounting RH ✓	Broken	341.20	20	✓ 341.20	20
1pc. Engine mounting bracket SVC	Refit	210.50	20		20
1pc. Engine mounting LH ✓	Cracked	261.50	20	✓ 261.50	20
1pc. Engine mounting rear \( \square\$	Bent / Cracked	241.20	20	✓ 241.20	20
1pc. Engine undercover 🗸	Holder Cracked	131.20	20	✓ 131.20	20
1set. Engine wire haarness SVC	Refit	2,455.90	20		20
1pc. Inlet manifold 🗸	Dented / Cracked	1,350.50	20	<b>√</b> 1,002.20	20
1pc. Washer tank $\checkmark$	Cracked	186.90	20	109.2 186.90	20
1pc. Washer tank motor SVC	Refit	89.90	20		20
1pc. Wiper panel garnish ✓	Cracked / Cut	260.90	20	✓ 260.90	20
1pc. Front windscreen glass ✓	Cracked	1,101.80	20	<b>√</b> 1,101.80	20
1pc. Front windscreen moulding \( \square\$	Necessary	126.20	20	✓ 126.20	20
1pc. Steering wheel SVC	Refit	1,885.90	20		20
1pc. Steering wheel air-bag \square	Deployed	2,251.60	20	1082.5 2,251.60	20
2pcs. Safety belts L/R $\checkmark$	Jammed	1,782.20	20	√ 1,782.20	20
2pcs. Safety belt trims L/R ✓	Deformed	252.40	20	✓ 252.40	20
1pc. Passenger air-bag 🗸	Deployed	2,850.50	20	1169.6 2,850.50	20
1pc. Dashboard $\checkmark$	Cracked	1,391.80	20	1100 1,391.80	20
1pc. S.R.S control unit ✓	Activated / Necessary	1,053.00	20	<b>√</b> 1,053.00	20
	pair Dented / Bent	1,700.00	20	1,700.00	20
	Cracked / Malfunction	3,850.00	20	1731 2,050.00	20
Sub-Total :-		49,561.46		24976.46 34,464.96	
Total Discount :-		9,912.29		6,892.99	
		39,649.17		27,571.97	
				19981.16	
Special Nett Items :-					
1tube. Front windscreen sealant $\checkmark$	Necessary	80.00		✓ 40.00	
1pc. Front windscreen solar film SVC	Not In Use	280.00			

Vehicle No : SLG 6953 G Mazda 3 (A) Workshop : Euro Success Services Pte Ltd

Replacement of Parts	Condition	Repairer's	Dist.%	Our	Dist.%
		Estimate		Recommendation	
		(S \$)		(S \$)	
1pc. Front tyre RH SVC	Refit	350.00			
1pc. I.U. bracket ✓	Necessary	30.00		26.00	
1btl. A/C oil SVC	Charge In Labour	65.00			
1btl. Radiator coolant 🗸	Necessary	60.00		35.00	
Total For Parts :-		40,514.17		27,672.97	
				451	
Labour Charges :					
To check front electrical wiring.		150.00		20.00	
To remove, refix front windscreen.		180.00		120.00	<b>V</b>
To remove, refix A/C condenser & re-fill		180.00		100.00	,
A/C gas.		100.00		100.00	<b>✓</b>
To remove & re-install whole engine with		650.00		400.00	/
gearbox to assist repairs.		050.00		400.00	<b>V</b>
To remove, replace & refix front		350.00		300.00	<b>✓</b>
undercarriage parts.		330.00		200.00	•
To check & adjust wheel alignment		120.00		60.00	/
system.		120.00		00.00	
To re-spray undercoating.		150.00		60.00	<b>✓</b>
To remove, refix & replace front		400.00		300.00	200
dashboard & all attachments.		400.00		300.00	
To remove, refix, replace & reset S.R.S.		450.00		250.00	150
systems.		430.00		230.00	150
Panel beating, cut, weld, remove &		2,000.00		1,400.00	<b>/</b>
replacing above parts.		2,000.00		1,400.00	
		*			
Spray Painting:					
To re-spray painting & etc.		1,400.00		1,000.00	<b></b>
Towing Charges :					
Towing charges.		100.00		50.00	<b></b>
Grand Total :-		46,644.17		31,732.97	
		10,011017		3860	
				3000	

Surveyed By : Lawrence Ng

24292.16

-20%: 13k

MV 60k

rebate 47038

15 days