

DATE	:	24/2/2020
ACC DATE	:	20/02/2020
POLICY NO	:	DMCG19001459

SHEET NO. 1 OF 2 SHEET

RE: VEHICLE NO.:XE4599Y MITSUBISHI/FUSO/ CHENG HENG LEE PTE LTD

45000
 $44\checkmark$
 xnn
 xnn
 $\left. \begin{matrix} x \\ nn \end{matrix} \right\} nnx$
 $\left. \begin{matrix} x \\ nn \end{matrix} \right\} x$
 6675
 xnn
 6134
 xnn
 $\left. \begin{matrix} x \\ nn \end{matrix} \right\} x$
 $9005N 73231.10$
 $25\% 54,123.32$
 $SN 900$

S/N	QTY	DESCRIPTION	UNIT PRICE	AMOUNT \$
1	X1	SPECIAL NET		
2	X1	BRAKE OIL	\$	25.00
3	X1	AUTO OIL	\$	30.00
4	X1	COOLANT	\$	30.00
5	X1	FRONT TYRE RHS	\$	800.00
6	X1	FRONT RIM RHS	\$	800.00
				<u>1485.00</u>



Vfx Auto Pte Ltd
24 Chio Ping Road
Singapore 619977
Email: contact@vfxauto.com.sg
Tel: 64552967 Fax: 68628669
UEN / GST REG No.: 201830761R

ESTIMATE

DATE : 24/2/2020
ACC DATE : 20/02/2020
POLICY NO : DMC618001459

Attention: Motor Claim Department

SHEET NO. 2 OF 2 SHEET

RE: VEHICLE NO: XE46899Y MITSUBISHI / FUSO / CHENG HENG LEE PTE LTD

S/NO	QTY	LABOUR & MISCELLANEOUS	AMOUNT \$
1		To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten affected area, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	2,600.00
2		To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	3,200.00
3		Remove & Refit Front Cabin	1,800.00
4		Check & reconnect Wire Harness system & diagnosis fault code	3,200.00
5		Remove & Replace Radiator and Intercooler	400.00
6		Rejack & Alignment Chassis Frame Member	1,200.00
			<u>12,300.00</u>
GRAND TOTAL			\$ 141,242.33

2400

2000

900

1200

xnn

600

7100

54923.32

900

7100

62,923.32

415\$50,300 #

25 days



Photo 1 RH FRT VIEW



Photo 2 LH FRT VIEW



Photo 3 RH RR VIEW



Photo 4 LH RR VIEW



Photo 5 FRONT END VIEW



Photo 6 CRUSHED RH SIDE OF CABIN



Photo 7 SHEARED RH PILLAR & FIREWALL



Photo 8 CRUSHED DOOR & DOOR COMPONENTS



Photo 9 DENTED RH BUMPER / BROKEN RH LAMPS




Photo 10 SNAPPED & BURST WIRE HARNESS & AIR PIPING




Photo 11 SNAPPED RH LOWER STEPS



Photo 12 SHEARED FIRE WALL & DEFORMED DASHBOARD



Photo 13 SNAPPED WIPER LINKAGE



Photo 14 BROKEN DASHBOARD & COVERINGS




Photo 15 DEFORMED STEERING COLUMN



Photo 16 DISTORTED DRIVER'S SEAT



Photo 17 CHASSIS PLATE



Photo 18 REMOVED CABIN 1



Photo 19 SHEARED CABIN



Photo 20 CABIN REMOVED



Photo 21 SNAPPED WIRE HARNESS & BENT LOWER STEPS



Photo 22 BROKEN AIR FILTER HOUSING




Photo 23 INTACT RADIATOR FAN BLADE



Photo 24 INTACT RADIATOR



Photo 25 INTACT ENGINE MOUNTING



Photo 26 AFTER PAINT 1



Photo 27 AFTER PAINT 2



Photo 28 AFTER PAINT 3